

05/27/2021

U.S. Nuclear Regulatory Commission - Region III Materials Licensing Section 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352

RE: NRC Radioactive Materials License 21-24828-01MD RLS (USA), Inc., 1200 Hubbard Road, Livonia, MI 48150

Dear NRC Representative.

Please allow this letter to serve as notice that RLS (USA), Inc. wishes to report a package that was delivered by FedEx to the wrong address in compliance with 10 CFR 20.2201 (b):

The package that was delivered by FedEx contained a 250 mCi vial of HiCon (I-131) dated for 05/23/2021. At the time of initial reporting on 05/21/2021, the activity contained in the vial was estimated to be approximately 297 mCi.

On 05/21/2021 at 09:34 ET, FedEx delivered the package to Valassis Anderson Printing Plant located at 35944 Schoolcraft Road, Livonia, MI 48150. The package was intended for delivery at 12300 Hubbard Road, Livonia, MI 48150. At approximately 13:30 ET, the pharmacy was alerted of the delivery to the wrong address by an employee of Valassis Anderson Printing. RLS (USA) Inc. Immediately retrieved the package. The package was checked-in at approximately 14:00 ET. A visual inspection was conducted which revealed that the package was intact and there wasn't any evidence of leaking. Package surveys we conducted which resulted in a surface reading of 17 mR/hr and a TI of 0.5. A wipe was also taken of which did not reveal any removeable contamination.

A conservative dose assessment was performed using the package survey results. The dose was estimated utilizing the estimated time the package was in control of the identified member of public, ~ 4.5 hours, and found to be approximately 76.5 mrem if an member of public was in constant contact with the package and approximately 2.25 mrem if the member of public maintained a minimum distance of one meter from the package.

An email was sent om 5/27/2021 to <u>DGHOTLINE@FEDEX.com</u> to notify them of the event so that they may internally address this issue to prevent reoccurrence.

Should you have any additional questions or require additional information, please feel free to contact Bradley Ambs at (734) 425-0425 or myself at (607) 205.2237.

Sincerely,

Jaime Lynn Herner Jaime Lynn Herner

Corporate Radiation Safety Officer & Regulatory Affairs Manager

RLS (USA) Inc.

Enclosed. Attachment A – FedEx Delivery Time Screenshot


Attachment B – Packaging Slip

Attachment C – Package Check-in Form CC: Bradley Ambs, RLS Livonia RSO
Attachment D – FedEx tracking number Jill Twehues, Business Unit Manger

RLS (USA) Inc. 483 Mix Rd Chenango Forks, NY 13746 T: +1-607-205-2237 E: Jaime.Herner@rls.bio




# Attachment A






#### Attachment B





### Attachment C





# Attachment D





# Song, Taehoon

From: RidsRgn3MailCenter Resource
Sent: Thursday, May 27, 2021 2:30 PM

**To:** Song, Taehoon **Cc:** Pavon, Sandy

Subject: FW: RLS (USA) Inc. Event 55269 5/21/2021 Misdelivery of I-131

**Attachments:** 2021-5-21 DET I-131 Misdelivery of I-131.pdf

# Good afternoon,

This message was received in the RIDS mailbox. I thought it best to forward to you.

From: Jaime Herner <jaime.herner@rls.bio> Sent: Thursday, May 27, 2021 2:00 PM

To: RidsRgn3MailCenter Resource < RidsRgn3MailCenter.Resource@nrc.gov>

Cc: Warren, Geoffrey <Geoffrey.Warren@nrc.gov>; Jill Twehues <jill.twehues@rls.bio>; Bradley Ambs

<bradley.ambs@rls.bio>

Subject: [External\_Sender] RLS (USA) Inc. Event 55269 5/21/2021 Misdelivery of I-131

### To whom it may concern,

Please find in the attachments the required 30 day written report for event 55269. Please let me know if there is any additional information which is needed to satisfy our reporting requirements.

Best Regards,

Jaime Lynn Herner

Corporate Radiation Safety Officer & Regulatory Affairs Manager



RLS (USA) Inc. M: 607.205.2237 483 Mix Rd. Chenango Forks, NY 13746