

**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

1. LICENSEE/LOCATION INSPECTED:  Summit Medical Associates, LLC 4656 W Jefferson Blvd Ste. 125 Fort Wayne, IN 46804  REPORT NUMBER(S) 2021001	2. NRC/REGIONAL OFFICE  Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352
--	---

3. DOCKET NUMBER(S)  030-38056	4. LICENSE NUMBER(S)  13-32752-01	5. DATE(S) OF INSPECTION  June 25, 2021
--------------------------------------	---	---

**LICENSEE:**

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

\_\_\_\_\_ Non-cited violation(s) were discussed involving the following requirement(s):

- 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.  
(Violations and Corrective Actions)

**Statement of Corrective Actions**

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Jason D. Draper, Health Physicist	Jason D. Draper	Digitally signed by Jason D. Draper Date: 2021.07.09 07:11:32 -05'00'
BRANCH CHIEF	Michael A. Kunowski	Michael A. Kunowski	Digitally signed by Michael A. Kunowski Date: 2021.07.12 12:06:21 -05'00'



### Materials Inspection Record

1. Licensee Name: Summit Medical Associates, LLC		2. Docket Number(s): 030-38056		3. License Number(s) 13-32752-01	
4. Report Number(s): 2021001			5. Date(s) of Inspection: June 25, 2021		
6. Inspector(s): Jason Draper		7. Program Code(s): 02201	8. Priority: 5	9. Inspection Guidance Used: IP 87130	
10. Licensee Contact Name(s): Lori Bryant, CMNT		11. Licensee E-mail Address: lorib1050@gmail.com		12. Licensee Telephone Number(s): 260-434-1177	
13. Inspection Type:		14. Locations Inspected:		15. Next Inspection Date (MM/DD/YYYY):	
<input type="checkbox"/> Initial <input checked="" type="checkbox"/> Routine <input checked="" type="checkbox"/> Announced <input type="checkbox"/> Non-Routine <input type="checkbox"/> Unannounced		<input checked="" type="checkbox"/> Main Office <input type="checkbox"/> Field Office <input type="checkbox"/> Temporary Job Site <input type="checkbox"/> Remote		06/25/2026 <input checked="" type="checkbox"/> Normal <input type="checkbox"/> Extended <input type="checkbox"/> Reduced <input type="checkbox"/> No change	

16. Scope and Observations:

This was a routine, announced inspection of a cardiology clinic in Fort Wayne, Indiana, authorized under its NRC license to use byproduct materials for medical uses permitted by 10 CR 35.200. The nuclear medicine department operated on Fridays only, and was staffed with one part-time nuclear medicine technologist (NMT) who performed administrations on approximately three to five patients per week. Doses were primarily technetium-99m for cardiac stress tests. The licensee received unit doses from a licensed radiopharmacy. All waste was either held for decay-in-storage or returned to the nuclear pharmacy.

Due to the Covid-19 public health emergency, the inspector contacted the licensee prior to the inspection to ensure an on-site inspection could be performed safely. During the inspection the inspector observed the NMT prepare and administer two Tc-99m dosages. The inspector also observed the NMT perform package receipt surveys and demonstrate dose calibrator constancy checks, daily and weekly surveys, and handling of radioactive waste and disposal procedures. The inspector reviewed records for dose calibrator linearity, accuracy, and geometry tests, quarterly radiation safety program audits, and personnel dosimetry. The inspector also performed independent radiation measurements of the licensee's facility and found readings consistent with the licensee's survey results.

No violations of NRC requirements were identified as a result of this inspection.