



Materials Inspection Record

1. Licensee Name: Williams Gun Sight Company		2. Docket Number(s): 030-39129		3. License Number(s) 21-35400-02E	
4. Report Number(s): 2021001			5. Date(s) of Inspection: August 5, 2021		
6. Inspector(s): Jason Draper		7. Program Code(s): 03254	8. Priority: 5	9. Inspection Guidance Used: IP 87128	
10. Licensee Contact Name(s): Gabe Thompson, RSO		11. Licensee E-mail Address: gabe@williamsgunsight.com		12. Licensee Telephone Number(s): 810-653-2131, ext. 265	
13. Inspection Type:		14. Locations Inspected:		15. Next Inspection Date (MM/DD/YYYY):	
<input checked="" type="checkbox"/> Initial <input type="checkbox"/> Routine <input checked="" type="checkbox"/> Announced <input type="checkbox"/> Non-Routine <input type="checkbox"/> Unannounced		<input checked="" type="checkbox"/> Main Office <input type="checkbox"/> Field Office <input type="checkbox"/> Temporary Job Site <input type="checkbox"/> Remote		08/05/2026 <input checked="" type="checkbox"/> Normal <input type="checkbox"/> Extended <input type="checkbox"/> Reduced <input type="checkbox"/> No change	

16. Scope and Observations:

This was an announced initial inspection of a gun sight manufacturer licensed to distribute self-luminous gun sights containing tritium (H-3) sealed sources to persons exempt from the requirement for a license. The licensee was also licensed to possess and manufacture these gun sights by NRC License No. 21-35400-01 (Docket 030-39020). The licensee's activities under their possession and manufacturing license were previously inspected (initial) on January 16, 2018. The initial inspection for the exempt distribution license was originally attempted on July 23, 2019; however the licensee had not started principal activities at the time of that inspection. The licensee began principal activities on March 4, 2021, when they started distributing products. At the time of the inspection, the licensee had distributed 9 sets of gun sights that included Series 1111- Variation 1 and Series 2112 - Variation 1 models containing nominally 17.8 mCi and 35.6 mCi of H-3, respectively. The licensee had four individuals trained in the handling of radioactive materials.

The inspector toured the licensee's facility to observe the storage and security of the gun sights the licensee had not yet distributed. The inspector also observed a set of gun sights that were ready for distribution to verify the products and their packaging were appropriately labeled. The inspector also interviewed licensee staff and reviewed the licensee's quality assurance and quality control records as well as records associated with the distribution of the products to verify the licensee distributed products they were authorized to distribute. The inspector also verified that the licensee had timely and accurately filed annual reports for prior years. The inspector also discussed with the licensee their plan regarding selling the products in the licensee's retail store at the same address.

No violations of NRC requirements were identified as a result of this inspection.