

Document Title	Accession Number	Document Date
License SMB-0743 for Shieldalloy Corp,authorizing use of 17,700 lb Brazilian pyrochlore containing not more than 0.07% U & 2.05 thorium for production of ferro columbium & columbium nickel.	9002050242	12/26/1963
Forwards documents related to preparation of environmental assessment (EA) in response to Sheildalloy Metallurgical Corp application to renew matl license.	9212300183	12/18/1992
"Instrumentation & Surveillance."	9501040012	3/11/1994
Requests fee for 850619 application for amend to License SMB-743.	8508020287	7/9/1985
Ack receipt of 770224 & 0311 responses to NRC 761119 ltr. Info supplied re licensee radiation safety program & results of dust surveys to be taken when operations involving radioactive matls resumed,will be reviewed during next insp.	9002060032	3/16/1977
"Radiological Impacts from Use of CANAL - Slag Fluidizer in Steel Production."	9505120116	4/13/1995
"Radiological Areas & Posting."	9501040009	3/10/1994
Forwards copy of Shieldalloy Metallurgical Corp current license & four supporting documents referenced in license as requested by J Bergstein.W/o encl.	9404040187	3/30/1994
Discusses insp of License SMB-743 on 850402 & forwards notice of violation.Corrective actions described in 801030 ltr not effective.Response should address recurrent violations & provide addl info re waste storage & disposal.	8507030282	6/21/1985
FOIA request,for dockets 4007102,4007397 & 4008948,for documents re Foote Mineral/Shieldalloy/Cyprus Minerl Site in Cambridge,OH.	9508280128	3/7/1995
Discusses insp of License SMB-0743.Noncompliance noted. Requests reply within 20 days of ltr date.	9002050345	6/30/1965
Discusses class action lawsuit filed by four families against Cyprus Foote Mineral,Cyprus Amax Minerals,Newmont Mining & Cabot Corp.	9509220004	3/7/1995
Comments on Mar 1994 draft summary rept for EIS scoping process for Shieldalloy Metallurgical Corp in Cambridge,OH.	9404290266	4/19/1994
Forwards addendum to 870422 response to NRC 861211 ltr & topographic map & aerial photograph.W/o encls.	8705130146	4/29/1987
Advises that Sheildalloy Metallurgical Corp (SMC) should not move any Ferrovanadium Slag off-site.NJ seeking to resolve certain regulatory issues re matl,including jurisdictional issues,w/NRC.	9201080174	12/20/1991
Discusses Insp Rept 40-7102/76-01 on 761006 & forwards notice of violation.	9002050430	10/15/1976

Forwards "Project Status & Schedules Environ Programs."	9507070448	6/26/1995
Requests extension until 851201 for filing environ info outline due to recent consolidation of environ affairs & author appointment as environ manager.	8511130035	10/8/1985
Safety evaluation supporting Amend 8 to License SMB-743.	9204070083	3/25/1992
Ack receipt of 650706 ltr informing NRC of steps taken to correct noncompliance noted in 650630 ltr & Form AEC-592.	9002050381	7/13/1965
Comment expressing concern re radioactive dump at Shieldalloy Corp in Newfield,NJ.Advises either moving or capping dump.	9401260104	1/5/1994
Notice of violation from insp on 980727-28.Violation noted: as of 980713,licensee parent company,Metallurg,Inc,was acquired by group of institutional investors & Commission had not been notified of acquisition.	9902100078	1/21/1999
Submits specific info needed before final action can be taken on request for renewal of license SMB-743.	9506210144	6/15/1995
Transmits preliminary analytical results of soil samples collected by EPA from Newfield Landfill during June 1997 in attempt to clarify whether landfill had been impacted by contaminate migration from site.	9710270122	10/17/1997
Application for amend to license SMB-0743, revising condition 12 to reflect administrative changes in Radiation Protection Program.	9408120180	8/3/1994
Requests permission to post at plant gates signs reading "Any containers within plant may contain radioactive matl" & bearing radiation symbol,per 10CFR20.203a.	9002070047	12/13/1965
Application for amend to license SMB-743,removing provision 13 re monitoring of occupational intake of radioactive matl.	9804080257	3/25/1998
Discusses comments on substance of agreement re Shieldalloy EIS.	9508290230	11/17/1994
Application for amend to License SMB-743,authorizing rev of possession limits.Fee paid.	9005290253	5/22/1990
Application for renewal of License SMB-743,authorizing use of natural U & thorium for production of ferroalloys.	8508020282	6/19/1985
App 1,A-1,2-4,J-M & Figures & Tables to "Final Rept, Remedial Investigation."	9402240026	1/31/1994
Submits addl info requested by NRC 800523 ltr re application to renew matl/byproduct license.Describes storage of ferrocolumbian slag.State of NJ concerns re licensee methods of slag storage rectified.	8006170624	5/27/1980

Informs that revised license amend request,w/two listed exceptions,will be submitted under separate cover,in response to NRC 980219 ltr.	9804080097	3/25/1998
Application for amend to license SMB-743,allowing handling & sales of imported matl found to be source.	9103270157	3/19/1991
"Training & Qualifications of Radiation Protection Personnel."	9501040018	3/11/1994
FINAL GRADING PLAN SHIELDALLOY METALLURGICAL CORP CAMBRIDGE, OH.	9109260164	2/28/1991
Revised draft final rept, "Human Health Risk Assessment."	9411230169	4/30/1994
Comment supporting proposed rule re carting off site 1.2 million cubic yards of radioactive waste at Shieldalloy plant in State of NJ.	9401250003	1/12/1994
Ground water monitoring rept for period of Jul 1994.	9409150004	7/31/1994
Presents NRC understanding of respective roles & responsibilities of NRC & EPA re decommissioning of Shieldalloy Metallurgical Corps Cambridge,OH site.	9208100030	7/27/1992
Comment supporting proposed notice of intent to prepare EIS & to conduct scoping process.	9401250002	1/19/1994
Requests (including docket 7000100) that companies disregard NRC ltr dtd 990114,requesting future plans as to any new licensing actions through Sept 30,2002.Ltr was intended for fuel cycle licensees.	9901290072	1/27/1999
Forwards data that will be useful in preparing Environ Assessment document in response to application for renewal of source matl license for Newfield,NJ facility.	9211250195	11/23/1992
Responds to NRC 780103 ltr re violations noted in Insp Rept 40-7102/77-01.Provides discussion & analysis of licensee position re thorium concentration evaluation to show full compliance w/10CFR20.201(b) & 10CFR20.106.	9002060133	1/10/1978
Advises that YH Faraz has been assigned new NRC project manager of Licenses SMB-743 & SMB-1507.	9012130264	12/11/1990
Advises that request for extension for filing environ rept until 851201 granted.Schedule for completion of environ assessment will be prepared upon receipt of rept.	8511050284	10/31/1985
Application for amend to renewal of License SMB-734, submitting radiation protection procedures,RSP-001 "Radiation Protection Program" & RSP-003 "Control of Radiation Safety Procedures."	9509210192	9/15/1995
Confirms 940919 telcon concerning Shieldalloy site in Cambridge,Ohio,discussion indicated that Cyprus Foote Mineral Co was committed to completing task outlined in 940624 ltr to NRC.	9509150099	9/20/1994

Discusses ltr which would define info needs to prepare EIS & requests licensee to submit info on crisp schedule to avoid prolonged delays on EIS.	9508290219	3/16/1994
Urges Shieldalloy Corp to follow policy of transporting slag to federally approved facilities.	9403230038	1/11/1994
Requests info on radioactive properties of ferrovanadium slag to be shipped off site, within seven calendar days to determine source of radioactivity of slag. Advises that slag shall not be removed from site before determination made.	9112160095	11/21/1991
"Conceptual Decommissioning Plan for Newfield, NJ Facility."	9512210176	12/8/1995
"Groundwater Investigation."	9105280195	4/30/1987
Forwards "Work Plan for Radiological Characterization of Sheildalloy Metallurgical Corp Newfield Facility."	9103210378	3/14/1991
Advises that Div of Industrial & Medical Nuclear Safety planning to sponsor fuel cycle licensee workshop in mid-Sept in Washington, DC to bring together NRC officials & fuel cycle licensee to discuss NRC programs & policies.	9205050041	5/1/1992
Discusses facilitating communications w/NRC including revised procedures for submitting correspondence, per 980114 ltr.	9807170030	6/29/1998
Responds to 920806 request to terminate irrevocable ltr of credit from Deutsche Bank & substitute ltr of credit from Natl Westminster Bank. Recommends that draft form of ltr be modified, as stated.	9303260108	8/26/1992
Expresses desire to review work plan by Oak Ridge Associated Univs re radiological survey of licensee facility & to submit comments before start of field work.	9002060255	6/17/1987
"Final Focused Feasibility Study Rept, Ground Water Remediation."	9307080206	4/30/1993
Forwards corrected pages to Shieldalloy Metallurgical Corp application for renewal of License SMB-743, App C. Pages withheld.	8808020070	7/19/1988
Responds to NRC 990121 ltr re violations noted in insp rept 40-7102/98-01. Corrective actions: met with representatives of NRC Region I on 981001 & complete disclosure of sale of Metallurg stock made.	9902230325	2/19/1999
Forwards "EIS Scoping Process Summary Rept for Shieldalloy Metallurgical Corp Facility in Newfield, NJ" for review & comments by 940420. W/o encl.	9404130305	4/6/1994
Ack receipt of 970207 ltr to EDO re modifying license to SMC only to possess licensable matls for purpose of decommissioning.	9703180111	3/7/1997

Refers to 980811 & 21 ltrs describing criteria for free-release of soils from Newfield,New Jersey facility. Licensee should ensure that implemented procedures re free-release of soils meet criteria as described.	9809080351	8/26/1998
Notice of violation from insp on stated dates.Violation noted:licensee did not make or cause to be made surveys necessary for licensee to comply w/regulations in Part 30,as of 950306.	9512120023	11/30/1995
Undated comment supporting proposed rule re carting 1.2 million cubic yards of radwaste at plant off site.	9401240320	1/19/1994
Provides results of review of rept entitled, "Technical Basis,Work Plan & Health/Safety for Sale of East Pile Slag." NRC review results included in encl.SAIC results included in encl 2.	9810210270	10/13/1998
Comment supporting carting off site 1.2 million cubic yards of radwaste at Shieldalloy plant.	9401260193	1/19/1994
Requests need of addl info in ref to 960904 ltr asking NRC to review indirect bioassay procedure to determine if it is an acceptable & appropriate method to use to determine internal exposure levels.	9612200110	12/17/1996
Forwards Reg Guide 1.86, "Termination of Operating Licenses for Nuclear Reactors" & NMSS equivalent, "Guidelines for Decontamination of Facilities & Equipment Prior to Release for Unrestricted...", in response to 911107 telcon.W/o encl.	9111270087	11/20/1991
Summarizes status of studies conducted to date & will provide w/contacts so that P Hallett may follow up w/any addl questions.	9404260397	4/15/1994
Ack receipt of NRC 990422 ltr which requested changes to radiation protection program plan contained in licensee 990325 license amend application.Revised plan incorporating NRC changes,encl.	9906090143	6/1/1999
Requests documents of existing NRC permit,new permit & environ survey rept for Shieldalloy Corp.	8809080299	7/13/1988
Comment on proposed rule re cleaning up nuclear waste in Newfield,NJ.Requests relief from contamination.	9401240322	1/7/1994
Forwards proposed final order that will be presented to JL Garrity for signature in connection w/930921 hearing in respect of debtor in possessing financing agreement between Metallurg,Inc & Shieldalloy Metallurgical Corp.	9309200193	9/13/1993
Safety evaluation supporting amend 1 to license SMB-0743,to remove bldg D203A from listing of permanent restricted areas.	9907230304	7/20/1999

Notice of violation from insp on 850402. Violations noted: air surveys in blending area not performed since 800926 & air surveys in furnace area performed only four times in 1981, once per yr during 1982-84 & not at all in 1985.	8507030293	6/21/1985
Comment re NRC notice of intent to prepare environ impact statement for decommissioning of Shieldalloy Metallurgical Corp facilities.	9401260157	1/10/1994
URANIUM-238 CONCENTRATIONS IN SOIL SEDIMENT & WATER SAMPLES.	9204290379	3/4/1992
Discusses insp of License SMB-0743 on 771213 & forwards notice of violation.	9002060071	1/3/1978
Amend 5 to License SMB-0743 for Shieldalloy Corp, authorizing use of metaliferous ore containing 0.4% U & 2% thorium for ore processing.	9002050317	1/24/1973
Expresses concerns & requests clarification of 910319 ltr from Shieldalloy Metallurgical Co to NRC requesting exemption, mod or amend to license to allow handling & sale of 55,920 pounds ferrosilicon zirconium.	9106180280	6/7/1991
Responds to interest in potential offsite contamination found at Shieldalloy Metallurgical Corp site in Newfield, NJ. Understands that State of NJ Dept of Environ Protection received NRC insp rept dtd 980827.	9809230229	9/18/1998
Notice of intent to prepare EIS to conduct scoping process & conduct scoping meeting.	9312020286	11/19/1993
Amend 2 to License SMB-0743 for Shieldalloy Corp, authorizing use of unlimited quantities of metaliferous ore containing 2% U & 4% thorium.	9002050254	9/21/1965
Application for amend to License SMB-743, authorizing use of 17,637 lb pyrochlore concentrate containing 1.2-2.0% thorium & 0.03-0.07% U to produce ferro columbium & columbium nickel.	9002060376	11/24/1964
Requests approval to sale baghouse dust to facility not holding NRC license & not requiring facility to apply for one.	9607010119	6/24/1996
Notice of proposed order per bankruptcy code Sections 328(a) & 1103 authorizing retention of Kekst & Co NUNC PRO TUNC to 930902 as public relations consultants for debtors.	9309140105	9/3/1993
Undated memo informing that licensee submitted application for amend to license to correct items of noncompliance noted during insp on 650526. Forwards insp rept for info & requests to be informed if application denied.	9002070278	2/7/1990
Forwards drawings showing locations of environ TLDs used on site, as requested during NRC 940913 visit to licensee Newfield site.	9409270241	9/21/1994
Forwards partially deleted recorded annual whole body exposure rept for CY87 in compliance w/License SMB-743.	9002070443	5/12/1988

Acks 940213 ltr,informing of community activities re Shieldalloy Metallurgical Corp facility located in Newfield, New Jersey.Also,lists location & hours of operation of LPDRs.	9403140086	3/8/1994
Application for amend to license SMB-743, revising program description & requesting authorization to use source matl at Newfield facility & at other off-site, approved in advance by US NRC.	9712030266	11/26/1997
Refers to 990219 correspondence in response to 990121 ltr transmitting NOV, in which licensee denies. NRC finds that both violations valid & will not be changed.	9907230119	7/14/1999
Documents status of radiochemical groundwater sampling program & licensee basis & understanding for current suspension of analyses & reporting. Draft groundwater monitoring requirements for radionuclides encl.	9303250137	3/2/1993
Discusses IE Insp Rept 40-7102/80-01 on 800926 & forwards notice of violation.	8012190686	10/15/1980
Responds to NRC 650630 ltr re noncompliance noted in 650526 insp. Corrective actions taken: amend to License SMB-0743, covering licensing of Nigerian & Norwegian ores & baddeleyite requested & slag storage drums labeled.	9002050394	7/6/1965
Ack receipt of 780110 ltr informing NRC of corrective & preventive actions taken re violations noted in Insp Rept 40-7102/77-01.	9002060120	2/8/1978
Forwards requested environ info, per E Adensam 930505 ltr. Reply includes info from various govt agencies & licensee records & repts. W/two oversized drawings.	9307080183	6/29/1993
Forwards proposed plan for radiological survey at Shieldalloy per 860916 request. Comments or concurrence requested.	9002060247	7/30/1987
"Notice of Motion Pursuant to Section 1121(d) of Bankruptcy Code to Extend Debtors Exclusive Periods in Which to File Plan or Plans of Reorganization & Disclosure Statement & Solicit Acceptances Thereto."	9405020165	12/21/1993
Forwards insp rept 40-7102/94-01 on 940322 & 0421, re fact that slag which may have contained radioactive matl had been removed from Shieldalloy Metallurgical Corp site & used for construction & road fill. Slag not regulated by NRC.	9408290001	8/18/1994
Application for amend to License SMB-743, authorizing change in License Condition 12 as stated. Fee paid.	9002070251	10/30/1980
Forwards Amend 9 to License SMB-743, revising conditions 10 & 12 re radiation protection program & authorized users, respectively.	9307290259	7/21/1993
"Final Status Survey of A-Warehouse."	9902100262	1/18/1999

Requests to meet L Friedman re NRC data on licensee as soon as possible.	9002060313	10/24/1988
Forwards signed original FRN for renewal request for Shieldalloy Metallurgical Corp Facility in Newfield,NJ & opportunity for hearing.	9706270266	6/25/1997
Submits items of interest.On 871015,NRC met w/NUTECH Engineers,Inc & Duke Power Co to discuss submittal of revised NUTECH NUHOMS modular storage sys design topical rept.	8710260004	10/21/1987
Draft Rev 0 to Radiation Safety Procedure RSP-006, "Training & Qualification of Radiation Protection Personnel - Newfield Facility."	9512050090	9/19/1995
Ack receipt of 950412 ltr re Cyprus Foote Mineral Phase II Work Plan & fax on 950425 concerning slag characterization at Shieldalloy Metallurgical Corp facility in Cambridge,OH.	9505030032	4/26/1995
Opposes revision of relative priorities of EIS for Shieldalloy & Parks Township sites.Discusses major info gap on composition of West Pile at Cambridge site.	9508290276	12/13/1994
"Receipt,Handling & Identification of Radioactive Matls."	9501040007	3/10/1994
Forwards revised pages to 880718 application for renewal of License SMB-743.	8808170197	8/3/1988
Rev 0 to RSP-003, "Control of Radiation Safety Procedures (Newfield Facility)."	9509210198	9/15/1995
Requests copy of NRC release which announces formulation of plan to stabilize & dispose of three piles of radioactive slag & dust at Shieldalloy Metallurgical Corp.Also,requests to be placed on mailing list.	9401130304	12/3/1993
Comment expressing concerns re radioactive slag piles located at Shieldalloy in Newfield,NJ.Opposes capping slag piles w/clay.	9401260154	1/10/1994
Responds to 961105 statement re not renewing Newfield Facility license for handling radioactive matls.	9701020013	12/24/1996
Partially deleted Insp Rept 40-7102/85-01 on 850402. Noncompliance noted.Major areas inspected:mgt meeting, program requirements, followup on noncompliance & deviations, independent insp effort, transportation & mgt organization.	9002070304	5/8/1985
Comment re decommissioning of Shieldalloy Metallurgical Corp facility in Newfield,NJ.	9401260164	1/13/1994
Rev 0 to RSP-001, "Radiation Protection Program Plan (Newfield Facility)."	9509210194	9/15/1995
Advises that NRC has implicitly accepted jurisdiction over ferrovanadium slag by issuing directions to Shieldalloy Metallurgical Corp re licensee responsibility to monitor all outgoing ferrovanadium slag.	9112300027	12/18/1991

Amend 4 to License SMB-0743 for Shieldalloy Corp,authorizing use of metaliferous ore containing 0.4% U & 2% thorium for ore processing.	9002050313	1/10/1969
Ack receipt of 940315 ltr informing NRC of steps taken to correct violations noted in insp 40-7102/93-01 on 931202-03.	9408160160	7/29/1994
Notice of receipt of petition for director s decision under 10CFR2.206 by undated ltr requesting NRC revoke & downgrade Shieldalloy s license for Newfield,NJ site,thus permitting possession of LL radwaste for decommissioning only.	9611200109	11/14/1996
"Ferrocolumbium Slag Leachability Rept," for Shieldalloy Metallurgical Corp,Newfield,NJ.	9201210274	1/31/1992
Forwards update on phase I scoping survey of Vicinity Properties,Cambridge,OH.	9509180037	12/14/1994
Requests submittal of more detailed proposal of 900410 plan to circumscribe source matl storage yard w/ferrovanadium slag.Stated concerns should be addressed w/calculations on expected shielding results & design drawings.	9005110283	5/3/1990
Discusses Safety Insp 40-7102/87-01 on 871019.No violations noted.	8801120082	12/28/1987
Forwards requested results of quarterly radiochemical analysis of groundwater monitoring program,per JW Hickey 930114 request.	9302120210	2/5/1993
Insp Rept 40-7102/80-01 on 800926.Noncompliance noted.Major areas inspected:mgt meeting,program requirements, independent insp effort,transportation,organization,licensee internal audits & training & instructions to employees.	9002060204	10/6/1980
Advises of adjustments in application fee for renewal of License SMB-743.	9002070256	4/18/1986
Requests extension until 851231 to file environ info outline for License SMB-743.Extension required due to recent consolidation of environ affairs div & author appointment as environ manager.	8601020331	12/2/1985
Forwards application to amend SMB-743,as requested per 990713 telcon.	9907160197	7/13/1999
Responds to NRC 940216 ltr re violations noted in insp rept 40-7102/93-01 on 931202-03.Corrective actions:radiation safety committee to provide oversight for performance of activities as specified in 1992 OL renewal application.	9408160170	3/15/1994
Forwards application for renewal of License SMB-743.	9206150267	6/2/1992

Responds to NRC 900824 ltr re violations noted in Insp Rept 40-7102/90-01 on 900502. Corrective actions: radiation survey instrument submitted immediately after insp for calibr & calibr stickers will be placed on all calibr instruments.	9010020028	9/27/1990
Responds to NRC 790507 request for addl info re application for renewal of License SMB-743. Provides info, including description of final products, results of analysis of final product & total amount of thorium & U possessed at any time.	7908140357	6/28/1979
Responds to 961108 statement requesting NRC not to renew Newfield facility license for handling radioactive matls.	9701020092	12/24/1996
Forwards summary of 910814 meeting in Rockville, MD. List of attendees, example EA & SER prepared for renewal of source matl license & Branch Technical Position re disposal or on-site storage of thorium & U wastes. W/o encls.	9109030139	8/26/1991
Notice of proposed amended order per Bankruptcy Code Sections 328(a) & 1103 authorizing retention of Zolfo, Cooper & Co NUNC PRO TUNC to 930902 as financial advisors for debtors.	9311030154	9/13/1993
Forwards comments on draft annotated outline dtd 941020 for Shieldalloy Metallurgical Corp EIS.	9412280305	12/8/1994
Responds to 960209 request re licensing status of license SMB-920.	9602210227	2/13/1996
Insp Rept 40-7102/79-01 on 791031. No noncompliance noted. Major areas inspected: mgt meeting & mgt organization. Advises that review of 980506 & 13 ltrs re production of CANAL-lite Slag Fluidizer will continue upon receipt of listed info requested. "ALARA Program."	9002060173	11/6/1979
Forwards Shieldalloy s 940818 response to NRC request for addl info re Environmental Impact Statement for Shieldalloy Metallurgical Corp. Attachments J & L will be provided under separate cover. W/encl.	9806030253	5/21/1998
Third partial response to FOIA request for records. App C & D records encl & available in PDR. App E records withheld (ref FOIA exemption 5).	9501040002 9409070095	3/11/1994 8/29/1994
Undated comment re decommissioning of Shieldalloy Metallurgical Corp located in Newfield, NJ. Lists questions re issue.	9509210019	5/23/1995
Draft Rev 0 to Radiation Safety Procedure RSP-011, "Radiological Areas & Posting - Newfield Facility."	9401240329	1/19/1994
	9512050118	9/19/1995

Trip rept of 861203-04 site visit re discussion of license renewal & tour of slag storage & process areas. Some slag samples, not considered radioactive by licensee, had elevated readings of 50-70 micror/h. Runoff streams observed.	8612170340	12/12/1986
Forwards updated "Ferrocolumnium Slag Leachability Rept." Chart presenting leachability results for various nuclides of analyzed samples listed. Leachability of all nuclides greater than 9.8.	9201210272	1/16/1992
Responds to 940623 ltr to DK Rathbun, requesting that NRC review concerns raised by residents living near Shieldalloy Metallurgical Corp facility in Newfield, NJ.	9408040148	7/22/1994
Informs that NRC aware of NJDEPE intent not to accept offer of becoming cooperating agency on Shieldalloy EIS, in response to Marie e-mail on meeting w/NJ.	9508290220	3/22/1994
US Bankruptcy Court Southern District of NY order to show cause scheduling hearing on motion of Official Committee of Unsecured Creditors to compel debtors to provide equal info to prospective buyers & sellers of claims. W/encl.	9501090179	12/30/1994
"Radiation Dose Estimates for Members of General Public at Newfield, NJ Facility."	9307080204	2/16/1993
Provides Oak Ridge Associated Univs plan for surveying licensee facility in Newfield, NJ, per 870617 request, for review & comment. Requests to provide comments on subj plan as soon as possible.	9002060252	8/7/1987
Notice of proposed order per Section 327(a) of Bankruptcy Code authorizing debtors employment of Deloitte & Touche.	9310280177	10/18/1993
Forwards Amend 2 to License SMB-0743.	9002050250	9/21/1965
Requests withdrawal of 970306 license amend request for possession & storage of tantalum minerals for resale.	9707180256	7/1/1997
Informs that NRC staff accepting withdrawal request & will not take any further action re request.	9707230361	7/17/1997
Forwards status rept for CAL-1-95-04.	9510240399	5/15/1995
Requests response to encl comments & questions re 850619 application for renewal of License SMB-743 within 90 days. W/o draft guide on preparing applications.	8711120112	11/5/1987
Responds to petition re request to modify Shieldalloy Metallurgical Corp license to allow only possession of radioactive matl for express purpose of decommissioning & decontaminating Newfield facility. Director's Decision, encl.	9705010017	4/22/1997

Submits list of identified customers,who have expressed interest in performing trial runs for slag & schedule for obtaining executed contract for sale of slag.	9804280063	4/20/1998
"Notice of Motion for Entry of Order Pursuant to Sections 105 & 363 of Bankruptcy Code Authorizing Metallurg,Inc to Release Electrowerk Weisweiler GMBH From Certain Accrued Mgt Fees."	9402070228	1/28/1994
Requests that NRC review encl ltr from constituent L Williams re various proposals offered to deal w/ contamination at Shieldalloy site in Newfield,NJ.	9402150370	1/7/1994
Notice of appearance & request for svc of papers.	9309290284	9/20/1993
Opposes approach to develop draft DEIS for Cambridge site by devoting necessary technical experts to task re G Beveridge frustration on Shieldalloy.	9508290281	12/19/1994
Notice of consideration of license renewal request for Shieldalloy Metallurgical Corp Facility in Newfield,NJ & opportunity for hearing.	9706300103	6/25/1997
Comment supporting carting 1.2 million cubic yards of radwaste at Shieldalloy plant off site.	9401260159	1/11/1994
Forwards responses to NRC RAI re Newfield EIS,including ground water monitoring rept for period of Jul 1994,rept on "Rept on Surface Water Contamination Study..." & Vols I & II of "Summary of Geohydrologic Info Collected...."	9409150003	8/18/1994
Notice of violation from insp on 931202-03.Violation noted: air surveys in blending area & furnace area performed two times in 1993 frequency less than monthly.Licensee did not make adequate surveys to assure compliance w/10CFR20.106.	9402220093	1/31/1994
"Notice of Hearing on First Applications of Professionals for Allowance of Compensation for Svcs Rendered & Reimbursement of Expenses."	9405020129	3/2/1994
Forwards Application for renewal of License SMB-743. application prepared as discussed per latest draft of "Guide for Preparation of License Renewal Applications for Processors of Source Matl for Element Other...."	8807290067	7/18/1988
Advises that environ technical review meeting will be held on 901219 in Newfield,NJ to provide update on remedial investigation,groundwater studies & groundwater treatment. Attendance requested.	9012200175	12/14/1990
Confirms receipt of application for renewal of License SMB-743 & forwards environ info outline,per 850805 telcon. Environ info listed in outline should be submitted by 851001.	8508090393	8/5/1985

Discusses IE Insp Rept 40-7102/79-01 on 791031.No noncompliance noted.Major areas inspected:procedures & representative records,interviews w/personnel & measurements & observations made by inspector.	8001040436	11/14/1979
Forwards responses to request for addl info to support license renewal application for Shieldalloy Metallurgical Corp at Newfield.	9509210144	9/15/1995
Responds to 920108 memo re classification of Cabot in "Other" category.	9206100141	1/17/1992
Notice of appearance & request for notices & svc of papers.	9309290356	9/21/1993
Comment supporting carting 1.2 million cubic yards of radwaste at Shieldalloy plant off site.	9401260145	1/8/1994
Responds to 961105 statement requesting NRC not to renew Newfield facility license for handling radioactive mats.	9701020090	12/24/1996
Requests extension until 880715 for submittal of renewal application for License SMB-743.	8807180291	7/11/1988
Motion filed to compel debtors to provide equal info to prospective buyers & sellers of claims.W/supporting matl encl.	9501090196	12/30/1994
"Contamination Control."	9501040013	3/11/1994
Forwards Mayor E Marshall ltr re Shieldalloy site in Newfield,NJ for review & response.	9403170079	2/3/1994
Forwards check to cover fee for 801030 amend request for License SMB-743.	9002070236	11/24/1980
Ack receipt of 940621 ltr & advises that detailed budget for EIS will not be provided as requested.Costs to be billed in accordance w/10CFR170.12 of Commission regulations,encl.W/o encl.	9408050234	8/3/1994
Informs that Shieldalloy Environmental Assessment Annotated Outline is acceptable w/listed revisions.	9411300068	11/21/1994
Provides info re standardizing use of pyrochlore concentrates as used under License SMB-743,per 650903 request.Licensee program for future work also discussed.	9002060397	1/12/1965
Comment supporting Shieldalloy Metallurgical Corp remaining in town & continuing to provide jobs & much needed tax revenue to community.Advises capping slag piles w/clay, revegetating & monitoring of situation.	9401260110	1/6/1994
Transmits status rept for CAL-1-95-04.Next status rept will be forwarded by 950515.	9510240364	3/14/1995
"Measurement of Leachability of Solidified Low-Level Radioactive Wastes by a Short-Term Test Procedure." Complete hardcopy available in NRC Library.	8704130107	12/31/1986
Draft Rev 0 to Radiation Safety Procedure RSP-005, "ALARA Program - Newfield Facility."	9512050089	9/19/1995

Rev 0 to Procedure RSP-003, "Control of Radiation Safety Procedures (Newfield Facility)."	9510250248	10/6/1995
<p>Informs that,based on info submitted in 960624 ltr,NRC has performed independent dose calculations to determine potential doses to individual members of public as result of transfers.NRC has no objection to transfer.</p> <p>"Remedial Investigation Figures & Data Tables," final rept.</p> <p>US NRC FONSI for renewal of source matl license SMB-743 Shieldalloy Metallurgical Corp,Newfield,NJ.</p> <p>Forwards transcript of 931216 public scoping meeting re Shieldalloy Metallurgical Corp facility in Newfield,NJ, including fact sheet handouts from meeting & FR notice announcing meeting.</p>	9902190285	2/9/1999
	9708290239	4/30/1992
	9709290250	9/16/1997
	9401260023	1/13/1994
<p>Requests authorization to visit Shieldalloy Corp to observe facilities & equipment to be used in proposed activities,to observe site for burial of byproduct slag & to discuss items &/or info needed to amend license.</p> <p>Application for amend to License SMB-743,reflecting listed organizational changes in Shieldalloy Metallurgical Corp radiation protection program.</p> <p>Forwards ltr from Oak Ridge Inst for Science & Education on radioactivity of slag taken from vicinity properties,pages from rept on slag characteristics at Cambridge site & other info on slag at Shieldalloy-Cambridge,OH site.W/o encls.</p> <p>Forwards Attachment 1 to application for renewal of license SMB-743.Attachment 3 (Radiation Protection Program) & Attachment 5 (Methodology for Control Issues & Distribution of Radiation Safety Procedures) w/o word draft.</p>	9002060416	6/17/1965
	9708290175	8/11/1997
	9507250200	7/17/1995
	9510250241	10/12/1995
<p>Responds to 961109 statement requesting NRC not to renew Newfield facility license for handling radioactive matls.</p> <p>Amend to License SMB-0743 for Shieldalloy Corp,amending Item 10 of license to exempt licensee from requirements of 10CFR20.203(e)(2).</p> <p>Forwards sample of environ assessment document entitled "Environ Assessment for Decommissioning of B&W Apollo Site," dtd 920612 in response to an application from B&W.</p>	9701020081	12/24/1996
	9002050307	11/2/1966
	9302030156	1/29/1993
<p>Requests copy of Oak Ridge Associated Univs rept re field insp of Shieldalloy facility in Newfield,NJ.</p> <p>Forwards notice of opportunity for hearing to support renewal of matls License SMB-743.</p>	8809130071	6/14/1988
	9706270277	6/20/1997

Informs that listed statement apparently made in error & should be eliminated from original memo dtd 930226,in response to NRC 930504 ltr re State of NJ 930304 site visit memo.	9306090527	6/4/1993
Informs that application dtd 990923,requesting amend to license SMB-743,to reflect current makeup of radiation safety committee,has been accepted for formal review.	9910280163	10/14/1999
Responds to NRC 801015 ltr re violations noted in IE Insp Rept 40-07102/80-01.Corrective actions:signs posted in slag dump area & columbium ore storage area as required.	8012190683	10/30/1980
"Radiation Dose Estimates from Atmospheric Emissions from Newfield Facility."	9703180213	3/11/1997
Advises that as discussed in 950608 telcon,NRC has no objection to licensee accelerating monitoring schedules for sampling programs other than large area monitoring.	9507240372	7/11/1995
Comment supporting carting off site 1.2 million cubic yards of radwaste at Shieldalloy plant.	9401260196	1/12/1994
Forwards Rept IT/NS-92-118,Rev 0, "Applicant Environ Rept for Newfield,NJ Facility," per 920417 ltr requesting updated environ info.	9211030183	10/28/1992
Application for amend to license SMB-743,reflecting current makeup of Radiation Safety Committee.	9910040263	9/23/1999
Responds to 961114 statement requesting NRC not renew Newfield facility license for handling radioactive matls.	9701030063	12/24/1996
Responds to 961101 statement requesting NRC not to renew Newfield facility license for handling radioactive matls.	9701020052	12/24/1996
Comment re renewing license for Shieldalloy Metallurgical Corp of Newfield,NJ.Supports renewing license & allowing slag to be buried on site.	9401260161	1/11/1994
Forwards "Shieldalloy Metallurgical Corp,Cambridge,OH West Pile Decommissioning Plan Supporting Design Calculations & Recommendations in Ref to NRC Comments."	9109230081	9/16/1991
Informs that HN Schooley replaces S Rappaport as president of Shieldalloy Metallurgical Corp & that effective immediately,responsibility for both Newfield,NJ & Cambridge, OH facilities transferred to HN Schooley.	9405170154	5/6/1994
Responds to Nov 1996 statement requesting NRC not to renew Newfield facility license for handling radioactive matls.	9701020087	12/24/1996
Provides figures indicating location of water & soil samples taken at Shieldalloy Corp on 861204.	9002060242	12/10/1986

Responds to NRC request to revise proposed source matl possession limits in 880718 application for amend to License SMB-743 to reflect recent recalculations of inventory at Newfield Facility.	9202250014	2/13/1992
Application for amend to License SMB-743,reflecting listed administrative changes in radiation protection program.	9302030276	1/25/1993
Discusses scoping process for EIS & forwards EIS summary rept June 1994.	9407250101	7/15/1994
Requests update on status re decommissioning of Shieldalloy Metallurgical Corp facility located in Borough of Newfield be provided to Mayor of Newfield & Council.	9506090061	5/8/1995
Rev to application for renewal of License SMB-743.	8808240149	8/3/1988
Application for amend to license SMB-0743,replacing annual limit on intake (ALI) & derived air concentration (DAC) for Y-class thorium & U compounds that appear in App B of 10CFR20 with 1995 recommendations of ICRP.	9909270191	9/9/1999
Provides input re Shieldalloy Corp application for renewal of license.Requirement for annual repts summarizing environ monitoring results & any significant activities influencing radiological conditions on or off site requested.Data encl.	8611210193	10/20/1986
Discusses insp of License SMB-743 on 850402 & forwards notice of violation.Corrective actions described in 801030 ltr not effective.Response should address recurrent violations & provide addl info re waste storage & disposal.	8507030282	6/21/1985
Notice of proposed order per Section 1121(d) of Bankruptcy Code extending debtors exclusive period in which to solicit acceptance of plan of reorganization.	9603180375	3/8/1996
Submits items of interest.On 870217,GH Bidinger met w/B&W representatives to review draft license renewal document & on 870213,meeting held w/Shieldalloy to discuss addl info needed to complete environ assessment for license renewal.	8702270190	2/18/1987
Forwards revised summary of 910814 meeting w/Shieldalloy Metallurgical Corp in Rockville,MD.	9109250116	9/13/1991
Forwards response to NRC 861211 questions re slags,left unanswered as of 870422 & 29.Delay in response due to environ assessment & development of solutions resulting from purchase of Ohio plant.	8710010054	9/2/1987

Confirmatory action ltr CAL 1-95-04 re potential safety & regulatory concerns noted during insp on 950215-17. Concerns re adequacy of dose assessments to both occupational workers & members of public. Listed actions taken by licensee.	9503210163	2/22/1995
Application for license, authorizing use of 17,637 lb pyrochlore containing 1.2-2.0% thorium & 0.03-0.07% U as oxides.	9002060320	11/25/1963
Ack receipt of undated ltr requesting action re revocation of Shieldalloy's license for Newfield, NJ site & instead downgrading license. Copy of FRN & SECY Paper 96-210 encl.	9611200105	11/14/1996
Requests addl info for renewal of License SMB-743 re environ assessment. List of questions discussed during 861203-04 site visit encl. Written response requested by 870220.	8612150135	12/11/1986
Forwards technical position on fire protection for fuel cycle facilities, published in FR on 920810.	9210130172	10/6/1992
Forwards amended 1996 & 1997 source matl inventory spreadsheets, as follow-up to 970812 telcon. Error occurred in amount of CANAL shipped.	9708200138	8/12/1997
Requests response to encl questions & list of documents ref in past documents & conversations, but not in NRC inventory, in order to assist NRC in development of EIS re permanent disposal of radioactive contaminated matl at facility.	9406280254	6/23/1994
Provides info in response to 871015 ltr re NRC survey effort to characterize facility radiological status. Licensee has contracted w/Oak Ridge Associated Univs to characterize radiological aspects of facility operation.	8712140436	12/9/1987
Approves Shieldalloy request for extension of submittal date for responses to questions & rev to renewal application until 880715.	8808030155	7/14/1988
Ack receipt of 761111 ltr informing NRC of corrective & preventive actions taken re violations noted in Insp Rept 40-7102/76-01.	9002050442	11/19/1976
Discusses delay of issuance of draft EIS re decommissioning of Shieldalloy Metallurgical Corp facility in Newfield, NJ. Lists reason NRC maintain stated piles not release & are only considered to be in storage.	9501250352	1/20/1995
Forwards rept of analyses of soil samples for non-radiological components performed as part of survey of facility conducted in 1987.	8902170126	2/9/1989
Forwards estimation of public dose exposures from baghouse releases at Shieldalloy Metallurgical Corp Newfield facility.	9707160099	7/9/1997
Forwards revised "Annotated Outline for Shieldalloy Metallurgical Corp (SMC) Environ Assessment."	9303170176	3/5/1993

Forwards "Conceptual Decommissioning Plan for Newfield NJ Facility.	9512210174	12/12/1995
Forwards predecisional enforcement conference rept conducted on 981001 in King of Prussia,PA,to gain better understanding of position & completed & planned actions to correct seven apparent violations & concerns in insp rept 40-7102/98-01.	9902100074	1/21/1999
Provides info,per telcon request re 650525 application for amend to License SMB-743.Auxiliary operations to be employed in preparing ore for aluminothermic or electric furnace smelting listed.	9002060418	8/30/1965
Requests that revised environ rept be submitted in support of technical review of license renewal application.Requests info by 920601.	9204230263	4/17/1992
Apologizes for assessing annual fee for FY91 in excess for license SMB-743.	9206100140	5/20/1992
"Decommissioning Funding Plan for Newfield,NJ Facility."	9910290229	10/14/1999
Forwards "Radiological Survey of Shieldalloy Corp Newfield, NJ," Jul 1988.W/o encl.	9001080128	12/26/1989
Notification of 931103 meeting w/Shieldalloy Metallurgical Corp in Rockville,MD to discuss licensees notification of Chapter 11 filing & alternatives for future decommissioning of facility.	9310290208	10/28/1993
Draft Rev 0 to Radiation Safety Procedure RSP-012, "Control of Work - Newfield Facility."	9512050121	11/21/1995
Forwards description of analysis,tables of results & brief discussion of results re east pile slag from Shieldalloy Metallurgical Corp Cambridge,OH facility.	9810210277	6/11/1998
Forwards comments on draft annotated outlines dtd 941020 for Shieldalloy Metallurgical Corp EIS.	9501030140	12/8/1994
Forwards EIS statement schedules for listed Site Decommissioning Mgt Plan sites.	9701080200	12/19/1996
Notifies NRC of electing not to renew Standby Ltr of Credit for addl one yr period beyond current 930718 expiration.	9305270275	4/19/1993
License SMB-0743 for Shieldalloy Corp,authorizing use of unlimited quantities of metaliferous ore containing 0.4% U & 2% thorium for ore processing.	9002050429	1/24/1973
Ack receipt of AEC 650201 ltr & requests for extension of License SMB-743.Requests that license be further revised to allow licensee to process unlimited quantities of Araxa pyrochlore concentrates & resulting slag,per 650112 ltr.	9002060404	2/15/1965

Responds to 940103 ltr to Vice President Gore.NRC carefully evaluating comments on proposed scope of NRC review of Shieldalloy Metallurgical Corp proposed in situ disposal of radioactive matl at Newfield,NJ facility.	9403170086	3/14/1994
Application for renewal of License SMB-0743,authorizing use of unlimited quantities of metaliferous ores containing 0.4% U & 2.0% thorium for ore processing & potential radiation hazard evaluation per procedures described.	9002060058	12/23/1977
Forwards final rept, "Radiological Survey of Shieldalloy Corp,Newfield,NJ."	8808180013	7/27/1988
Requests addl info re 641124 application for renewal of License SMB-743.Lists info needed.Advises that no allowance shall be made for use of protective equipment in determining exposure of personnel to radioactivity in excess of limits.	9002060384	12/24/1964
Comments on EIS proposal issued by NRC in FR on 931126 re Shieldalloy Metallurgical Corp site in Cambridge,OH,to determine whether on-site stabilization & disposal of radwaste acceptable for decommissioning.	9402170247	1/14/1994
Final response to FOIA request for documents.Records in App A encl & will be made available in PDR.	9702130125	2/11/1997
Forwards info which contains revised copy of attachment 1 of 980325 amend application showing wording designed to clarify authorized use of source matl by Shieldalloy Metallurgical Corp to avoid further questions re Provision 10.	9904020242	3/10/1999
Informs that time provided by NRC regulation within which Commission may act to review Director s Decision DD-97-10 expired.Decision became final agency action on 970512.	9705190127	5/16/1997
W/Certificate of Svc.Served on 970516.		
Second interim order authorizing continuation of centralized cash mgt sys.	9309280246	9/21/1993
Forwards notice published in 950821 FR announcing NRC intent to revise scope of environ impact statement,preparing for Shieldalloy facility in Cambridge,OH.	9509180050	9/7/1995
Requests that NRC review constituents J & P Madden ltr re concern over proposals offered to deal w/contamination at Shieldalloy site in Newfield,NJ.	9403140312	2/7/1994
Forwards evaluation of dose assessment for four scenarios in response to technical assistance request dtd 971230 re review of Shieldalloy Metallurgical Corp dose assessment in support of sale of east slag pile.	9810210273	2/25/1998

Notice of violation from insp on 850402. Violations noted: air surveys in blending area not performed since 800926 & air surveys in furnace area performed only four times in 1981, once per yr during 1982-84 & not at all in 1985.	8507030293	6/21/1985
Forwards response to RAI for 920602 application.	9412300007	12/22/1994
Responds to 980924 ltr re sale of stock by former Metallurg, Inc shareholders to group of institutional investors headed by Safeguard International, Inc last July. Copy of agreement is attached.	9810070165	9/29/1998
Ack receipt of notice of expiration of License SMB-743 & submits Form AEC-2, per request.	9002060371	11/24/1964
Forwards rept 94005/G-6131, "Radiation Dose Estimates from Atmospheric Emissions from Newfield Facility."	9703180209	3/11/1997
Confirms 920901 as submittal date for revised rept, updating previously submitted environ info outline in License SBM-743 renewal application, in response to 920419 ltr & 920505 telcon.	9205280076	5/21/1992
Forwards analytical results from ground water sampling at Shieldalloy Metallurgical Corp, in follow up to 950919 telcon. Six monitoring wells (and one duplicate) sampled & analyzed using gamma spectroscopy as requested by State.	9510200245	9/20/1995
Forwards ANSI/ANS-16.1-1986 for licensee to perform leachability test, demonstrating non-leachable nature of radium, U & thorium contained in slag temporarily store onsite. Results of test requested before 911118.	9106200089	6/14/1991
Amend 2 to License SMB-743 for Shieldalloy Corp, authorizing use of unlimited quantities of Brazilian pyrochlore containing 0.07% U & 2.0% thorium & 15 tons of baddeleyite.	9002060412	4/5/1965
Renewed license SMB-743 for Shieldalloy Metallurgical Corp.	9907160205	10/20/1997
Requests new signed original ltr of credit re financial assurance for licenses SMB-1507 & SMB-743 within 30 days of ltr date.	9603210362	3/12/1996
Informs that matls license amended to authorize increase in possession & storage of source matl & personnel changes in radiation protection program, as requested in application for amend, dtd 940803.	9409290229	9/23/1994
"Gamma Spectrometry Results."	9710270123	9/8/1997
Responds to request for comments re scope of proposed EIS for decommissioning of Shieldalloy Metallurgical Corp facility in Newfield, NJ.	9401270297	1/11/1994

Forwards draft rept on radiological survey at licensee site in Newfield,NJ.Rept to be finalized based on comments from Region I & NMSS.Analyses for nonradiological metal contaminants in soil,sediment & water samples performed.	9002060276	5/31/1988
Lists MA Finn,Group Secretary,Metallurg,Inc & JE Silberg, Esquire of Shaw,Pittman,Potts & Trowbridge,to be copied on any future correspondence from NRC.	9111040119	10/22/1991
"Control of SOPs for Radiation Safety."	9501040005	3/10/1994
"Radon-222 Emission Assessment Ferrocolumbium Slag at Newfield,NJ Facility."	9603200209	1/11/1995
Recommends that NMSS pursue meeting schedule outlined by licensee.	9508290252	12/11/1994
"Environmental Impact Statement Scoping Process Summary Report."	9407250110	6/30/1994
Undated comment re decommissioning of Shieldalloy Metallurgical Corp located in Newfield,NJ.Lists questions re issue.	9401240327	1/19/1994
Informs that licensee responses to 25% of NRC 870105 questions prepared but remaining questions require careful review of regulations.Requests extension of response submittal until 880405.	9002060273	2/25/1988
"GENERAL ARRANGEMENT MAP." Sheet 2 of 14.	8911130309	6/8/1989
Advises of transfer of responsibility for licensing of facility from Fuel Cycle Safety Branch to Licensing Branch, effective 930208.Future correspondence should be addressed, as listed.	9304150015	4/14/1993
"Notice of Motion for Entry of Order Pursuant to Bankruptcy Code Sections 105 & 363 Authorizing Payment of Certain Prepetition Wage Obligations in Excess of \$2,000."	9405020145	11/16/1993
Responds to NRC 850621 ltr re violations noted in Insp Rept 40-7102/85-01.Corrective actions:air sampled,film badge program results showed average whole body exposure negligible & gamma surveys to be taken quarterly.	8508220109	7/17/1985
Ack receipt of 941216 ltr informing NRC of steps taken to correct violations noted in insp rept 40-07102/93-01.	9502030263	1/27/1995
Advises that OH EPA will follow guidelines for info repositories as outlined in Natl Oil & Hazardous Substances Pollution Contingency Plan 40CFR300,Subpart I,Section 300.800-300.810 re Shieldalloy site.	9403170226	3/7/1994
Requests addl info re sale of Metallurg,Inc to fully understand terms of sale & potential impact of Shieldalloy Metallurgical Corp.Response requested in advance of 981001 enforcement conference.	9810070230	9/24/1998

Summary of 910814 meeting w/Shieldalloy Metallurgical Corp in Rockville,MD re Cambridge,OH site,including decommissioning of two slag piles containing source matl & sampling & analysis of surface water.List of attendees encl.	9109250123	9/13/1991
Requests for addl info re baghouse dust sampling from Newfield facility.	9707230358	7/14/1997
Revised attachments to 920602 application for renewal of License SMB-743.	9302220449	2/10/1993
Forwards general population dose estimates from atmospheric emissions.CAP88-PC Synopsis Rept encl.	9705160125	5/8/1997
Fifth partial response to FOIA request for records re Foote Mineral/Shield Alloy/Cyprus Mineral site in Cambridge,OH. Records in App G available in PDR.	9509110081	8/8/1995
Forwards info provided to Consulate General for Trinidad & Tobago in response to request for info re possible toxicity of CANAL,per 951005 meeting.	9511030069	10/12/1995
Comment on proposed rule re decommissioning of Shieldalloy Metallurgical Corp facility in Newfield,NJ & notice of intent to prepare EIS & to conduct scoping process.	9401240330	1/14/1994
Submits addl info requested by NRC 800404 ltr re application to renew Matl/Byproduct License SMB-743.Disposal of ferrocolumbian slag would require transfer of 122 million lb of matl.Requests meeting.	8006170424	4/16/1980
Responds to 910309 request for exemption from provisions of 10CFR40 in order to authorize receipt,possession,use & transfer of specific amount of source matl contained in imported batch of FeSiZr.	9105280173	5/20/1991
Ack receipt of 850717 ltr informing NRC of steps taken to correct violations noted in Insp Rept 40-7102/85-01.Results of film badge program unrelated to exposure from airborne radioactive concentrations.	8508220104	8/15/1985
Responds to 910607 ltr requesting clarification re Shieldalloy Metallurgical Corp handling & sale of 55,920 lbs of ferrosilicon zirconium.NRC does not consider inadvertent receipt & transfer of source matl,substantial safety hazard.	9109030011	8/21/1991
Discusses insp 40-07102/93-01 on 931202-03.Violations noted but not cited.Radiation safety program currently required by license not adequate,especially in areas of environmental monitoring & meeting requirements of new part 20.	9403220022	3/15/1994
Certificate of Commencement of Case re Metallurg,Inc & Shieldalloy Metallurgical Corp petition requesting relief under chapter 11 of Bankruptcy Code (title 11 of US Code).	9309130195	9/2/1993

Informs that NRC proceeding w/development of EIS that will evaluate disposition alternatives for stabilization & disposal,in response to commitment made at 931103 meeting w/ Shieldalloy Metallurgical Corp.	9404190084	4/7/1994
Provides addl response to NRC 761015 ltr re violations noted in Insp Rept 40-7102/76-01 on 761006.Retained WL Silvernail as consultant to review licensee radiation safety program at Newfield facility.Consultant review rept forwarded.W/o encl.	9002060040	3/11/1977
Comment supporting carting 1.2 million cubic yards of radwaste at Shieldalloy plant off site.	9401260143	1/12/1994
Requests copy of IT Corp evaluation of low-level radioactive matls at Shieldalloy Corp Newfield,NJ site & to be kept informed of status & conclusions of EA of continuing operations at facility.	9401130307	12/22/1993
Comment supporting 1.2 cubic yards of radwaste at Shieldalloy plant off site.	9401260115	1/9/1994
Responds to 921215 request for further environ info re license renewal application.Vendor has not applied nor been granted permit allowing releases of radioactivity to environ by any govt agency.Survey form encl.	9302030344	1/22/1993
Inquires if CJ Glenn could attend meeting in Arlotto office re Shieldalloy-Newfield.Discusses comments made at impromptu meeting w/Bernero & Burnett.	9508290226	8/31/1994
Advises that final position on jurisdictional issues related to disposition of ferrovanadium slag at site will not be available until appropriate review & concurrence by NRC mgt has occurred & is not expected by 911230,as requested.	9201070114	12/24/1991
Informs that SN Rappaport resigned as President of Shieldalloy Metallurgical Corp.Requests that repts & other correspondence be sent to successor,HN Schooley,PO Box 768,Newfield NJ.	9503020232	2/21/1995
THORIUM-232 CONCENTRATIONS IN SOIL & WATER SAMPLES.	9204290381	3/6/1992
Forwards comments on Shieldalloy Metallurgical Corp final revs to remedial investigation work plan dtd 900706 & 20. Grants licensee conditional approval of remedial investigation work plan.	9010020229	9/21/1990
Undated comment on decommissioning of Shieldalloy Metallurgical Corp in Newfield,NJ.Lists questions re matter.	9401240324	1/19/1994
Provides listing of key steps involved in sale of CANAL to either foreign or domestic customers,per 970929 telcon.	9710060087	9/29/1997

Comments re NRC proposals on how best to deal w/1.2 million cubic yards of radwaste at Shieldalloy Corp.Advises that NRC revoke or not renew Shieldalloy licenses to use radioactive matl.	9401260165	1/12/1994
Discusses draft EIS re process rept for Sheildalloy Metallurgical Corp.NRC agrees that final cleanup standards be applied to site.	9407150092	7/11/1994
Discusses info re Shieldalloy Corp site in Newfield, Gloucester County,NJ & forwards fact sheets re Agency For Toxic Substances & Disease Registry & health consultation process.	9404050070	3/18/1994
Forwards request for addl info re environ assessment for renewal of Shieldalloy Metallurgical Corp.	9401180090	1/12/1994
Discusses concerns from citizen who originally indicated that fill matl which may have been radioactively contaminated might have been used as fill in large pits on Shieldalloy Metallurgical Corp site.	9509150054	5/1/1995
Responds to 950606 ltr,to RL Bangart of NRC.Ltr requested that NRC consider comments,presented by 950508 ltr,re disposal of nuclear waste at Shieldalloy Metallurgical Corp facility located at Newfield,NJ.	9508020145	7/25/1995
Responds to Spall 950508 ltr requesting an update re developments of decommissioning plans for Shieldalloy Metallurgical Corp facility located near Newfield,NJ.	9506090058	5/31/1995
Forwards ltr to Shieldalloy Corp,terminating svcs as consultant on License SMB-743.	9002070245	10/15/1982
Provides assurance to NRC that licensee will not ship any of CANAL-Lite Slag fluidizer which had been blended & prepared for shipment to N Hickman on 980420.Telcon record of 980505 from P Henderson of NRC to D Smith & J Valenti,encl.	9805270060	5/6/1998
"Gamma Replicate Summary," w/"Gross Alpha & Beta Analytical Results" & "Gross Alpha/Beta Replicate Summary," included.	9710270135	9/8/1997
Forwards publication of NUREG-1543, "DEIS - Decommissioning of Shieldalloy Metallurgical Corp,Cambridge,OH,Facility," completed Forms 335 & 426.W/o attachments 1-3.	9607010236	6/27/1996
Requests addl info on invoices charged to licenses SMB-743 & SMB-1507.Invoices encl.	9502100040	12/16/1994
Forwards copy of 961217 ltr to CS Eves from GC Comfort re bioassay testing for employees at Shieldalloy.	9701240177	1/8/1997
Informs that licensee will be able to comply w/AEC recommendation.After 661104,licensee will be governed by 10CFR20.203(f)(3)(iv) & (vi).	9002070065	10/24/1966
Requests copy of transcript re 960131 meeting at St Rose Vineland,NJ.	9603050517	2/27/1996

Forwards documents requested by 940428 ltr to assist in developing EIS for decommissioning Shieldalloy Metallurgical Corp.NRC will obtain remaining info requested from licensee.W/o encl.	9406100215	6/7/1994
"Stop Work Authority."	9501040015	3/11/1994
Summary of 910827 environ technical review meeting in Newfield,NJ re lagoon characterization work plan, monitoring well closure & replacements & underground storage tank closure plan.List of attendees encl.	9112060143	12/3/1991
Insp Rept 40-7102/68-01 on 680607.No noncompliance noted. Major areas inspected:administrative control,use of licensed matl,facilities,equipment,radiological safety procedures & personnel monitoring & exposure to external radiation.	9002050422	7/17/1968
AMBIENT GAMMA EXPOSURE RATES.	9204290366	3/4/1992
"Environ Evaluation Addendum Shieldalloy Metallurgical Corp Newfield,NJ."	9411230176	6/30/1994
Second partial response to FOIA request for documents. Forwards documents listed in App B.Documents withheld in part (ref FOIA exemption 6).	9508280134	5/17/1995
Acks receipt of 950531 ltr & requests that any further actions or developments w/regard to Newfield Site Of Shieldalloy be communicated to Borough by correspondence sent to attention of Mayor & Council.	9507070194	6/7/1995
Offers support for Shieldalloy Metallurgical Corp proposed alternative for decommissioning facility in Newfield,NJ.	9312280098	12/17/1993
Discusses weekly conference call re Shieldalloy contractors concerning item of interest.	9509220002	3/3/1995
Expresses desire for systematic gamma survey of all licensee properties,documenting current radiological conditions of site both inside & outside controlled area.Provides comments on proposed survey plan by Oak Ridge Associated Univs.	9002060259	9/2/1987
Requests formally that NRC provide further explanation in responses to comments prior to finalizing draft environ impact statement scoping process summary rept for Shieldalloy Metallurgical Corp facility in Newfield,NJ.	9406060283	5/12/1994
Amend 8 to License SMB-743 for Shieldalloy Metallurgical Corp,authorizing increase in possession & storage onsite of source matl (thorium & U) & reflecting change of name.	9204070080	4/2/1992
Forwards drawing of storage yard showing locations of four proposed monitoring wells.NRC permission to drill subj wells for groundwater chrome contamination studies at facility requested.	8808180388	8/1/1988

<p>Advises that Div of Industrial & Medical Nuclear Safety sponsoring 2 1/2 day Fuel Cycle Licensee Workshop on 920915- 17 in Bethesda,MD.Purpose of workshop is to discuss NRC programs & policies applicable to fuel cycle licensees.</p>	9207240014	7/20/1992
<p>Discusses final rule re radiological criteria for license termination.</p>	9709240190	9/12/1997
<p>Safety insp on 650630 of License SMB-743.Insp findings: source matl possessed & used in form of Norwegian & Nigerian ore & 38,000 lb Baddeleyite ore w/o authorization & slag storage drums not labeled.W/5 oversize drawings.</p>	9002070290	6/30/1965
<p>Forwards "Work Plan for Radiological Characterization of Shieldalloy Metallurgical Corp Newfield Facility." Site work & reporting planned for completion during fourth quarter 1990.</p>	9007120171	6/29/1990
<p>Comment on proposed rule re disposal of Shieldalloy slag & baghouse dust from ferrocolumbium operations.Concerned w/NRC present evaluation process re subj.</p>	9401240323	1/14/1994
<p>Vols I & II of "Summary of Geohydrologic Info Collected Since Jan 1988 Shieldalloy Metallurgical Corp Newfield,NJ."</p>	9409150010	4/30/1990
<p>Forwards application for renewal of License SMB-743.</p>	9002070196	1/12/1973
<p>Requests course of action & legal ramifications of NRC release of Oak Ridge data re Shield Alloy Corp Site in Newfield,NJ.</p>	9403290148	3/18/1994
<p>Informs that licensee has scheduled meeting for 960131 at 6:30 p.m. at St Rose of Lima Church.</p>	9601250066	12/21/1995
<p>Safety insp on 680221 of License SMB-743.Insp findings:no noncompliance noted.</p>	9002070160	6/21/1968
<p>Forwards notice published in 950821 FR announcing NRC intent to revise scope of environ impact statement,preparing for Shieldalloy facility in Cambridge,OH.</p>	9509180046	9/7/1995
<p>Expresses thanks for NRC 940113 reply re Shieldalloy & decommissioning plan.Background & EIS outline in FR & page from NUREG-1444 informative.Resolutions opposing nuclear waste storage facility in Borough of Newfield county encl.</p>	9403140093	2/13/1994
<p>Forwards 940312 ltr from TF Ragone,P Hallett & L Williams for response.</p>	9408100126	6/23/1994
<p>Forwards draft copy of RSP-010 "Exposure Control-Newfield Facility.Variou requirements & parameters involved w/indirect bioassay of potentially exposed individuals addressed.</p>	9706110025	6/5/1997
<p>Requests listed documents re Shieldalloy Corp,including existing NRC permit or license,new permit when issued & environ survey rept.</p>	8809010315	7/25/1988

"Order Fixing Time,Date & Place & Limiting Notice of Hearing on Motion of Debtors for Entry of Order Per Sections 105 & 363(b) of Bankruptcy Code Authorizing Debtors to Consent,as Lienholder,to Sale of Certain Property."	9408240168	8/15/1994
"Statement of Account," consisting of statement of income & principal transactions & list of assets,per Trust Agreement dtd 900719 & between Shieldalloy Metallurgical Corp & Mellon Bank,NA.	9208250034	7/1/1992
Forwards copy of conceptual decommissioning plan for Shieldalloy,dtd 930407,in response to 931222 request & informs that NRC will add recipient to mailing list to receive copy of EA.W/o encl.	9401130309	1/11/1994
Forwards License SMB-743,as renewed.	9002070156	1/10/1968
Forwards amend 1 to license SMB-743.License is amended by removing D203A from listing of permanent restricted areas. SER encl.	9907230297	7/20/1999
Forwards request for addl info on invoices submitted to licensee for action.	9502100029	2/7/1995
Responds to 940318 ltr,requesting advice on how to gather data from NRC re Shieldalloy Metallurgical Corp facility located in Newfield,NJ.Forwards copy of "Radiological Survey Of Shieldalloy Corp,Newfield,NJ," (ORAU-88/G-79).	9404050063	3/29/1994
Amend to License SMB-743 for Shieldalloy Corp,exempting licensee from requirements of 10CFR20.203(e)(2) for areas within plant provided all entrances to plant conspicuously posted per subj regulation.	9002070104	11/2/1966
Confirms 941118 telcon re violations noted in insp rept 40-7102/93-01.Understands that licensee did not receive NRC 940729 ltr & that corrective actions taken or planned will be forwarded by 941221.	9501050165	11/23/1994
Documents telcon w/J Wilson of Academy of Natural Science in Philadelphia,PA,re leaking drums in Newfield landfill owned by licensee.Insp of subj leaking drums requested.	9002060197	9/11/1980
Forwards Shieldalloy Metallurgical Corp proposal to use radioactive shielding for listed ferrocolumbium slags. Listed values reported in Oak Ridge Assoc Univs rept, "Radiological Survey of Shieldalloy Corp," dtd Jul 1988.	9001020316	12/6/1989
Forwards certified copy of resolution unanimously adopted by Mayor & Council of Borough of Newfield at Regular Meeting held 950711.	9509200113	7/14/1995

Informs that HN Schooley new President of Shieldalloy Metallurgical Corp (SMC), replacing S Rappaport & that effective immediately R Swenson responsibility for SMC Radiation Protection Program transferred to HN Schooley.	9405240184	5/6/1994
Ack receipt of application for renewal of License SMB-0743. Application deemed timely filed & accordingly, license will not expire until final action taken by ofc.	9002070224	1/20/1978
"Final Focused Feasibility Study Rept Ground Water Remediation."	9411230177	2/28/1994
Forwards info re disposal of nuclear waste at Shieldalloy Metallurgical Corp facility located at Newfield, NJ for consideration & would appreciate receiving info as soon as possible.	9508020151	6/6/1995
Forwards insp rept 40-7102/94-01 on 940322-0421. No violations noted.	9408240001	8/10/1994
Amend 6 to License SMB-0743 for Shieldalloy Corp, amending license in entirety.	8008250641	2/6/1981
Requests verification survey of facility. Site will be ready for release survey by fourth wk of October w/exception of four areas. W/one oversize drawing.	8911080246	10/17/1989
Informs that application dtd 990925, requesting amend to license SMB-743, to replace annual limit on intake (ALI) & derived air concentration (DAC) for Y-Class thorium & U compounds, has been accepted for formal review.	9910280157	10/14/1999
Advises that next licensee reviewer should get estimate of U & thorium in slag dump & tighter controls on airborne activity monitoring (blending & furnace areas) & develop requirement for bioassays.	9002060225	4/5/1985
Revised "Radiation Protection Program Plan."	9906090144	6/1/1999
Forwards info requested by American Embassy in Trinidad re toxicity repts or data on canal-slag fluidizer.	9511030062	11/1/1995
Advises that no deficiencies noted during review of decommissioning financial assurance submittal dtd 900723.	9110040287	9/30/1991
Application for renewal of License SMB-743 for Shieldalloy, Newfield facility.	9206150306	5/30/1992
Draft Rev 0 to Radiation Safety Procedure RSP-010, "Exposure Control - Newfield Facility."	9512050115	9/19/1995
Advises that MR Morgenstern informed of second extension of submittal date to 880630 per 880603 request.	8806290458	6/21/1988
Forwards amend to AEC License SMB-743. Advises that application for authorization to dispose licensed matl by burial in manner different from 10CFR20.304 specs must be filed. Airborne survey program included in amend.	9002060410	4/5/1965

Forwards Rept 94005/3-001, "Radon-222 Emission Assessment Ferrocolumbium slag at Newfield,NJ Facility."	9603200207	3/13/1996
"Control of Radwaste."	9501040016	3/10/1994
"Assessment of Environmental Radiological Conditions at Newfield Facility." W/nine oversize drawings.	9204270290	4/9/1992
Requests that submittal date for response to NRC 930505 request for addl info re environ assessment questions for license renewal be rescheduled to 930630.Delay due to time required to receive response from various federal agencies.	9306030251	5/27/1993
Confirms schedule of meeting on 921118 in Rockville,MD to discuss NRC initial comments re 920602 license amend & renewal request for matl license SMB-743.	9211130350	11/3/1992
Discusses Shieldalloy stabilization of Columbium slag at Newfield,NJ.	9402150334	1/27/1994
Rcommends that attention be given to licensee air surveys during next insp of License SMB-0743.Complete info on method for obtaining & analyzing samples not available during 650526 insp.	9002050373	7/13/1965
Draft Rev 0 to Radiation Safety Procedure RSP-008, "Instrumentation & Surveillance - Newfield Facility."	9512050110	10/10/1995
Expresses concern re radioactive slag piles located at Shieldalloy in Newfield,NJ.	9403230023	1/11/1994
First partial response to FOIA request for documents.Records in App A encl & will be available in PDR.	9509150027	5/1/1995
Forwards rept 94005/G-9194, "Decommissioning Funding Plan for Newfield,NJ Facility," including description of decommissioning objective for facility,conceptual plan for decommissioning & how costs will be funded.	9910290228	10/19/1999
Forwards annotated outline for licensees proposed EA. Requests that responses to questions be submitted by 930530.	9305120034	5/5/1993
Forwards partially withheld info re Shieldalloy meetings of 12/1.	9508290287	12/2/1994
Forwards FRN re NRC issuance of "Clarification of Decommissioning Funding Requirements," (60FR38235) dtd 950726,as discussed in meeting w/licensee on 951005.	9510190393	10/11/1995
Forwards amend to Irrevocable Ltr of Credit 839-51288, extending validity until 940718.All other terms & conditions unchanged.	9306100359	6/2/1993
RAI for SER for license renewal application.	9508160321	8/8/1995
Advises of preparation to proceed w/circumscription & shielding of source matl storage yard at Newfield plant.	9004190255	4/10/1990

Informs that effective 930901, membership of licensee Radiation Safety Committee revised as listed.	9309160103	9/9/1993
Trip rept of 941221 visit to Shieldalloy Metallurgical Corp facility in Newfield, NJ to familiarize M Lamastra w/site operations.	9501260001	1/18/1995
"Technical Basis for Use of Baghouse Dust as Additive in Concrete Production."	9607010130	6/17/1996
Comment on proposed rule re decommissioning of Shieldalloy facility in NJ. Urges NRC to use power & influence to force Shieldalloy to clean up radioactive mess made in Newfield, NJ.	9401250103	1/12/1994
Requests extension for application of NRC License renewal until 880715. Delay due to conduct of radiation protection programs & major environ programs.	8807200154	7/11/1988
Forwards License SMB-0743 re disposal of slag from smelting operations per 10CFR20.301.	9002060334	12/20/1963
Ack receipt of encl ltr dtd 950519 forwarding B Marcyniuk & Z Marcyniuk 950508 ltr expressing concerns re storage of radioactive matl at Shieldalloy Metallurgical Corp.	9507070422	6/27/1995
Requests to provide info specified in Part II of encl re review of bioassay program. NRC will examine licensee bioassay program at future NRC insp.	9802240112	1/28/1998
Comment supporting on site capping re Shieldalloy plant.	9401250004	1/12/1994
Advises that fee required for 801030 application for amend to License SMB-0743, per 10CFR170.	9002070232	11/12/1980
Discusses info re 920602 revised application requesting renewal of license SMB-743.	9411300058	11/21/1994
Responds to request to determine if any international stds regulating disposal of naturally-occurring radioactivity in relation to Shieldalloy Metallurgical Corp application to export CANAL exist.	9505180534	5/11/1995
Confirms 930809 telcon re resignation of RSO, C Rieman, effective 930813. Alternate RSO, JP Valenti will temporarily assume RSO responsibilities. Search for permanent RSO already begun. NRC will be notified when search complete.	9308200292	8/12/1993
"Work Plan for Radiological Characterization of Shieldalloy Metallurgical Corp Newfield Facility."	9007120175	6/30/1990
Forwards AEC License SMB-743 as renewed. Advises that per 10CFR20.103(c)(1), allowance may not be made for use of protective equipment in determining exposure of individuals to airborne radioactivity w/o AEC approval.	9002060402	2/1/1965

Forwards insp rept 40-7102/95-01 on 950215-17,0306 & 0918, CAL 1-95-04 closure & NOV.	9512120019	11/30/1995
Forwards Ledoux rept re solubility of slags produced in aluminothermic smelting of Araxa pyrochlore concentrates & ltr from Ledoux & Co outlining procedures used in analyses.	9002060406	2/25/1965
Ack receipt of 791116 ltr w/addl info re renewal of Mat/ Byproduct License SMB-743.Requests submittal of plans for waste disposal,as originally requested in NRC 791023 ltr. Review will continue upon receipt of info.	8004290249	4/4/1980
Comment re decommissioning of Shieldalloy Metallurgical Corp facility.Comments on concerns of citizens w/respect to health & safety re use & storage of materials at facility. Questions whether appropriate health/safety studies done.	9402030003	1/20/1994
Ack receipt of T McGinty site investigation rept & N Stanley site visit memo for 930217-18 site visit to Shieldalloy Metallurgical Corp.Based on listed info,NRC does not consider licensee to be out of exposure limits.	9305110319	5/4/1993
Forwards draft copy of RSP-010, "Exposure Control Newfield Facility" assessing control of radiation exposure procedures.SMC requests NRC review & approval of biassay monitoring program to determine internal exposure levels.	9609240323	9/4/1996
Responds to 961003 ltr re Shieldalloy Metallurgical Corp, Cambridge,OH,facility decommissioning.	9611130122	11/6/1996
Notice of expiration of License SMB-743 on 730131.Advises to submit renewal application,using Form AEC-2,30 days before expiration date of license.	9002070194	12/20/1972
Forwards 961217 ltr to CS Eves from GC Comfort dtd 961217 for NRC info re bioassay testing for employee at Shieldalloy.	9701240231	1/8/1997
Application for amend to license SMB-1507,allowing for receipt & placement of off-site slag/soil from temporary staging area onsite to West Slag Pile as described in encl Environ Rept.	9810220329	9/14/1998
Amend 9 to license SMB-743,revising conditions 10 & 12 re radiation protection program & authorized users, respectively.	9307290270	7/22/1993
Responds to 961102 statement requesting Newfield Facility license for handling radioactive matls not be renewed.	9701020031	12/24/1996
Forwards responses to concerns raised re Shieldalloy Metallurgical Corp & Cyprus Foote Mineral Co activities in Cambridge,OH area.Requests that future info requests or concerns be directed to J Kennedy at NRC Rockville,MD.	9603220097	1/18/1996

Forwards Oak Ridge Associated Univs rept re analyses of soil samples for non-radiological components performed as part of survey of Shieldalloy Corp.	8902170144	2/9/1989
Part 2 of application for renewal of License SMB-743 for Shieldalloy Newfield Facility.	8807290073	7/31/1988
Acks speech w/townspeople of Newfield & Vineland re environmental situation at Newfield,NJ.	9602290207	2/9/1996
Comment opposing proposed decommissioning of Shieldalloy facility.	9401260270	12/29/1993
Discusses Safety Insp 40-7102/87-01 on 871019.No violations noted.	8801120082	12/28/1987
Forwards Amend 8 to License SMB-743 & safety evaluation. Amend authorizes increase in possession & storage onsite of source matl (thorium & U) & reflects change of name.	9204070073	4/2/1992
Application for renewal of license SMB-743 for Shieldalloy, Newfield facility.	9304140254	4/7/1993
"Radiation Protection Program Plan."	9712030267	11/24/1997
Forwards comments for consideration in response to TAR of 960216,which requested review of Shieldalloy Metallurgical Corp (Newfield) Conceptual Decommissioning Plan.	9607020200	6/24/1996
Requests addl time to respond to NRC RAI re SER for license renewal application.	9508020205	7/21/1995
Forwards responses to questions identified by ORNL on summary repts for EIS scoping process initiated for repts Shieldalloy Metallurgical Corporation s (Shieldalloy s) facilities in Newfield,NJ & Cambridge,OH.	9403310249	3/25/1994
Requests response to 910608 ltr expressing concerns & requesting clarification on issues re possession,handling & sale of 55,920 pounds of FeSiZr by Shieldalloy Metallurgical Corp.	9108210142	8/7/1991
Advises that Shieldalloy Metallurgical Corp has file bankruptcy proceedings under Chapter 11.	9410240136	9/23/1994
Ack receipt of 900503 request for addl technical support & info re proposal to utilize ferrovanadium slag for shielding & circumscribing source matl storage yard.Slag will be used for decommissioning columbium slag pile.	9005170246	5/14/1990
Forwards Shieldalloy Metallurgical Corp responses to Mazaika 930305 environ questions.Requests that finished product be delivered by 930930.W/o encl.	9307190168	7/13/1993
Forwards Insp Rept 40-7102/90-01 on 900502-03 & notice of violation.	9009100245	8/24/1990
Amend 3 to License SMB-0743 for Shieldalloy Corp,adding Condition 10 to exempt licensee from requirements of 10CFR20.203(e)(2) & 20.203(f)(2).	9002050273	12/27/1965

Informs that effective 961118,MF Weber will be Branch Chief for Fuel Cycle Licensing Branch & GC Pangburn will be Section Chief for Licensing Section 2.Addresses for future correspondence & phone numbers,listed.	9612160285	12/10/1996
Forwards addl info requested re license application packages dtd 971125,980325 & 990325.Revised pages reflecting required changes can be submitted as single page changes.	9904290189	4/22/1999
Forwards "Groundwater Investigation" of Cambridge,OH facility dtd Apr 1987.	9105280187	5/13/1991
Forwards draft radiation safety procedures to assist in evaluating Shieldalloy Metallurgical Corp revised license renewal application submitted to NRC on 950915.Procedures will not be finalized until renewed license issued.	9512050081	11/28/1995
"Internal Radiation Exposure Control."	9501040021	3/11/1994
Forwards revised document, "Radiological Impacts from Use of CANAL - Slag Fluidizer in Steel Production," for use per request.	9505120110	4/20/1995
Requests info from fuel cycle licensees on future plans as to any new licensing actions through Sept 30,2002.Info should be provided to NRC Project Manager by 990129.	9901290091	1/14/1999
"Comparison of NRC Decommissioning Process w/Ohio EPA Remediation Process."	9509130198	4/3/1995
Comment supporting Shieldalloy Metallurgical Corp continuing to provide jobs & tax revenue for community.	9402030004	1/12/1994
Discusses vendor intent to transfer ferrovanadium slag to steel industry to be used to improve fluid characteristics, per 911122 telcon.Vendor should perform radiological survey of outgoing ferrovanadium slag.	9112030003	11/27/1991
Informs that 950511 memo found conclusions of "Radiological Impacts From use of CANAL - Slag Fluidizer in Steel Production," to be acceptable.	9506210166	6/16/1995
Forwards draft guidance to assist in preparation of application for renewal of License SMB-743.Final decontamination/decommissioning plans & environ info should be included in renewal application.W/o encl.	8504170561	4/5/1985
Provides items of interest,including summary of 861203 & 04 meetings w/Shieldalloy Corp,update of NUREG/CR-1620 & status of hearings on Sequoyah Fuels.	8612170108	12/10/1986
Reaffirms licensee desire to participate in NRC responsibility to renew License SMB-743.Proposed facility radiological survey plan from Oak Ridge Associated Univs dtd 870730 more extensive than necessary.	8712140450	10/15/1987

Summarizes 950524 meeting w/Shieldalloy re application to export CANAL slag from Newfield,NJ facility & to discuss NRC 950511 memo on subject.	9506150128	6/5/1995
Submits responses to comments & questions as listed in 940112 ltr,received by Shieldalloy Metallurgical Corp on 940114 re environ assessment.List of 19 proposed SOPs & various analytical results of baghouse dust & slag encl.	9402080303	1/28/1994
Amend 10 to license SMB-743 for Shieldalloy Metallurgical Corp.	9409290237	9/23/1994
Forwards copy of environ assessment for Shieldalloy Metallurgical Corp in Newfield,NJ.FONSI published in FR on 970922,encl.NRC is currently completing SER,which evaluates Shieldalloy operational & safety programs.	9711140239	10/28/1997
Notice of violation from insp on 900502-03.Violations noted: licensee possessed more than 150,000 kg of thorium & 17,000 kg U & radiation survey instruments not calibr every 7 months.	9009100246	8/24/1990
FENCE LINE GAMMA EXPOSURE RATES.	9204290374	3/4/1992
First partial response to FOIA request for documents.App A records available in PDR.Records in App B encl & being made available for PDR.App C partially withheld & App D completely withheld (ref FOIA exemptions 4 & 6).	9509130178	4/3/1995
"Notice of Appearance,Request for Service of Papers & Reservation of Rights."	9309240298	9/14/1993
Notifies that ltr & rept, "TRC Ground Water & Surface Water Monitoring Program," dtd 940726 need no longer be considered confidential.Rept still considered draft & has not been finalized.	9504100185	3/28/1995
Informs that NRC will carefully consider comment & respond to comments through scoping rept that will be issued in Apr 1994 re Shiedalloy site in Newfield,NJ.Copy of scoping rept will be mailed to individuals submitting comments.	9402220183	2/11/1994
Revised summary of 921118 meeting w/licensee in Rockville,MD re content of license renewal/amend application submitted in June 1992,source matl possession limits & conceptual decommissioning plan.	9302100098	2/3/1993
Informs NRC that licensee has not received info requested in FOIA.Request was made to NRC on 940721.	9509150088	8/31/1994
SER accepting amend 2 to license SMB-743 for Shieldalloy Metallurgical Corp.	9909010004	8/27/1999

Forwards licensee 940818 response to NRC RAI, in conjunction w/BPNL review of environ assessment for Shieldalloy Metallurgical Corp. Attachments J & L will be provided under separate cover. W/o encl.	9409070118	8/29/1994
Forwards environ assessment & FONSI prepared to support renewal of source matl License SMB-743. FONSI forwarded to Ofc of FR for publication.	9709290241	9/16/1997
Forwards finding of no significant impact & notice of opportunity for hearing on 920213 & 871127 requests for amend to License SMB-743. Amend would authorize increase in possession & storage onsite of source matl.	9203260258	3/25/1992
Discusses Allegation RI-85-A-0002 involving concerns of unknown allegor re licensee activities that caused tree deaths & increase in cancer cases in local area. Concerns not substantiated during 850402 insp. Unrelated violations noted.	9002060238	1/2/1986
"QA in Radiological Protection."	9501040004	3/11/1994
"Ferrocolumbium Slag Leachability Rept, Dec 1991 for Shieldalloy Metallurgical Corp, Newfield, NJ."	9201020236	12/16/1991
Discusses offsite agency comments on licensees emergency plan changes. Licensees required to provide offsite response organizations w/copy of emergency plan changes within 6 months after changes made.	9210160067	10/7/1992
Forwards insp rept 40-7102/98-01 on 980727-28. Seven apparent violations identified & being considered for escalated enforcement. No NOV presently being issued for these insp findings. Partially deleted "Annual Whole Body Exposure Rept for CY87."	9809090078	8/27/1998
Informs that NMSS would like to meet w/Bob early next week to discuss status of EIS & need for Shieldalloy to provide addl info.	9002070448	12/31/1987
Notice of violation from insp on 800926. Noncompliance noted: unauthorized personnel supervised use of licensed matl & air sample surveys in blending & furnace areas of Bldg 3 not performed.	9508290268	12/13/1994
Forwards Rev 1.0 to "Std Operating Procedure for U in Urine."	8012190690	10/15/1980
Forwards "Radiological Survey of Shieldalloy Corp, Newfield, NJ," by Oak Ridge Associated Univs, per 880614 ltr.	9703260318	3/11/1997
"Shieldalloy Metallurgical Corp, Cambridge, OH West Pile Decommissioning Plan Supporting Design Calculations & Recommendations in Ref to NRC Comments." W/one oversize drawing.	8809130068	9/6/1988
Rev 0 to Procedure RSP-001, "Radiation Protection Program Plan (Newfield Facility)."	9109230089	2/28/1991
	9510250245	10/6/1995

Ack receipt of AEC 650630 ltr & AEC-592. Informs that licensee applied for amend to License SMB-743, authorizing possession of Nigerian & Norwegian ores & surplus quantity baddeleyite. Slag storage drums labeled as required.	9002070283	7/6/1965
Discusses 941013 memo re possible new issues received from NMSS re Shieldalloy Metallurgical Co.	9509180021	10/26/1994
Discusses insp rept 40-7102/95-01 on 950215-17. Violations noted. Safety concerns & apparent violations had been noted re failure to perform survey determine compliance w/occupational dose limits.	9505050009	4/27/1995
Ack receipt of 971125 license application package containing revised program description to replace draft radiation safety procedures contained in current license. Document is being reviewed & estimated completion date is 980227.	9712150229	12/4/1997
"Training in Radiation Protection."	9501040001	3/10/1994
Informs of 951206 meeting at 7 p.m. at St Rose of Lima Church in Newfield, NJ.	9511300001	11/15/1995
Forwards "Groundwater & Surface Water Monitoring Program for Shieldalloy Metallurgical Corp, Cambridge, OH Facility," developed by RMT, Inc. W/o encl.	9206120222	5/29/1992
Discusses NRC 910614 ltr re leachability testing of slag stored in source matl storage yard. Four samples of ferrocolumbium taken on 910712. Analytical results to be available by end of Nov 1991.	9108210148	8/12/1991
Forwards renewed license SMB-743 & SER, IAW application dtd 950915 & suppls dtd 951128 & 0811,0924 & 970926.	9907160202	10/20/1997
Requests addl info re 771223 application for renewal of License SMB-743. Info needed re final product produced by licensee, ultimate use of each product & results of analysis of amounts of thorium &/or U in final products.	7906190586	5/7/1979
Forwards Irrevocable Standby Ltr of Credit 839-51288, dtd 900718 & standby trust agreement, providing financial assurance for decommissioning for Shieldalloy Metallurgical Corp.	9007270200	7/23/1990
Application for renewal of License SMB-0743, authorizing use of unlimited quantities of metaliferous ores containing 0.4% U & 2% thorium for ore processing.	9002050426	1/12/1973
Discusses ferrovanadium slag issues raised by State of NJ Dept of Environ Protection & Energy. Rigorous testing, sampling & recording procedures will ensure that slag leaving Newfield Site will not contain contamination.	9201080256	1/7/1992

Forwards some quarterly groundwater monitoring results for radiochemical parameters submitted by Shieldalloy Metallurgical Corp in accordance w/Administrative Consent Order dtd 881005,per telcon in Dec 1992.

9301270097 1/21/1993

Provides list of documents dated from 1980 to early 1994 reviewing in situ disposal at Shieldalloy metallurgical facility.

9404080015 4/4/1994

Undated comment re decommissioning of Shieldalloy Metallurgical Corp located in Newfield,NJ.Lists questions re issue.

9401240331 1/19/1994

Offers listed comments based on review of NRC 940406 draft scoping process summary rept for EIS on decommissioning of Shieldalloy Metallurgical Corp plant in Newfield,NJ.

9406290278 6/22/1994

Requests that M Weber & all recipients of ltr substitute encl authorized uses of licensed matls for earlier ltr dtd 990310,which contained typo.

9904020238 3/18/1999

Forwards SECY-96-210,dtd 961001 which closed actions associated w/Conceptual Decommissioning Plan,dtd 951212. Project manager responsibility has changed for facility, effective 970709.

9707160094 7/9/1997

"Applicants Environ Rept for Newfield,NJ Facility."

9211030188 10/28/1992

"Radiation Protection Records."

9501040011 3/10/1994

Suppl application for amend to license SMB-743,requesting to remove one facility from listing of permanent restricted areas.

9902100258 1/28/1999

"Memo of Law in Support of Motion of Debtors Per Section 1121(d) of Bankruptcy Code to Extend Debtors Exclusive Periods in Which to File Plan or Plans of Reorganization & Disclosure Statement & Solicit Acceptance."

9405020204 12/9/1993

Environ assessment for renewal of source matl license SMB-743.

9709290257 9/30/1997

"Project Status & Schedules Environ Programs."

9507070451 6/14/1995

Transcript of 931216 public meeting in Franklinville,NJ re scope of EIS on Shieldalloy Metallurgical Corp facility in Newfield,NJ.Pp 1-105.Background info on radioactive matl & radiation encl.

9401070139 12/16/1993

"Rept on Surface Water Contamination Study for Shieldalloy Corp Newfield,NJ." W/ten oversize encls.

9409150005 3/10/1975

Notice of Appearance & Request for Notices & Svc of Papers.

9408290391 8/16/1994

Order fixing time date & place limiting notice of hearing on motion of debtors for entry of order per Sections 363(b) & 105(a) of Bankruptcy Code authorizing payment of certain pre-petition obligations to US Customs Svc.

9310280161 10/18/1993

Forwards financial assurance info per 920110 telcon, consisting of administrative consent order dtd 881005, irrevocable standby ltr of credit, trust agreement & amend to irrevocable standby ltr of credit.	9202190200	2/3/1992
Informs that NRC will carefully consider comment & respond to comments through scoping rept that will be issued in Apr 1994 re Shiedalloy site in Newfield,NJ.Copy of scoping rept will be mailed to individuals submitting comments.	9402220183	2/11/1994
Forwards insp rept 40-7102/97-01 on 970520-21.No violations noted.Two violations identified in insp rept 40-7102/93-01 remain open.Review of these items further during insp following renewal of license.	9710140036	9/24/1997
Provides results of survey of underground tanks at licensed facilities,in response to request.	8602210046	2/13/1986
Responds to NRC 861211 request for info.Further response will be submitted within 2 months.Response delayed due to preparation of environ assessment for proposed purchase of Ohio plant.Oversize facility map encl.	8706260382	4/22/1987
Provides addl info re renewal of License SMB-0743,per 791023 request.	9002060182	11/16/1979
Responds to 940623 ltr to DK Rathbun,requesting that NRC review concerns raised by residents living near Shieldalloy Metallurgical Corp facility in Newfield,NJ.	9408040148	7/22/1994
Informs that 770301 due date for rept of WL Silvernail re study of licensee radiation safety program will be missed by few days.Final rept will be forwarded upon receipt from consultant for NRC review.	9002060047	2/24/1977
Ack receipt of 650405 ltr & amend to AEC License SMB-743. Based on situations discussed,requests further amend to license as indicated.	9002060415	5/25/1965
Requests that Shieldalloy Metallurgical Corp issuer of current instrument,begin to prepare modified financial assurance instrument with changes described.	9908240046	8/12/1999
Informs that informal public meeting should be held in early December in Newfield area to discuss status of EIS & delays that have occurred due to limited availability of info.	9508290228	10/31/1994
Notice of expiration of License SMB-743 on 680131.Advises that application should be submitted using Form AEC-2 at least 30 days prior to expiration date.	9002070145	11/28/1967
Safety evaluation approving application for revision to possession limits & radiation protection program.	9409290249	9/23/1994
Submits response to 961217 RAI re bioassay testing program for employees.	9701300014	1/14/1997

Forwards draft guide for preparation of license renewal applications for processors of source matl for elements U & thorium.	9111250142	11/12/1991
Forwards comments on work plan for radiological characterization of Shieldalloy Metallurgical Corp. Level of detail in work plan found to be insufficient to adequately describe characterization methodologies to be used.	9010020230	9/24/1990
Forwards info notice re revs in 10CFR20, "Stds for Radiation Protection" issued on 930105 for review & applicability to operations. W/o encl.	9305170006	5/12/1993
Trip rept of 871117 visit to site in Cambridge, OH to discuss decontamination & decommissioning activities.	8712030017	11/24/1987
Forwards response to NRC questions re adjustments to derived air concentration for airborne thorium & U activity at facility.	9510240375	9/22/1995
Press release re Metallurg, Inc filing for court protection in order to complete operational & financial reorganization.	9309090318	9/7/1993
Responds to 940503 telcon inquiry re status of NRC plans to establish LPDR near Shieldalloy Metallurgical Corp Cambridge, OH facility.	9405260175	5/9/1994
"Environ Evaluation Shieldalloy Metallurgical Corp Newfield, NJ."	9411230174	4/30/1994
Ack receipt of 801030 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 40-7102/80-01.	8012190678	11/20/1980
Informs NRC that as of 970714, undersigned is no longer RSO nor contact individual for Shieldalloy Metallurgical Corp facility in Newfield, NJ.	9708290178	8/9/1997
Application for renewal to License SMB-743, authorizing use of 15 tons baddeleyite containing 0.35% U & unlimited quantities of pyrochlore concentrate containing 0.03-0.07% U & 1.2-2.0% thorium as oxides.	9002070150	12/22/1967
Ack receipt of 880809 ltr & radiological survey rept by Oak Ridge Associated Univs (ORAU). Rept data will be used as basis of cleanup program to be implemented at Newfield site. Details of cleanup procedures to be discussed w/ORAU.	9002060280	8/26/1988
"Control of Radiological Work."	9501040003	3/11/1994
Draft Rev 0 to Radiation Safety Procedure RSP-016, "Emergency Response & Notifications - Newfield Facility."	9512050122	11/21/1995
Responds to NRC 761015 ltr re violations noted in insp on 761006. Corrective actions taken: Parts 19 & 20 of License SMB-0743 & Form NRC 3 posted in certain places per 10CFR19.11 & complied w/requirements re restricted areas.	9002050440	11/11/1976
"Environ Surveillance."	9501040020	3/10/1994

<p>Trip rept of 871019 visit w/Region I to licensee facility at Newfield,NJ re license renewal process & insp.</p>	8711230138	11/18/1987
<p>Describes methodology used during production of batch of Canal-Lite that was staged & shipped to NUCOR-Hickman facility in Blytheville,Arkansas.</p>	9805270188	5/13/1998
<p>Trip rept of 930217-19 visit to Newfield,NJ re observation of licensees processes & discussions on info necessary to develop an EA in response to license renewal request.List of attendees encl.</p>	9304260246	4/21/1993
<p>Informs that RD Way will be leaving employment of Shieldalloy Metallurgical Corp,effective 940101.Role in radiation protection program will be transferred to RL Swenson.</p>	9401110115	12/20/1993
<p>Draft Rev 0 to Radiation Safety Procedure RSP-007, "Training in Radiation Protection - Newfield Facility."</p>	9512050094	11/21/1995
<p>Ack receipt of 880715 ltr re application of renewal of License SMB-743.NRC recently amended 10CFR40 which applies to such applications,effective 880727.Application being returned for compliance w/amend.Guidance encl.W/o encl.</p>	8808010109	7/21/1988
<p>Submits clip-offs from Oct 1996 newsletter petitioning NRC not to renew Shieldalloy Corps license for handling radioactive matls until decommissioning plan is in place.</p>	9612230156	12/12/1996
<p>Requests that issues re bioassay program be placed "on hold" until amend 1 has been issued.Shieldalloy will address issues stated in 980128 ltr at later date.</p>	9803120005	3/6/1998
<p>Informs that proposed transfer of buttons back to Shieldalloy Metallurgical Corp,acceptable per 940805 ltr re slag buttons containing source matl currently located in Cambridge,OH.</p>	9408250057	8/22/1994
<p>Refers to 990813 ltr for docket 7007102,responding to NRC concern on potential contamination found north of Shieldalloy Metallurgical Corp property boundary.NRC suggests that issue be resolved as soon as possible.</p>	9910220177	10/15/1999
<p>Responds to 940524 ltr re prohibition on removal of assets covered in license & reasserted position that NPA is ready for release for unrestricted use.</p>	9407080060	6/21/1994
<p>Amend 3 to License SMB-743 for Shieldalloy Corp,authorizing use of unlimited quantities of metaliferous ore containing 2% U & 4% thorium.</p>	9002070041	9/21/1965

Final response to FOIA request for documents.App A,B & C records encl & also available in PDR.App D records available in PDR.App E documents partially withheld (ref FOIA Exemptions 4 & 6).	9002050102	1/23/1990
Notifies that License SMB-743 expires on 641231 & advises that application for license renewal be filed 30 days before expiration date if licensee wishes to renew license.	9002060365	11/19/1964
Draft Rev 0 to Radiation Safety Procedure RSP-009, "Contamination Control - Newfield Facility."	9512050112	9/19/1995
Advises that NRC anticipates commencement of technical review of license renewal application,dtd 880718,upon receipt of site-wide characterization rept.Requests revised application or change pages be submitted.	9203240378	3/19/1992
Amend 1 to license SMB-0743 for Shieldalloy Metallurgical Corp.	9907230301	7/20/1999
Requests permission to accelerate quarterly monitoring requirement for licensee Newfield facility.	9506190187	6/7/1995
FOIA request for documents re preparation of environmental impact statements for Shieldalloy Metallurgical.	9508180105	12/16/1994
Forwards NRC latest rept on Site Decommissioning Mgt Plan & rept prepared by Shieldalloy Metallurgical Corp entitled, "Ferrocolumbium Slag Leachability Rept," in response to 920706 telcon.W/o encl.	9207100372	7/8/1992
Advises that Shieldalloy contacted & informed of approval of extension until 880405 for submittal of responses re renewal application,per licensee 880225 request.	8803300055	3/23/1987
Amend 2 to license SMB-743 for Shieldalloy Metallurgical Corp.	9909010003	8/27/1999
Amend 1 to License SMB-0743 for Shieldalloy Corp,authorizing use of 125,000 lb Brazilian pyrochlore containing 0.07% U & 2.0% thorium for production of ferro columbium & columbium nickel.	9002050247	2/1/1965
Undated comment supporting carting 1.2 million cubic yards of radwaste at Shieldalloy plant off site.	9401260135	1/12/1994
Forwards documents containing data that will be useful in preparing Enviornmental Assessment document,in response to Shieldalloy Metallurgical Corp application to renew source matl license.W/o encl.	9211090042	11/4/1992
Submits list of commitments re development & implementation of written procedures on free-release of equipment & soils from licensee Newfield,NJ facility.	9809170236	7/31/1998

Application for amend to license SMB-743,allowing possession & storage of matls containing U & Th when not used for production,but instead sold as tradeable commodity.	9703280333	3/6/1997
Discusses info on telcon re request for establishment of local public document room near Cambridge,OH & Newfield,NJ.	9403080034	2/24/1994
Requests to extend license to include 100,000 lb columbium bearing pyrochlore ore,per understanding of discussion during 640812 telcon between WB Clymer & DA Nussbaumer that such license extension possible.	9002060349	8/12/1964
Forwards copy of ltr sent to NRC re opinion about radioactive slag piles at Shieldally in Newfield,NJ.	9402220192	1/11/1994
Summarizes 880518 meeting re review of responses to NRC questions concerning permit conditions.Requests confirmation of agreement to submit responses by end of June 1988.	8806230325	6/3/1988
Advises that due to extensive nature of questions requiring addl studies,responses to 861211 request for addl info re renewal of License SMB-743 will be submitted by 870320.	8703180509	2/19/1987
Proposes listed method for reducing radwaste w/regard to Shieldalloy,Newfield,NJ facility.	9402030017	1/6/1994
Requests NRC approval of extension until 880405 to allow submission of more integrated & complete response to questions posed in 880105 ltr.	8803080283	3/2/1988
"EIS Scoping Summary Rept."	9509130193	3/31/1994
Forwards "Radiological Survey of Shieldalloy Corp,Newfield, NJ" in response to 880908 ltr.Amends 6 & 7 to License SMB-743 & documents incorporated by ref in license also encl.Encl license remains in effect after expiration date.	9002060284	10/13/1988
Notice of violation from insp on 761006.Violation noted: failure to make surveys necessary to determine that extent of exposure of persons handling significant quantities of U & thorium bearing ore & to assure compliance w/10CFR20.106.	9002050434	10/15/1976
Forwards insp rept 40-7102/93-01 on 931202-03 & notice of violation.	9402220088	1/31/1994
Informs that licensee no longer intends to replace Deutsche Bank ltr of credit at this time.Deutsche Bank ltr of credit, provided to NRC on 900723,remains in effect as decommissioning surety for Newfield & Cambridge facilities.	9305260505	5/10/1993

Notice of violation from insp on 771213. Violation noted: failure to evaluate concentration of thorium released to unrestricted area in air leaving filter house, per 10CFR20.106.

9002060079 1/3/1978

Forwards T McGinty site investigation rept & N Stanley site visit memo for site visit to licensee on 930217-18. Site map, indicating gamma exposure rate measurements made during site visit, also encl.

9303250113 3/4/1993

"Environ Rept for Proposed Action to Relocate Off-Site Slag/Soil at Shieldally Metallurgical Corp Plant in Cambridge, OH."

9810220333 7/24/1998

Inquires if now is time to try approach of using PAWG in start up mode re meeting on Shieldalloy.

9508290267 12/12/1994

Informs that NRC received anonymous call from concerned individual re 600,000 tons of low grade radioactive & chemical waste located near factory called Shieldalloy Metallurgical Corp.

9509150049 8/18/1994

Third final response to FOIA request for documents. App G records available in PDR. Records in App H will be withheld in part (ref Exemptions 4 & 6).

9508280393 5/5/1995

Requests for documents re Shieldalloy Corp, including existing NRC permit, new permit & date permit issued, environ survey rept & application of licenses document, incorporated by ref.

9002060308 9/8/1988

"Packaging & Transportation of Radioactive Matls."

9501040019 3/10/1994

Forwards amend 2 to license SMB-743, including revised radiation protection program plan. License condition 10 is modified to include dates of 971125, 980325 & 990601 & license condition 11 is deleted. SER accepting amend, encl.

9909010002 8/27/1999

Second partial response to FOIA request for documents. Forwards documents listed in App E. Documents also available in PDR. App F documents totally withheld (ref FOIA Exemption 5).

9508180109 4/10/1995

Comment opposing Shieldalloy Corp being permitted to dispose of nuclear waste at facility in Newfield, NJ.

9503070091 2/24/1995

Ack receipt of 790628 application for renewal of Matl/ Byproduct License SMB-743. Requests addl info re amount of thorium & U contained in slag & other wastes stored in slag dump & calibr procedures for radiation survey meters.

7911300323 10/23/1979

Forwards gross alpha & gross beta activities for water samples from Shieldalloy site in NJ, results show no appreciable activity.

9402150405 2/2/1994

Comment on stabilization & disposal of slag piles onsite at Shieldalloy. Advises of shipment of radioactive slag to nuclear disposal wastesite in Utah.	9401260096	12/29/1993
SER accepting amend 9 to license SMB-743.	9307290276	7/21/1993
Comment urging Shieldalloy Corp to follow NRC policy of transporting slag to federally approved facilities.	9401260108	1/5/1994
Inquires if someone could challenge increase in possession limits on ground of segmentation under NEPA, given that NRC in midst of developing EIS for waste disposal at Sheildalloy-Newfield site.	9508290227	8/31/1994
Requests copies of permits granted by federal, state or local agencies that allow routine releases of radioactivity to environment & related analyses. Requests that rev to 920602 SNM renewal & amend application be submitted also.	9212230250	12/15/1992
Comment supporting carting 1.2 million cubic yards of radwaste at Shieldalloy plant off site.	9401260147	1/8/1994
Notification of 950524 meeting w/ Shieldalloy Metallurgical Corp in Rockville, MD to discuss NRC comments re Shieldalloy submitted document, "Radiological Impacts From Use of CANAL."	9506020032	5/23/1995
Transcript of 940104 town meeting in Gloucester County, NJ re Shieldalloy filing for bankruptcy under chapter 11. Pp 1-52.	9401270126	1/4/1994
Forwards application for license, per 850509 telcon. Instructions provided for renewal of application for License SMB-743. W/o encl.	8505240563	5/14/1985
Submits info re physical characteristics of slag & baghouse dust product in Dept 111 & summary of procedure followed for initial 6,000 ton lot which has been screened & crushed, per 920106 telcon w/NRC.	9201230079	1/13/1992
Summary of 950620 meeting w/ Shieldalloy Metallurgical Corp Cyprus Foote Mineral Corp in Rockville, MD re development of EIS for Cambridge, OH & Newfield, NJ facilities.	9507270310	6/28/1995
Forwards "Ferrochromium Slag Leachability Rept, Dec 1991 for Shieldalloy Metallurgical Corp, Newfield, NJ," to support request to increase source matl possession limit.	9201020235	12/26/1991
Provides comments on revised program submitted on 971125, to be incorporated into application. New complete license application should be resubmitted within 30 days.	9803050185	2/19/1998
Forwards "Ferrochromium Slag Leachability Rept Jan 1992 for Shieldalloy Metallurgical Corp."	9411090399	10/31/1994

Director s Decision DD-97-10,granting in part & denying in part request that NRC modify Shieldalloy Metallurgical Corp license to allow only possession of radioactive matl for express purpose of decommissioning & decontaminating.

9705010035 4/15/1997

Requests that NRC or NRC proposed contractor prepare & submit for review & approval,detailed budget for EIS to be prepared for sites & that any invoice on project include detailed breakdown of work performed.

9403020101 2/21/1994

"External Radiation Exposure Control."

9501040017 3/11/1994

Informs that WJ Hughes will greatly appreciate ofc careful review of addl ltrs & make reasonable effort to ensure that constituents comments & suggestions receive appropriate consideration.

9402220188 1/14/1994

Informs that NRC currently evaluating comments on proposed scope of NRC review,from constituent & other concerned individuals & organizations re licensee proposed in situ disposal of contaminated matl,in response to 940107 ltr.

9402150365 2/3/1994

Submits status of action items contained in 980731 ltr re procedure for free-release of equipment & soils from Shieldalloy Metallurgical Corp,Newfield,NJ facility.

9809170212 8/21/1998

Forwards Rept IT/NS-92-116, "Baseline Radiological Risk Assessment for Hudson Branch Watershed," per request.

9708210243 8/11/1997

"Emergency Response & Notifications."

9501040010 3/10/1994

"Baseline Radiological Risk Assessment for Hudson Branch Watershed."

9307080200 11/3/1992

Forwards environ info outline,per 850805 request.

8604220502 3/10/1986

Advises that Div of Industrial & Medical Nuclear Safety sponsoring Fuel Cycle Licensee Workshop on 920915-17 in Bethesda,MD.Preliminary agenda encl.W/o agenda.

9208120143 8/10/1992

Forwards application for renewal of License SMB-743.Fee paid.

8508020275 6/19/1985

Provides supplemental info to 950825 license renewal application for SMB-743.

9710020008 9/26/1997

Requests approval of form of proposed ltr of credit from Natl Westminster Bank & written consent to cancel Deutsche Bank ltr of credit prior to current expiration date.Draft irrevocable standby ltr of credit encl.

9208190010 8/6/1992

Forwards addl info needed for preparation of EA & draft annotated outline of EA for license renewal of Newfield,NJ facility.Staff from NRC & Battelle Pacific Northwest Lab will be visiting site on 930217.

9301220168 1/14/1993

Discusses 950314 & 0515 ltrs which indicated that plan to adjust Derived Air Condition for airborne Th & U activity at plant.	9509250328	9/8/1995
Responds to NRC 941123 ltr re violations noted in insp rept 40-07102/93-01. Corrective actions: SMC agrees to initiate sampling program for measuring effluent from Dept 111 stacks in order to satisfy requirements of open item.	9502030266	12/16/1994
"Ferrochromium Slag Leachability Rept for Jan 1992 for Shieldalloy Metallurgical Corp."	9411090403	1/31/1992
Informs of voluntary petition filed for protection from creditors in US Bankruptcy Court for Southern District of NY under Chapter 11 of US Bankruptcy Code. W/press release encl.	9309090312	9/7/1993
Comment on proposed EIS re 931216 public scope meeting decommissioning of Shieldalloy Metallurgical Corp facility in Newfield, NJ. Listed requests & questions should be considered during meeting.	9401250031	1/12/1994
Forwards revised attachments to 920602 application for renewal of License SMB-743, in response to 921215 ltr. Proposed listed license conditions for License SMB-743, per NRC 921215 ltr also encl.	9302220442	2/10/1993
Requests to secure authorization to possess 15 tons baddeleyite & to smelt matl in test series w/simultaneous survey of airborne pollution. Results of analyses of baddeleyite provided.	9002060408	3/4/1965
Informs that twenty soil samples analyzed by combination of X-ray fluorescence & neutron activation. Results encl.	8902170135	1/30/1989
Submits that survey results cited in NRC 990121 & 0714 ltrs do not support conclusion that licensed matls migrated outside fence at levels above site-specific release criteria.	9908230201	8/13/1999
Requests consent re 880919 visit w/JD Berger to obtain informal technical input to radiological survey outline.	8809200241	9/8/1988
Informs that Agency for Toxic Substances & Disease Registry completed radiological review of "Slag Pile" conditions located on Shieldalloy Metallurgical Corp site, Newfield, Gloucester County, NJ.	9407290273	7/22/1994
Discusses facilitating communications w/NRC & role of Project Manager in facilities.	9801230009	1/14/1998
"TYPICAL SECTIONS SHIELD ALLOY - WEST RICE CAMBRIDGE, OHIO."	9002090209	9/5/1989
Responds to 940203 ltr to Chairman Selin requesting NRC review concerns of Mayor Marshall of Borough of Newfield re health effects from Shieldalloy Metallurgical Corp facility. NRC presently developing updated EA & SE.	9403170076	3/7/1994

Comment expressing concerns re decommissioning of Shieldalloy Metallurgical Corp facility in Newfield,NJ.	9401260114	1/6/1994
Forwards listed supplemental info re Newfield EIS for Shieldalloy Metallurgical Corp License SMB-743.	9411230168	10/31/1994
Responds to 911125 ltr re ferrovanadium slag at Shieldalloy Metallurgical Co Newfield,NJ site.Confirms 911125 telecon re proposal to sell slug additive to steel production slag.	9112050181	12/3/1991
Requests technical assistance in reviewing Shieldalloy Metallurgical Corp Conceptual Decommissioning Plan.	9603060029	2/16/1996
Forwards four samples of slag collected from Shieldalloy site in Cambridge,OH,per 880203 telcon.Analyses for Th-232, Ra-226 & U-238 requested.W/o encl.	8803010158	2/3/1988
Undated comment re decommissioning of Shieldalloy Metallurgical Corp located in Newfield,NJ.Lists questions re issue.	9401240335	1/19/1994
Recommends that OH & NRC jointly review CFM program for off-site properties w/expectation that OH would take lead role in ensuring effective remediation of off-site properties.	9701080192	12/11/1996
"Notice of Proposed Order Authorizing NUNC PRO TUNC Retention of Segal Co as Actuarial Consultant to Official Committee of Unsecured Creditors of Metallurg,Inc & Shieldalloy Metallurgical Corp."	9506190162	5/30/1995
Forwards Oak Ridge Associated Univs rept, "Radiological Survey of Shieldalloy Corp,Newfield,NJ."	8808180057	8/9/1988
Advises that MR Morgenstern of Shieldalloy informed that NRC approval to install four addl monitoring wells not required.MR Morgenstern informed by telcon on 880817.	8809080279	8/19/1988
Discusses 940221 ltr to C Glenn & G Comfort of NRC Office of Nuclear Matl Safety & Safeguards which requested NRC to prepare & submit detailed budget for EIS for Cambridge & Newfield sites covered by licenses SMB-743 & SMB-1507.	9405170238	5/11/1994
FOIA request for documents re Shieldalloy Metallurgical Corp,including but not limited to correspondence between NRC & licensee,New Jersey EPA & other governmental agencies & documentation re on & off site radwaste storage & disposal.	9002050091	10/18/1989
Forwards summary of 901219 technical review meeting in Newfield,NJ re remedial investigation/feasibility study, groundwater sampling & schedule for future work.Next meeting scheduled on 910207 in Newfield,NJ.	9102080032	1/30/1991

Responds to 961104 statement requesting Newfield Facility license for handling radioactive matls not be renewed.	9701020019	12/24/1996
Part 1 of application for renewal of License SMB-743 for Shieldalloy Newfield Facility.	8807290071	7/31/1988
Informs of review of 940315 memo re issues raised in Insp Rept 40-7102/93-01.Licensing Branch still reviewing license for renewal & plans to address issues re radiation safety program,baghouse dust cover & stack monitoring.	9406280269	6/22/1994
Informs that NRC will be receiving rept which demonstrates that dose to off-site member of public will not exceed 10 millirem CEDE per year.	9705160193	5/8/1997
"Work Plan for Radiological Characterization of Sheildalloy Metallurgical Corp Newfield Facility."	9103210412	3/31/1991
Safety insp on 680607 of License SMB-0743.Insp findings: no noncompliance noted.	9002050410	6/7/1968
Responds to 960227 ltr requesting a copy of transcript for meeting on 960131 at St Rose,Vineland,NJ.	9604080198	4/1/1996
"Conceptual Decommissioning Plan for Newfield,NJ Facility."	9304140262	4/7/1993
Submits items of interest re fuel cycle accident analysis, 871117 tour of Shieldalloy facility & acquisition of Sequoyah Fuels Corp stock.	8711230133	11/18/1987
Forwards "Radiological Survey of the Shieldalloy Corp, Newfield,NJ" & Amends 6 & 7 to License SMB-743,in response to 880713 & 0725 ltrs.New license not presently available & will be sent when issued.W/o encls.	8809010308	8/25/1988
Requests transcript for 931216 meeting at Delsea Regional High School re Shieldalloy & radioactive matls on site.	9402220176	2/1/1994
Ack receipt of 980306 ltr,requesting for delay for response to NRC 980128 ltr re bioassay program,until NRC has approved licensee 971125 application for amend to license.Request accepted.	9803250368	3/19/1998
Comment re Shieldalloy nuclear wastesite in Newfield.Advises that town people should decide what should be done w/waste.	9401260099	1/3/1994
SER for Shieldalloy Metallurgical Corp,supporting renewed license SMB-743.	9907160208	10/20/1997
Notice of noncompliance from insp on 650526.Noncompliance noted:matls possessed & used in form of Norwegian & Nigerian ore w/o authorization,source matl inventory in noncompliance w/License Condition 7 & slag storage drums not labeled.	9002050365	6/30/1965
Informs that Metallurg only has voting common stock & therefore stock transferred to Safeguard Intl was voting common stock,based upon 981119 telcon.	9812030019	11/20/1998

Rev 0 to Radiation Protection Procedure RSP-010, "Exposure Control - Newfield Facility." Forwards notice published in 950821 FR announcing NRC intent to revise scope of environ impact statement,preparing for Shieldalloy facility in Cambridge,OH.	9609240335	8/30/1996
Forwards Form AEC-591 re insp conducted on 680607.No noncompliance noted.	9509180038	9/7/1995
Comment on proposed EIS re decommissioning of Shieldalloy Metallurgical Corp facility in Newfield,NJ.EIS needs to discuss ongoing Shieldalloy actions & plans for disposition of slag under "cumalative impact."	9002050415	6/21/1968
Discusses Shieldalloy stabilization of Columbium slag at Newfield,NJ.	9401250048	1/11/1994
Forwards application for amend to license SMB-743, revising program description & requesting authorization to use source matl at Newfield facility & at other off-site,approved in advance by US NRC.	9402080307	1/27/1994
Package consisting of comments from 91 residents of Newfield,NJ re options suggested by NRC for dealing w/ radioactive slag piles & dust at Shieldalloy Plant.Seventy- five supporting carting off site & 16 for capping onsite.	9712030264	11/25/1997
Forwards notice of intent to prepare EIS & to conduct scoping process for decommissioning shield alloy metallurgical corp facility in Newfield,NJ.	9401260173	1/12/1994
Notice of Hearing on Second Application of Harris & Ellsworth for Allowance of Compensation for Services Rendered & Reimbursement of Expenses.	9312020277	11/19/1993
Trip rept of 960131 visit to Newfield,NJ to update public on licensing actions for license SMB-743.	9408290422	8/15/1994
Summary of 910814 meeting w/licensee in Rockville,MD re decommissioning of two slag piles containing NRC licensed source matl & sampling,analysis of surface water & offsite contamination from overland runoff from lime dust pile.	9603110127	3/1/1996
Forwards most recent draft of Commission Paper re transfer of baghouse dust from Shieldalloy Metallurgical Corp site in Newfield,NJ.Paper also addresses possible doses to general public which would result from transfer of slag from sites.	9109030132	8/26/1991
Summary of 921118 meeting w/Shieldalloy Metallurgical Corp in Rockville,MD re content of licensee 920602 licensee renewal application,decommissioning plan,source matl possession limits & NRC licensing review cost controls.	9809240086	9/18/1998
	9212110202	12/9/1992

Forwards Rept IT/NS-92-106, "Assessment of Environ Radiological Conditions at Newfield Facility."	9204270285	4/22/1992
Comment supporting carting 1.2 million cubic yards of radwaste at Shieldalloy plant off site.	9401260151	1/10/1994
Notice of consideration of issuance of amend to License SMB-743 & proposed NSHC determination & opportunity for hearing. Amend would authorize increase in possession & storage onsite of source matl & reflect change of name.	9203260259	3/25/1992
Notification of significant licensee meeting 98-75 w/util on 981001 to discuss apparent violations identified during routine insp conducted on 980727-28.	9809080353	8/27/1998
Confirms 631129 telcon re licensee application for use of source matl, Form AEC-2, inadequately completed. Clarification of application provided.	9002060330	12/2/1963
RADIUM-226 CONCENTRATIONS IN SOIL SEDIMENT & WATER SAMPLES.	9204290384	3/17/1992
Forwards revised summary of 921118 meeting in Rockville, MD. W/o encl.	9302110005	2/3/1993
Confirms 880420 discussion in Cambridge, OH facility re ratio of radioactive elements in slag piles at site. Licensee would not expect to find secular equilibrium of isotopes in FeCb slag. All concentrate processing came from offshore.	8805240397	5/10/1988
Informs that NRC will respond to comments re proposal offered to deal w/contamination at Shieldalloy site in Newfield, NJ through scoping rept that will be issued in Apr 1994, in response to 940207 ltr to Selin.	9403140309	3/3/1994
Requests addl info re 640812 application for amend to AEC License SMB-743. Lists info required.	9002060356	9/4/1964
Clarifies NRC position re jurisdiction over matls like ferrovanadium slag at Shieldalloy Metallurgical Corps Newfield, NJ, site.	9201210224	1/15/1992
Documents State of NJ position re ferrovanadium slag at Shieldalloy Metallurgical Co Newfield, NJ site. State believes slag contaminated w/matl subj to exclusive jurisdiction of NRC.	9112050158	11/25/1991
Provides comments on PR (DEP docket 11-99-06/697). Rule appears to contain many provisions which conflict with federal stds governing radioactive substances.	9910060048	9/14/1999
Draft Rev 0 to Radiation Safety Procedure RSP-002, "Definitions - Newfield."	9512050084	9/8/1995
Draft Rev 0 to Radiation Safety Procedure RSP-004, "Radiation Protection Records - Newfield Facility."	9512050087	9/19/1995
Forwards ltr to Shieldalloy Corp, terminating svcs as consultant on License SMB-0743.	9002060217	10/15/1982

Ack receipt of 900927 ltr informing NRC of steps taken to correct violations noted in Insp 40-7102/90-01.	9010290323	10/17/1990
Rev 1.0 "Std Operating Procedure for U in Urine."	9703260321	8/1/1996
WALKOVER SURVEY (COUNTS PER MINUTE).	9204290392	3/4/1992
"Radiological Survey of Shieldalloy Corp,Newfield,NJ."	8808180016	7/31/1988
Insp rept 40-7102/93-01 on 931202-03.Violations noted.Major areas inspected:organization & scope of activities,training & instruction of employees,radiation safety committee & observation of licensed activities.	9402220099	1/28/1994
Insp Rept 40-7102/90-01 on 900502-03.Violations noted.Major areas inspected:licensee action on previous violations,LERs, NRC notices,surveys of restricted area & training of personnel.	9009100247	8/9/1990
Insp rept 40-7102/94-01 on 940322-0421.No violations noted.Major areas inspected:training & instruction of contractors,disposal of ferro-vanadium slags & evaluation of ferro-columbium slag.	9408240003	8/4/1994
Insp rept 40-7102/95-01 on 950215-17,0306 & 950918.No violations noted.Major areas inspected:interviews w/personnel,selective exam of representative records & independent measurements & licensee action on 940131 NOV.	9512120029	11/21/1995
Informs Commission of staff approach to renew operating license while continues to review proposed decommissioning funding plan (DFP).	9610110022	10/1/1996
Enforcement conference summary rept 40-7102/98-01 on 981001.Violation noted.Major areas discussed:apparent violations identified during insp rept 40-7102/98-01 conducted on 980727-28.	9902100081	12/30/1998
Insp rept 40-7102/98-01 on 980727-28.Violations noted. Major areas inspected:review of licensee organization & scope of licensed activities,program mgt oversight, facilities & equipment & matl receipt,use & transfer.	9809090083	8/27/1998
Insp rept 40-7102/97-01 on 970520-21.No violations noted. Major areas inspected:status of previous violations, organization & scope of activities,facilities & equipment, radiation safety training & area radiation survey.	9710140041	9/24/1997