

**From:** [Hann, Patrick-John](#)  
**To:** [Clinical Cardiology Specialists](#)  
**Subject:** Request for additional information  
**Date:** Thursday, October 21, 2021 8:25:00 AM

---

License No: 07-30784-01

Docket No: 030-36153

Mail Control No: 628353

Mr. Bowen,

This refers to your request to amend your license dated August 18, 2021, In order to continue our review of your request, the following additional information is needed:

1. During the on-site inspection conducted on July 27, 2021, contaminated waste was found to be a waste can in the area labeled as injection site on your submitted area diagram. This area was observed to not have any access control (i.e. locked door). Please identify whether any radioactive materials will be stored in the area labeled as injection site, including waste. Additionally, please identify any security measures that will be implemented to ensure no unauthorized access to radioactive materials will occur in the area labeled injection site
2. Please identify the surveys that will be performed in the area labeled as injection site, including the frequency and acceptable limits.

Your reply must be an originally signed and dated letter. The letter may be scanned and submitted as a pdf document attached to an email.

Patrick-John E. Hann, MHP  
Health Physicist  
U.S. Nuclear Regulatory Commission