

## George, Mathews

---

**Subject:** FW: Technical Review Report: Tank 12 Grouting  
**Attachments:** HTF-SKM-2014-00031 Rev. A.pdf; SRR-CWDA-2014-00102.pdf; SRR-LWE-2014-00162.pdf; SRR-LWE-2016-00020.pdf; USQ-HTF-2015-00635.pdf; USQ-HTF-2015-00686.pdf

---

**From:** larry.romanowski@srs.gov <larry.romanowski@srs.gov>  
**Sent:** Tuesday, February 22, 2022 8:16 PM  
**To:** George, Mathews <Mathews.George@nrc.gov>  
**Cc:** Charles.Comeau@srs.gov; patricia.suggs@srs.gov; aaron.staub@srs.gov  
**Subject:** [External\_Sender] Technical Review Report: Tank 12 Grouting

Mathews,

In Appendix B to *Technical Review Report: U.S. Department of Energy Documentation Related to Tank 12 Grouting Operations with Emphasis on Specifications, Testing, Recommendations and Placement Procedures* (ML20296A550) the NRC requested a number of files and references. The majority of the information is attached to this email. I have noted status for each of the items below:

1. Goldsim modeling files associated with SRR-CWDA-2015-00100 (evaluation of impact of clean cap grout in Tank 16H), if not already provided.  
[-Files will be uploaded to the NRC Box location and separate notification will be provided when complete](#)
2. NRC requested and DOE provided work order No. 01324150-64. However, key attachment HTF-SKM-2015-00031 (Grout Placement Plan) was not provided (DOE provided attachments HTF-SKM-2015-00021 and HTF-SKM-2015-00010). Would DOE provide missing attachment HTF-SKM-2014-00031?  
[-HTF-SKM-2014-00031 is attached to this email](#)
3. SRR-CWDA-2014-00102. Layton, M.H. "Disposal of Cooling Coil Grouting Liquid Within Tank 16." Revision 0, Aiken, South Carolina: Savannah River Site. November 2014.  
[-SRR-CWDA-2014-00102 is attached to this email](#)
4. SRR-CWDA-2012-00051 *Revision 3 or later*, said to contain directions referenced in in a work order to: "PLACE/POUR GROUT; IF water is present Then add Dry Grout Per the guidance of SRR-CWDA-2012-00051 Revision 2 (Riser grouting)." NRC has Revision 2, which does not address application of dry grout mix to bleed water in risers.  
[-Revision 2 of SRR-CWDA-2012-00051 is the latest revision, will discuss during planned April 28, 2022 NRC-DOE Technical Discussions.](#)
5. SRR-LWE-2014-00162. Voegtlen, R.O. "Video Inspection Plan for Tank 12 During Tank Grouting Activities." February 2015.  
[-SRR-LWE-2014-00162 is attached to this email](#)
6. SRR-LWE-2016-00020. Voegtlen, R.O. "Tank 12 Grout Cracks under Riser 1." 2016.  
[-SRR-LWE-2016-00020 is attached to this email](#)
7. USQ-HTF-2015-00635 (Technical Review Package associated with grout cylinder laboratory temperature excursions).  
[-USQ-HTF-2015-00635 is attached to this email](#)
8. USQ-HTF-2015-00686 (Technical Review Package associated with grout cylinder laboratory temperature excursions).  
[-USQ-HTF-2015-00686 is attached to this email](#)
9. Any Tank 12 nonconformances.

-The two nonconformance Reports associated with Tank 12 have been provide to the NRC previously and were reviewed as part of this TRR. The Reports are captured as References 1 and 2 to the TRR (ADAMS Accession No's, ML20302A273 and ML20302A274).

Please pass the information on to NRC Technical Staff as necessary. I will notify you once we have the files for Item #1 above loaded on the NRC Box Folder.

Thanks,  
Larry Romanowski  
Waste Disposal Authority  
803-557-9900 (w)  
706-339-2462 (c)