

Hilcorp Alaska, LLC

Post Office Box 244027
Anchorage, AK 99524-4027

3800 Centerpoint Drive
Suite 1400
Anchorage, AK 99503

Phone: 907/777-8300
Fax: 907/777-8301

February 22, 2022

~~ATS~~

Office of Nuclear Material Safety and Safeguards
U.S. Nuclear Regulatory Commission
Washington DC 20555-0001



Re: ~~General License 728132~~

Dear Mr. Rolland:

Hilcorp Alaska recently took over operatorship of Point Thomson Unit, Alaska. Please update General License number 728132 to reflect the following:

Hilcorp Alaska, LLC
3800 Centerpoint Dr Ste 1400
Attn: Safety Department
Anchorage, AK 99503

The person responsible for the device is myself.

Sarra Ghiassi
Radiation Safety Officer
907-659-8101
sghiassi@hilcorp.com

Please advise if you require any additional documentation for processing this request.

Sincerely,

Sarra Ghiassi
Radiation Safety Officer
HILCORP ALASKA, LLC

Leak Tests - 15804 ExxonMobil Alaska Production, Inc.

Unit	Vessel	Device S/N	Source S/N	Isotope	Activity	Unit	Interval	Due	Manufact.	Model
Line/Area:	Point Thompson		License No: General							
MBF653114Top(A)		M3000601145	AJ-7280	Cs 137	.5	mCi	6		Endress & FQG60	
MBF653014Mid(A)		M3000701145	AJ-7281	Cs 137	.5	mCi	6		Endress & FQG60	
MBF653114Bot(B)		M3000801145	AJ-7282	Cs 137	.5	mCi	6		Endress & FQG60	
MBF653103Top(A)		M3000901145	AJ-7283	Cs 137	.5	mCi	6		Endress & FQG60	
MBF653114Top(B)		M3000A01145	AJ-7284	Cs 137	.5	mCi	6		Endress & FQG60	
MBF653103Top(B)		M3000B01145	AJ-7285	Cs 137	.5	mCi	6		Endress & FQG60	
MBF653003Mid(A)		M3000C01145	AJ-7286	Cs 137	.5	mCi	6		Endress & FQG60	
MBF653003Top(B)		M3000D01145	AJ-7287	Cs 137	.5	mCi	6		Endress & FQG60	
MBF653103Mid(B)		M3000E01145	AJ-7288	Cs 137	.5	mCi	6		Endress & FQG60	
MBF653114Mid(B)		M3000F01145	AJ-7289	Cs 137	.5	mCi	6		Endress & FQG60	
MBF653014Mid(B)		M3001001145	AJ-7290	Cs 137	.5	mCi	6		Endress & FQG60	
MBF653103Bot(A)		M3001101145	AJ-7291	Cs 137	.5	mCi	6		Endress & FQG60	
MBF653114Mid(A)		M3001201145	AJ-7292	Cs 137	.5	mCi	6		Endress & FQG60	
MBF653114Bot(A)		M3001301145	AJ-7293	Cs 137	.5	mCi	6		Endress & FQG60	
MBF653103Bot(B)		M3001401145	AJ-7294	Cs 137	.5	mCi	6		Endress & FQG60	
MBF653014Bot(A)		M3001501145	AJ-7295	Cs 137	.5	mCi	6		Endress & FQG60	
MBF653103Mid(A)		M3001601145	AJ-7296	Cs 137	.5	mCi	6		Endress & FQG60	
MBF653003Bot(A)		M3001701145	AJ-7297	Cs 137	.5	mCi	6		Endress & FQG60	
MBF653003Top(A)		M3001801145	AJ-7298	Cs 137	.5	mCi	6		Endress & FQG60	
MBF653014Bot(B)		M3001901145	AJ-7299	Cs 137	.5	mCi	6		Endress & FQG60	
MBF653003Bot(B)		M3001A11045	AJ-7300	Cs 137	.5	mCi	6		Endress & FQG60	
MBF653003Mid(B)		M3001B11045	AJ-7301	Cs 137	.5	mCi	6		Endress & FQG60	
MBF653014Top(A)		M3001C11045	AJ-7302	Cs 137	.5	mCi	6		Endress & FQG60	

MBE653014Top(B)

M3001D11045

AJ-7303

Cs 137

.5

mCi

6

Endress & FQG60

4/26/17

Page 1 of 1