



10 CFR 50.73
L-2022-047
March 28, 2022

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D.C. 20555-0001

RE: Turkey Point Unit 3
Docket No. 50-250
Reportable Event: 2021-004-00 (Cancellation)
Date of Event: November 12, 2021
Title: Cancellation of LER 2021-004, Through-Wall Leakage from Core Exit Thermocouple Tubing

On 11/12/2021 Licensee Event Report 05000250/2021-004-00 was submitted pursuant to 10 CFR 50.73 (a)(2)(ii)(A), due to evidence of RCS pressure boundary through-wall leakage on a Core Exit Thermocouple (CET) tube.

Subsequent analysis performed by an independent laboratory found that there was no RCS Pressure Boundary through-wall leakage and that the observed leakage likely originated from a threaded compression fitting on a tubing joint. On 3/10/2022 FPL Engineering concluded that the observed condition was not an ASME Section XI through-wall flaw and is therefore not reportable. The original NRCOC notification, EN# 55574, has been retracted. This letter serves to cancel LER 2021-004-00.

If there are any questions, please call Mr. Robert Hess at 305-246-4112 or e-mail Robert.Hess@fpl.com.

Sincerely,

A handwritten signature in black ink, appearing to read 'M. Pearce', is written over a light blue horizontal line.

Michael Pearce
Site Vice President – Turkey Point Nuclear Plant
Florida Power & Light Company

Attachments: None

cc: USNRC Senior Resident Inspector, Turkey Point Plant
USNRC Regional Administrator, Region II