



March 31, 2022
L-2022-057
10 CFR 50.4
10 CFR 50 Appendix E

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555-0001

Re: Turkey Point Units 3 and 4
Docket Nos. 50-250 and 50-251
Radiological Emergency Plan Revision 71

The Turkey Point Plant Radiological Emergency Plan, Revision 71 was implemented on March 29, 2021.

A summary of the changes to the revised document is attached. FPL has determined that the changes described do not result in a decrease in the effectiveness of the Emergency Plan.

Sincerely,

A handwritten signature in blue ink, consisting of several loops and a long horizontal stroke extending to the right.

Robert J. Hess
Licensing Manager
Turkey Point Nuclear Plant

Attachment

cc: Regional Administrator, Region II, USNRC
Senior Resident Inspector, USNRC, Turkey Point Plant

Summary of Changes to Turkey Point Plant Radiological Emergency Plan, Revision 71

Reference: AR 02415941

The Turkey Point Plant Radiological Emergency Plan was revised to correct the typographical errors in Table 3-2 for Reactor Coolant Letdown Line Monitor for 10 with a superscript 4 and correct the MSL notation to use 10 with a superscript instead of “E” for consistency.

This revision also updated the Quality Manager description in the normal operating organization, Section 2.2.1, to change the title of the department from “Quality Control/Quality Assurance Department” to “Quality Assurance Department.” Additionally, it changed the reporting relationship for the QC inspectors to be reporting to the Maintenance Site Director.

Revision 71 Implementation Date: 03/29/2022