ES-401

Record of Rejected K/As

Form ES-401-4

Tier / Group	Randomly Selected K/A	Reason for Rejection
1/1	000065 G 2.4.35	RO responsibilities in emergency plan implementation for instrument air is a mismatch of system and K/A. RO emergency plan implementation is limited to communication and monitoring functions and none are directly associated with instrument air.
Request		Description on outline is for G2.4.39 which we reject, if 2.4.35 we accept.
		CE correct 2.4.35 K/A description.
1/2	000036 AK3.03	The EOPs are written specifically for modes 1-4, fuel handling emergencies are mode 5 and below and covered under AOP procedures.
Request		Select new K/A.
		CE randomly selected K3.02 fuel handling interlocks.
2/2	000027 A2.01	Iodine removal system was abandoned at Braidwood Station.
Request		Select new system.
		CE randomly selected System 002 RCS; same K/A, A2.01.
2/2	000034 G2.4.1	There are no immediate actions or entry criteria associated with fuel handling equipment.
Request		Request new K/A.
		CE randomly selected new system (045) MTG using same K/A.
1/2	000067 AA2.11	Ability to determine and interpret the following as they apply to plant fire on site: Time limit for use of respirators.
Request	000067 AA2.15	Original KA is RO level; request new K/A.
		CE randomly selected AA2.15 fire watch requirements - SRO level.