

SVP-22-042

July 22, 2022

U. S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, DC 20555-0001

> Quad Cities Nuclear Power Station, Unit 2 Renewed Facility Operating License No. DPR-30 NRC Docket No. 50-265

Subject:

Owner's Activity Report Submittal

Fifth 10-Year Interval 2020 Refueling Outage Activities

Reference:

Letter from T. Tate (USNRC) to M. Pacilio (Exelon), "Quad Cities Nuclear Power Station, Units 1 and 2 – Safety Evaluation in Support of Request for Relief Associated with the Fifth 10 Year Interval Inservice Inspection Program," dated September 30, 2013.

This letter submits the Owner's Activity Report (i.e., Form OAR-1) for the Quad Cities Nuclear Power Station (QCNPS) Unit 2 refueling outage (Q2R26) that began on March 21, 2022 and was completed on April 24, 2022. This is the second refueling outage conducted in the Third (3rd) Inspection Period of the Fifth (5th) 10-Year Interval Inservice Inspection (ISI) Program for QCNPS Unit 2. A copy of the Owner's Activity Report is provided as attachment to this letter.

This Owner's Activity Report is submitted in accordance with American Society of Mechanical Engineers (ASME) Boiler and Pressure Vessel Code Case N-532-5, "Repair/Replacement Activity Documentation Requirements and Inservice Summary Report Preparation and Submission". Code Case N-532-5 requires an Owner's Activity Report Form OAR-1 to be prepared and certified upon completion of each refueling outage. In accordance with the conditions of Code Case N-532-5, this OAR-1 form is being submitted within ninety (90) days of the completion of the refueling outage. No new inaccessible areas were identified for evaluation in Q2R26 therefore reporting under 10 CFR 50.55a(b)(2)(ix)(A)(2) is not required.

No welds were reclassified or changed status within the Intergranular Stress Corrosion Cracking (IGSCC) program this outage.

SVP-22-042 July 22, 2022 U.S. Nuclear Regulatory Commission Page 2

Should you have any questions concerning this letter, please contact Mr. Mark Humphrey, Acting Manager of Site Regulatory Assurance at (309) 227-2800.

Respectfully,

Brian M. Wake

Site Vice President

Quad Cities Nuclear Power Station

Attachments: 1. Owner's Activity Report, Form OAR-1

cc: Regional Administrator – Region III

NRC Senior Resident Inspector, Quad Cities Station

Attachment 1 Owner's Activity Report, Form OAR-1

FORM OAR-1 OWNER'S ACTIVITY REPORT

Report Number		Refueling Outage Q2R2	6 OAR-1				
Plant	Quad Cities Nuclear Power Station, 22710 206th Ave. North, Cordova, IL 61242						
Unit No. 2	Commercial Service Date	03/10/1973	Refueling Outage Number	Q2R26			
(if applicable) Current Inspection Interval	5 th Inspection Interval (ISI), 3 rd Inspection Interval (Containment)						
Current Inspection Period	(1 st , 2 nd , 3 rd , 4 th , other) 3 rd Inspection Period (ISI), 1 st Inspection Period (Containment)						
Edition and Addenda of Section	XI applicable to the Inspection		2007 Edition and 2008 Addenda (ISI), 2013 Edition (Containment)				
Date and Revision of Inspection	n Plans	04/26/202	04/26/2021 and Revision 3				
Edition and Addenda of Section XI applicable to repair/replacement activities, if different than the inspection plans N/A							
Code Cases used: N-62-7, N-532-5, N-552-1, N-578-1, N-600, N-613-2, N-702, N-765, N-778, N-805 (if applicable, including cases modified by Case N-532 and later revisions)							
I certify that (a) the statements made in this report are correct; (b) the examinations and tests, meet the Inspection Plan as required by the ASME Code, Section XI; and (c) the repair/replacement activities and evaluations supporting the completion of Q2R26 conform to the requirements of Section XI Signed Signed Owner or Owner's designee. Title							
	CEDTIEICATE	OF THEEDVICE THE	PECTION				
I, the undersigned, holding a valid commission issued by the National Board of Boiler and Pressure Vessel Inspectors and and employed by The Hartford Steam Boiler Inspection and Insurance Company of Hartford, Connecticut have inspected the items described in this Owner's Activity Report, and state that, to the best of my knowledge and belief, the Owner has performed all activities represented by this report in accordance with the requirements of Section XI. By signing this certificate neither the Inspector nor his employer makes any warranty, expressed or implied, concerning the repair/replacement activities and evaluation described in this report. Furthermore, neither the Inspector nor his employer shall be liable in any manner for any personal injury or property damage or a loss of any kind arising from or connected with this inspection.							
Jeesny Norwille Aller			IL 2211; NB13175 R, N, I rd Number and Endorsements)	·-			
Date <u>)</u> \$<	luc 22						

Attachment 1 Owner's Activity Report, Form OAR-1

TABLE 1 ITEMS WITH FLAWS OR RELEVANT CONDITIONS THAT REQUIRED EVALUATION FOR CONTINUED SERVICE

Examination		Evaluation Description	
Category and	Item Description		
Item Number			
None	None	None	

Attachment 1 Owner's Activity Report, Form OAR-1

TABLE 2 ABSTRACT OF REPAIR/REPLACEMENT ACTIVITIES REQUIRED FOR CONTINUED SERVICE

Code Class	Item Description	Description Of Work	Date Completed	Repair/ Replacement Plan Number
3	IR 4386700 – Pin-hole leaks found at weld for 0- 5799-381 "B" HVAC Train	WO 05102122-02 - Weld Repair of Valve	03/28/2021	20-011
3	IR 4466003 – Pin-hole leaks found at weld for 0- 5799-381 "B" HVAC Train	WO 05213257-04 - Valve Replacement	12/15/2021	20-012