

Location: D-66 Above Steel Ceiling
Site: DHS-EML

RWP# EML-002

Survey # 038


Survey Type: Scan/Static/Smear

pg. 1 of 1

Smear (CPM/100 cm ²)					
Direct Count (CPM/Direct Frisk)					
No.	α	β	No.	α	β
1	0	79	26		
2	0	77	27		
3	0	80	28		
4	0	69	29		
5	1	84	30		
6	0	84	31		
7	0	61	32		
8			33		
9			34		
10			35		
11			36		
12			37		
13			38		
14			39		
15			40		
16			41		
17			42		
18			43		
19			44		
20			45		
21			46		
22			47		
23			48		
24			49		
25			50		

circle one

D-66 Survey After Removal of Pipe from Concrete Ceiling + wall



Comments	Surveyed By:	Date:	Instrument	Serial #	α Eff.	β Eff.	α Bkg.	β Bkg	γ Bkg	Cal. Due	Key	
Survey performed	GBright	3/21/08	2224-1 43-α3	27246 PR2 44549	22.7%	20.6%	1	145	N/A	12/5/08		
above steel drop ceiling	"	3/21/08	2929 43-γ-1	129566 PR1 32720	33.3%	20.4%	1	72	N/A	1/3/09	■ A/S Location	
and below concrete											*.* Boundary	
actual ceiling in											○ Smear	
"Supervisor's office"											□ Dose Rate _____ /hr	
											* Direct Reading CPM/direct frisk	
	Reviewed By:	Date:	Original Survey Merged									△ Grab Sample
	Nicholas M. Berliner	12/28/11										