

October 13, 2022

David Lew
Regional Administrator, Region I
U.S. Nuclear Regulatory Commission
475 Allendale Rd., Suite 102
King of Prussia, PA 19406-1415

Oyster Creek Nuclear Generating Station
Renewed Facility Operating License No. DPR-16
Docket No. 50-219

SUBJECT: NRC Confirmatory Order EA-21-041

REFERENCES: 1) Confirmatory Order Related to Oyster Creek Nuclear Generating Station – NRC
Investigation Report I-2020-007; NRC Inspection Report NOS. 05000219/2021402 &
07200015/20211401

Dear Mr. Lew,

On January 26, 2022, the Nuclear Regulatory Commission (NRC) issued Confirmatory Order EA-21-041 to Holtec Decommissioning International (HDI). Section V of the order specifies items to assure restoration of compliance by HDI that were agreed upon during the Alternate Dispute Resolution (ADR) session.

The purpose of this letter is to comply with Section V of the Confirmatory Order (Reference 1) and “Within 30 days of completing this action, HDI shall inform the NRC that the action is complete by sending a letter to the Region I Administrator and shall make the results of the evaluation available to the NRC for review during an inspection”. HDI has completed the commitments set forth in Section V item C1 to address armor function weaknesses.

Should you have any questions or require further information, please contact Steven Johnston at (609) 971- 4325.

Sincerely,

Jean A. Fleming Digitally signed by Jean A. Fleming
Date: 2022.10.13 13:31:09 -04'00'

Jean Fleming
Vice President of Licensing, Regulatory Affairs & PSA
Holtec International

Attachment 1: Reply to Confirmatory Order EA-21-041 Item (C1)

HDI-OC-22-054



Krishna P. Singh Technology Campus, 1 Holtec Blvd., Camden, NJ 08104

Telephone (856) 797-0900

Fax (856) 797-0909

ATTACHMENT 1

Reply to Confirmatory Order EA-21-041 Item
(C1)

Item C1: HDI has completed an evaluation of the implementation of the armorer position including weapons maintenance tracking methodologies and supervisory involvement during the completion of required activities. The evaluation included the comparison of site practices with at least one non-HDI nuclear site. The evaluation identified best practices and considered any changes needed at Oyster Creek and specified any identified corrective actions.