



**UNITED STATES  
NUCLEAR REGULATORY COMMISSION**

REGION IV  
1600 EAST LAMAR BOULEVARD  
ARLINGTON, TEXAS 76011-4511

November 9, 2022

Robert Schuetz  
Chief Executive Officer  
Energy Northwest  
MD 1023  
76 North Power Plant North  
P.O. Box 968  
Richland, WA 99352

SUBJECT: COLUMBIA GENERATING STATION – SECURITY BASELINE INSPECTION  
REPORT 05000397/2022404

Dear Mr. Schuetz:

On October 6, 2022, the U.S. Nuclear Regulatory Commission (NRC) completed an inspection at Columbia Generating Station and discussed the results of this inspection with David P. Brown, Site Vice President, and other members of your staff. The results of this inspection are documented in the enclosed report.

One finding of very low security significance (Green) is documented in this report. This finding involved a violation of NRC requirements. We are treating this violation as a non-cited violation (NCV) consistent with Section 2.3.2 of the Enforcement Policy.

If you contest the violation or the significance or severity of the violation documented in this inspection report, you should provide a response within 30 days of the date of this inspection report, with the basis for your denial, to the U.S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, DC 20555-0001; with copies to the Regional Administrator, Region IV; the Director, Office of Enforcement; the Director, Office of Nuclear Security and Incident Response; and the NRC Resident Inspector at Columbia Generating Station.

The following cross-cutting aspect was assigned to a finding using Inspection Manual Chapter 0310 "Aspects Within Cross Cutting Areas:" [H.12] - Avoid Complacency.

If you disagree with a cross-cutting aspect assignment in this report, you should provide a response within 30 days of the date of this inspection report, with the basis for your disagreement, to the U.S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, DC 20555-0001; with copies to the Regional Administrator, Region IV; the Director, Office of Nuclear Security and Incident Response; and the NRC Resident Inspector at Columbia Generating Station.

Enclosure(s) transmitted herewith contain(s) SUNSI. When separated from enclosure(s), this transmittal document is decontrolled.
--

R. Schuetz

2

This letter will be made available for public inspection and copying at <http://www.nrc.gov/reading-rm/adams.html> and at the NRC Public Document Room in accordance with Title 10 of the Code of Federal Regulations 2.390, "Public Inspections, Exemptions, Requests for Withholding."

The enclosed report contains Security-Related Information, so the enclosed report will not be made publicly available in accordance with Title 10 of the *Code of Federal Regulations* (10 CFR) 2.390(d)(1). If you choose to provide a response that contains Security-Related Information, please mark your entire response "Security-Related Information–Withhold from public disclosure under 10 CFR 2.390" in accordance with 10 CFR 2.390(d)(1) and follow the instructions for withholding in 10 CFR 2.390(b)(1). The NRC is waiving the affidavit requirements for your response in accordance with 10 CFR 2.390(b)(1)(ii).

Sincerely,



Signed by Kellar, Ray  
on 11/09/22

Ray L. Kellar, P.E., Chief  
Physical Security Branch  
Division of Radiological Safety & Security

Docket No. 05000397  
License No. NPF-21

Enclosure:  
As stated

cc w/o encl: Distribution via LISTSERV®

R. Schuetz

COLUMBIA GENERATING STATION – SECURITY BASELINE INSPECTION REPORT  
05000397/2022404 DATED NOVEMBER 9, 2022

**DISTRIBUTION:**

- SMorris, ORA
- JMonninger, ORA
- RLantz, DORS
- MHay, DORS
- LMcKown, RIV/OEDO
- DCylkowski, RC
- VDricks, ORA
- LWilkins, OCA
- MChawla, NRR
- AMoreno, RIV/OCA
- RAlexander, RSLO
- PVossmar, DORS
- SLichvar, DORS
- PNiebaum, DORS
- ADonley DORS
- MBennett, DORS
- DJohnson, NSIR
- EWharton, NSIR
- FSullivan, NSIR
- JTKeene, NSIR
- JRey, NSIR
- SOrth, RIII
- DSchroeder, RI
- JWorosilo, RII
- R4-DORS-IPAT
- R4Enforcement

DOCUMENT NAME: COLUMBIA GENERATING STATION – SECURITY BASELINE  
INSPECTION REPORT 05000397/2022404

Non-Public Designation Category: MD 3.4 Non-Public \_\_\_\_\_ (A.3 - A.7 or B.1)

ADAMS ACCESSION NUMBER **ML22312A545** (Cover letter w/ enclosure(s))

Non-Public Designation Category: MD 3.4 Non-Public \_\_\_\_\_ (A.3 - A.7 or B.1)

ADAMS ACCESSION NUMBER: **ML22314A033** (Cover letter)

<b>Entire Report:</b> <input checked="" type="checkbox"/> SUNSI Review		<input type="checkbox"/> Non-Sensitive <input checked="" type="checkbox"/> Sensitive	<input type="checkbox"/> Publicly Available <input checked="" type="checkbox"/> Non-Publicly Available
<b>Cover Letter Only:</b> <input checked="" type="checkbox"/> SUNSI Review		<input checked="" type="checkbox"/> Non-Sensitive <input type="checkbox"/> Sensitive	<input checked="" type="checkbox"/> Publicly Available <input type="checkbox"/> Non-Publicly Available
OFFICE	DRSS: PSB	DRSS: PSB	DRSS: PSB
NAME	Holman, D.	Tejada, W.	Kellar, R.
DATE	11/8/22	11/8/22	11/9/22

OFFICIAL RECORD COPY