

NRC FORM 591M
10 CFR 2.201

U.S. NUCLEAR REGULATORY COMMISSION

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Manson Construction Co. 5209 East Marginal Way S. Seattle, WA 98134 REPORT NO.: 2022-001		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region IV, 1600 East Lamar Blvd. Arlington, Texas 76011-4511	
3. DOCKET NUMBER 030-38921	4. LICENSE NUMBER 46-35305-01	5. DATE(S) OF INSPECTION 9/15/2022, 10/25/2022	

LICENSEE:


The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

1. Based on the inspection findings, no violations were identified.
2. Previous violation(s) closed.
3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.
- Non-Cited Violation(s) was/were discussed involving the following requirement(s):
4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with the NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

See Continuation Page.

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE'S REPRESENTATIVE	Carlos Vizcarrondo- RSO		10/25/2022
NRC INSPECTOR	Leonardo Wardrobe	Leonardo F. Wardrobe	Digitally signed by Leonardo F. Wardrobe Date: 2022.10.25 13:52:44 -05'00'
BRANCH CHIEF	Lizette Roldan-Otero, PhD	Lizette Roldan-Otero	Digitally signed by Lizette Roldan-Otero Date: 2022.11.06 04:08:32 -06'00'

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Manson Construction Co. 5209 East Marginal Way S. Seattle, WA 98134 REPORT NO.: 2022-001		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region IV, 1600 East Lamar Blvd Arlington, Texas 76011-4511	
3. DOCKET NUMBER 030-38921	4. LICENSE NUMBER 46-35305-01	5. DATE(S) OF INSPECTION 9/15/2022, 10/25/2022	

CONTINUED

10 CFR 20.1101(c) states that the licensee shall periodically (at least annually) review the radiation protection program content and implementation.

Contrary to the above, since December 31, 2020 until September 15, 2022, the licensee failed to periodically (at least annually) review the radiation protection program content and implementation. Specifically, the last annual review was performed December 15, 2019, exceeding the annual frequency.

This is a Severity Level IV violation (Enforcement Policy 6.3.d)

The licensee has committed to performing a review of their annual radiation protection content and implementation by December 31, 2022 and adding an annual reminder to their Outlook calendar to perform a review of their radiation protection program content and implementation.