



CCN: 23-02

10CFR 50.55a

January 23, 2022

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555-0001

Peach Bottom Atomic Power Station (PBAPS) Unit 2
Subsequent Renewed Facility Operating License No. DPR-44
NRC Docket No. 50-277

Subject: Submittal of the Inservice Inspection (ISI) Owner's Activity Report (OAR) for the 24th Refueling Outage for Unit 2

Attached is the ISI Owner's Activity Report for the 24th refueling cycle covering ISI activities associated with the first period of the 5th ISI inspection interval for Unit 2. This report is submitted in accordance with 10CFR 50.55a(b)(2)(xxxii); ASME Section XI, Article IWA-6200; and ASME Code Case N-532- 5.

If you have any questions or require additional information, please contact Marcellus Ruff at 610-765-5231.

Sincerely,

A handwritten signature in black ink, appearing to read "D. Henry".

David A. Henry
Site Vice President
Peach Bottom Atomic Power Station

Attachment

cc: USNRC, Regional Administrator, Region 1
USNRC, Senior Resident Inspector, PBAPS
W. DeHaas, Commonwealth of Pennsylvania
S. Seaman, State of Maryland
B. Watkins, PSEG