Re: FOIA-2023-000163, Interim #1

Below is a report of publicly available responsive records. You can search for these records by their accession number (ML#) in the Advanced Search of ADAMS at https://adams.nrc.gov/wba/. If you need assistance with searching and downloading these records, please contact the NRC's Public Document Room at 301-415-4737 from 8 am to 4 pm (EST) or at pdf.resource@nrc.gov.

Accession Number: ML17054A529

Document Date: Tue Jan 31 06:00:00 EST 1984

Document Title: "Evaluation of Angled Screen Fish Diversion Sys at Oswego Steam

Station Unit 6."

Author Affiliation: LAWLER, MATUSKY & SKELLY ENGINEERS

Accession Number: ML17054B236

Document Date: Fri Nov 30 06:00:00 EST 1984

Document Title: Advises that rept on vertical floor flexibility will be provided by 850101.

Author Affiliation: NIAGARA MOHAWK POWER CORP.

Accession Number: ML17054B402

Document Date: Tue Feb 12 06:00:00 EST 1985

Document Title: Responds to 850122 ltr, stating commitments re alternate damping values & verification of increased piping displacements. Commitments will be incorporated into FSAR

Amend 18.

Author Affiliation: NIAGARA MOHAWK POWER CORP.

Accession Number: ML17055A777

Document Date: Sat Nov 30 06:00:00 EST 1985

Document Title: Updated environ qualification document.

Author Affiliation: NIAGARA MOHAWK POWER CORP.

Accession Number: ML17055B175

Document Date: Fri Jan 10 06:00:00 EST 1986

Document Title: Preoperational Security Program Review Insp Rept 50-410/85-38 on

851028-1101.No violation noted.Major areas inspected:security plan & implementing

procedures. Portions withheld (ref 10CFR2.790(a) & 9.5.(a)(4)).

Author Affiliation: NRC OFFICE OF INSPECTION & ENFORCEMENT (IE REGION I)

Accession Number: ML17055B517

Document Date: Mon Mar 10 06:00:00 EST 1986

Document Title: Rev 4 to Administrative Procedure AP-2.0, "Production & Control of

Procedures."

Author Affiliation: NIAGARA MOHAWK POWER CORP.

Accession Number: ML17055B764

Document Date: Thu May 08 06:00:00 EDT 1986

Document Title: "Human Factors Engineering, DCRDR Supplemental Technical Evaluation

Rept, Nine Mile Point Unit 2."

Author Affiliation: LAWRENCE LIVERMORE NATIONAL LABORATORY

Accession Number: ML17055B997

Document Date: Mon Jun 09 06:00:00 EDT 1986

Document Title: Forwards marked-up revised supplemental rept to DCRDR final summary rept,including checklist survey,response to NRC SER & study results since Sept 1985 final

rept.Rept also addresses items in Haughey 860122 ltr & 860520 meeting.

Author Affiliation: NIAGARA MOHAWK POWER CORP.

Accession Number: ML17055C057

Document Date: Thu Jul 10 06:00:00 EDT 1986

Document Title: Insp Rept 50-410/86-28 on 860527-0613.No violation noted. Major areas inspected:const deficiencies, bulletins & outstanding items re safety-related mechanical, electrical

& instrumentation distribution & equipment.

Author Affiliation: NRC OFFICE OF INSPECTION & ENFORCEMENT (IE REGION I)

Accession Number: ML17055C117

Document Date: Thu Jul 31 06:00:00 EDT 1986

Document Title: SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF NINE MILE POINT NUCLEAR STATION, UNIT NO. 2. Docket No. 50-410. (Niagara Mohawk

Power Corporation)

Author Affiliation: NRC OFFICE OF NUCLEAR REACTOR REGULATION (NRR)

Accession Number: ML17055D117

Document Date: Tue Aug 04 06:00:00 EDT 1987

Document Title: Operational Readiness Team Insp Rept 50-410/87-16 on 870601-12. Violation noted. Major areas inspected: testing, training & maint & assessed licensee readiness for full power operations. Unresolved item identified.

Author Affiliation: NRC OFFICE OF INSPECTION & ENFORCEMENT (IE REGION I)

Accession Number: ML17055D694

Document Date: Thu Mar 10 06:00:00 EST 1988

Document Title: Exam Rept 50-410/87-430L on 871216 & 880126-28.Exam results: all senior reactor operators & reactor operators passed written exams, three senior reactor operators & three reactor operators passed operating exams. One senior operator failed.

Author Affiliation: NRC OFFICE OF INSPECTION & ENFORCEMENT (IE REGION I)

Accession Number: ML17055D843

Document Date: Wed May 04 06:00:00 EDT 1988

Document Title: LER 88-020-00:on 880407,ESF actuated on spurious radiation signal due to electrical noise. Caused by contractor "chattering" due to increased valve 2HCS*MOV25B torque requirement. Torque switch of valve adjusted. W/880504 ltr.

Author Affiliation: NIAGARA MOHAWK POWER CORP.

Accession Number: ML17055E127

Document Date: Mon Aug 22 06:00:00 EDT 1988

Document Title: LER 88-035-00:on 880721,automatic initiation of control bldg special filter train occurred. Caused by electrical noise due to operation of RCIC trip & throttle valve. Filter train returned to standby & work request issued. W/880822 ltr.

Author Affiliation: NIAGARA MOHAWK POWER CORP.

Accession Number: ML17055E359

Document Date: Wed Nov 23 06:00:00 EST 1988

Document Title: LER 88-059-00:on 881025,ESF actuation occurred. Caused by accidental contact of heat sink plates of power source w/flex conduit. Lessons learned transmittal issued to appropriate depts & warning will be emplaced. W/881123 ltr.

Author Affiliation: NIAGARA MOHAWK POWER CORP.

Accession Number: ML17055E366

Document Date: Tue Nov 29 06:00:00 EST 1988

Document Title: LER 88-061-00:on 881030, facility experienced ESF actuation while reactor mode switch in shutdown. Caused by equipment malfunction. Work stopped on gas treatment sys & verification that no actual high radiation signals noted. W/881129 ltr.

Author Affiliation: NIAGARA MOHAWK POWER CORP.

Accession Number: ML17055E520

Document Date: Thu Feb 09 06:00:00 EST 1989

Document Title: LER 87-078-01:on 871220, secondary containment isolation & standby gas treatment initiation occurred. Caused by design deficiencies. Isolations reset, safety sys secured & normal ventilation sys restored. W/890209 ltr.

Author Affiliation: NIAGARA MOHAWK POWER CORP.

Accession Number: ML17056A038

Document Date: Thu Jun 01 06:00:00 EDT 1989

Document Title: Insp Repts 50-220/89-05 & 50-410/89-05 on 890404-0512. Violations noted.Major areas inspected:licensee actions on previous insp findings,plant tours,safety sys walkdown,NRC bulletin & notice reviews & LER reviews.

Author Affiliation: NRC OFFICE OF INSPECTION & ENFORCEMENT (IE REGION I)

Accession Number: ML17056A390

Document Date: Wed Oct 25 06:00:00 EDT 1989

Document Title: LER 89-026-00:on 890926,unit experienced two ESF actuations of secondary containment isolation & standby gas treatment sys initiation. Caused by spurious signal due to electrical noise resulting from welding. Welding suspended. W/891025 ltr.

Author Affiliation: NIAGARA MOHAWK POWER CORP.

Accession Number: ML17056A396

Document Date: Wed Nov 01 06:00:00 EST 1989

Document Title: Forwards request for addl info on crane travel, per 890726 spent fuel

storage pool amend application.

Author Affiliation: NRC OFFICE OF NUCLEAR REACTOR REGULATION (NRR)

Accession Number: ML17056A463

Document Date: Tue Nov 28 06:00:00 EST 1989

Document Title: Ack receipt of 891031 response to 60-day reporting requirements of Generic Ltr 88-20 re individual plant exams. Util plan will be reviewed to determine impact on licensee & NRC resources.

Author Affiliation: NRC OFFICE OF NUCLEAR REACTOR REGULATION (NRR)

Accession Number: ML17056A536

Document Date: Tue Jan 02 06:00:00 EST 1990

Document Title: LER 89-040-00:on 891201,automatic reactor scram occurred due to APRM high neutron flux signals,causing turbine trip on reverse power by anti-motoring device.Caused by sudden zero voltage input.Work request issued.W/900102 ltr.

Author Affiliation: NIAGARA MOHAWK POWER CORP.

Accession Number: ML17056A570

Document Date: Sun Dec 31 06:00:00 EST 1989

Document Title: Monthly operating rept for Dec 1989 for Nine Mile Point Unit 2.

Author Affiliation: NIAGARA MOHAWK POWER CORP.

Accession Number: ML17056A647

Document Date: Sun Dec 31 06:00:00 EST 1989

Document Title: "Annual Tabulation of Occupational Exposure Rept & 10CFR20.407(a)(2)

Rept for 1989." W/900227 ltr.

Author Affiliation: NIAGARA MOHAWK POWER CORP.

Accession Number: ML17056A797

Document Date: Sun Dec 31 06:00:00 EST 1989

Document Title: "New York State Electric & Gas Corp 1989 Annual Rept."

Author Affiliation: NEW YORK STATE ELECTRIC & GAS CORP.

Accession Number: ML17056B042

Document Date: Mon Oct 08 06:00:00 EDT 1990

Document Title: LER 90-001-01:on 900103,unit experienced actuation of ESF. Caused by electrical interference associated w/cycling of control bldg chiller breaker. Chiller repaired & plant

change initiated.W/901008 ltr.

Author Affiliation: NIAGARA MOHAWK POWER CORP.

Accession Number: ML17056B236

Document Date: Thu Jan 10 06:00:00 EST 1991

Document Title: LER 90-024-00:on 901212, Unit 2 experienced actuation of ESF. Caused

by exterior electrical noises being induced into plant grounding grid. Verifies that no high

radiation condition existed.W/910110 ltr.

Author Affiliation: NIAGARA MOHAWK POWER CORP.

Accession Number: ML17056B281

Document Date: Mon Feb 04 06:00:00 EST 1991

Document Title: Special rept:on 910118, while mode selector switch in refuel position, main

stack & reactor bldg gaseous effluent monitoring sys instrumentation declared inoperable. Caused by component failures due to lightning strike to main stack.

Author Affiliation: NIAGARA MOHAWK POWER CORP.

Accession Number: ML17056B338

Document Date: Fri Feb 15 06:00:00 EST 1991

Document Title: LER 91-001-00:on 910118, primary containment vent & purge isolation signal from standby gas treatment sys radiation microprocessor occurred. Caused by lightning

strike on main stack tower. Tower design specs modified. W/910215 ltr.

NIAGARA MOHAWK POWER CORP. Author Affiliation:

Accession Number: ML17056B350

Mon Dec 31 06:00:00 EST 1990 Document Date:

Document Title: "Nine Mile Point Unit 2, Semiannual Radioactive Effluent Release

Rept, Jul-Dec 1990."

Author Affiliation: NIAGARA MOHAWK POWER CORP.

Accession Number: ML17056B435

Document Date: Tue Oct 08 06:00:00 EDT 1991

Document Title: Insp repts 50-220/91-17 & 50-410/91-17 on 910728-0907. Violations noted. Major areas inspected: operations, radiological controls, maint, surveillance, security, engineering & technical support & safety assessment.

Author Affiliation: NRC OFFICE OF INSPECTION & ENFORCEMENT (IE REGION I)

Accession Number: ML17056B530

Mon Nov 25 06:00:00 EST 1991 **Document Date:**

Document Title: "Emergency Preparedness Drills/Exercises."

NIAGARA MOHAWK POWER CORP. Author Affiliation:

Accession Number: ML17056B680

Thu Feb 20 06:00:00 EST 1992 Document Date:

Insp Repts 50-220/91-29 & 50-410/91-29 on 911222-920125. Major areas **Document Title:**

inspected:plant operations, radiological controls, maint, surveillance, security & safety

assessment/ quality verfication.

Author Affiliation: NRC OFFICE OF INSPECTION & ENFORCEMENT (IE REGION I)

Accession Number: ML17058A791

Document Date: Mon Jun 03 06:00:00 EDT 1991

Document Title: LER 91-009-00:on 910503,ESF actuation & secondary containment isolation occurred, causing reactor bldg recirculation unit cooler to start. Caused by spurious high

radiation signal. Work request initiated. W/910603 ltr.

Author Affiliation: NIAGARA MOHAWK POWER CORP. Accession Number: ML17058A841

Document Date: Fri Jun 28 06:00:00 EDT 1991

Document Title: LER 88-059-01:on 881025,ESF actuated,resulting in isolation of Div 1 RHR shutdown cooling subsystem. Caused by accidently contacting heat sink plates of power

source unit w/flexible conduit.Warning labels installed.W/910625 ltr.

Author Affiliation: NIAGARA MOHAWK POWER CORP.

Accession Number: ML17058A874

Document Date: Thu Aug 01 06:00:00 EDT 1991

Document Title: LER 91-009-01:on 910503,ESF actuation occurred due to spurious high radiation level signal. Caused by inadequate welder training program content. Procedure change

evaluation initiated.W/910801 ltr.

Author Affiliation: NIAGARA MOHAWK POWER CORP.

Accession Number: ML17058B081

Document Date: Wed Aug 01 06:00:00 EDT 1990

Document Title: Computer printout entitled, "Human Engineering Discrepancies."

Supporting documentation encl.

Author Affiliation: ADVANCED RESOURCE DEVELOPMENT CORP.

Accession Number: ML17058B398

Document Date: Thu Dec 20 06:00:00 EST 1990

Document Title: Rev 6 to 02-REQ-001-262-2-01, "Plant AC Electrical Distribution Sys."

Author Affiliation: NIAGARA MOHAWK POWER CORP.

Accession Number: ML17058B426

Document Date: Thu Sep 12 06:00:00 EDT 1991

Document Title: Forwards drawings requested from DJ Hess. Exide executive summary

encl.W/o encl.

Author Affiliation: EXIDE CORP.

Accession Number: ML17058B483

Document Date: Sun Aug 18 06:00:00 EDT 1991

Document Title: Transcript of 910818 NMP Nuclear Power Plant info exchange meeting in

Scriba, NY.Pp 1-164.

Author Affiliation: NRC OFFICE FOR ANALYSIS & EVALUATION OF OPERATIONAL DATA

(AEOD)

Accession Number: ML17058B611

Document Date: Tue Sep 03 06:00:00 EDT 1991

Document Title: Transcript of info meeting on 910903 in Bethesda, MD.Pp 1-175.

Author Affiliation: NRC - INCIDENT INVESTIGATION TEAM

Accession Number: ML17058B639

Document Date: Sat Sep 07 06:00:00 EDT 1991

Document Title: Transcript of info exchange meeting on 910907 in Bethesda, MD.Pp 1-

101.

Author Affiliation: NRC - INCIDENT INVESTIGATION TEAM

Accession Number: ML17058B722

Document Date: Fri Aug 31 06:00:00 EDT 1990

Document Title: Rev 2 to, "24 Volt DC Distribution."

Author Affiliation: NIAGARA MOHAWK POWER CORP.

Accession Number: ML17058B734

Document Date: Fri Jan 12 06:00:00 EST 1990

Document Title: Rev 3 to operating procedure N2-OP-97, "Reactor Protection Sys."

Author Affiliation: NIAGARA MOHAWK POWER CORP.

Accession Number: ML17058B736

Document Date: Mon Aug 18 06:00:00 EDT 1986

Document Title: Rev 2 to operating procedure N2-OP-96, "Reactor Manual Control & Rod

Position Indication Sys."

Author Affiliation: NIAGARA MOHAWK POWER CORP.

Accession Number: ML17059A091

Document Date: Thu Oct 28 06:00:00 EDT 1993

Document Title: LER 93-001-01:on 930105,ESF actuation occurred due to equipment failure.Root cause of event was radio frequency interference.Util eliminated use of radios in

switchgear rooms & evaluated use of delay circuits.W/931028 ltr.

Author Affiliation: NIAGARA MOHAWK POWER CORP.

Accession Number: ML18037A034

Document Date: Thu Sep 13 06:00:00 EDT 1984

Document Title: Forwards responses to SER Open Items 421.3,4,10,13,15,18,20, 23,25,27,28,34,36,37,42,43,44 & 47,to aid in NRC review of application for license.Info will be included in next FSAR amend.

Author Affiliation: NIAGARA MOHAWK POWER CORP.

Accession Number: ML18037A121

Document Date: Fri Feb 08 06:00:00 EST 1985

Document Title: Suppl 8 to environ rept - OL stage.

Author Affiliation: NIAGARA MOHAWK POWER CORP.

Accession Number: ML18038A091

Document Date: Wed Nov 20 06:00:00 EST 1985

Document Title: Forwards proof & review Tech Specs per 851118 discussion. Review

should identify areas inconsistent w/FSAR or as-built plant.

Author Affiliation: NRC OFFICE OF NUCLEAR REACTOR REGULATION (NRR)

Accession Number: ML18038A109

Document Date: Mon Dec 30 06:00:00 EST 1985

Document Title: Forwards marked-up proof & review Tech Specs,reflecting comments

based on review against current plant design.SAR & Tech Spec verification program

continuing. Changes will be incorporated during branch review process.

Author Affiliation: NIAGARA MOHAWK POWER CORP.

Accession Number: ML18038A372

Document Date: Tue Sep 10 06:00:00 EDT 1991

Document Title: Forwards Rev 1 to "Root Cause Rept for Exide Uninterruptible Power

Supplies (UPS) 1A,B,C,D & G Trip Event of 910813" & responses to root cause analysis,short

term corrective plan,load lists & procedures & training.

Author Affiliation: NIAGARA MOHAWK POWER CORP.

Accession Number: ML18038A374

Document Date: Mon Sep 09 06:00:00 EDT 1991

Document Title: Rev 1 to "Root Cause Rept for Exide UPS 1A,B,C,D & G Trip Event of

910813." Electrical fault on B phase main step-up transformer occurred due to improper

design.Logic power supply for subj UPS units to be modified.

Author Affiliation: NIAGARA MOHAWK POWER CORP.

Accession Number: ML18038A375

Document Date: Thu Sep 05 06:00:00 EDT 1991

Document Title: "Niagara Mohawk Nine Mile Point Unit 2 Event of 910813."

Author Affiliation: GENERAL ELECTRIC CO.

Document Report Number: NUREG-1455

Accession Number: ML18038A389

Document Date: Wed Feb 17 06:00:00 EST 1988

Document Title: LER 88-001-00:on 880120,reactor scram occurred due to actual low water level condition. Caused by design & personnel errors. Operator disciplined & mod addressed inadvertent feedwater control valve lockup. W/880217 ltr.

Author Affiliation: NIAGARA MOHAWK POWER CORP.

Accession Number: ML18038A470

Document Date: Mon May 15 06:00:00 EDT 1989

Document Title: LER 89-014-00:on 890413,unit reactor experienced reactor scram which was result of turbine trip due to actuation of generator protection circuitry. Turbine trip caused by disconnected wire. Wire relanded. W/890515 ltr.

Author Affiliation: NIAGARA MOHAWK POWER CORP.

Accession Number: ML18038A499

Document Date: Mon Dec 30 06:00:00 EST 1991

Document Title: Forwards Rev 24 to site emergency plan & Rev 15 to EPIP S-EPP-2, "Fire Fighting," Rev 13 to Emergency Preparedness Procedure S-EPP-5, "Station Evacuation" & Rev 8 to EPIP S-EPP-19, "Site Evacuation Procedure."

Author Affiliation: NIAGARA MOHAWK POWER CORP.

Accession Number: ML18041A031

Document Date: Tue Dec 13 06:00:00 EST 1994

Document Title: Forwards emergency plan maintenance procedure EPMP-EPP-08, Rev

02, "Maintenance, Testing & Operation of Oswego County Prompt Notification Sys."

Author Affiliation: NIAGARA MOHAWK POWER CORP.

Accession ML18041A286 Number:

Document Date: Mon Dec 31 06:00:00 EST 1984

Document Title: "Exide Electronics Model 1105." Supporting documentation & five oversize

drawings encl.

Author Affiliation: STONE & WEBSTER ENGINEERING CORP.

Accession Number: ML20044C678

Document Date: Sat Sep 07 06:00:00 EDT 1991

Document Title: "Main Transformer Rept for Event of 910813."

Author Affiliation: NIAGARA MOHAWK POWER CORP.

Accession Number: ML20044H209

Document Date: Mon May 24 06:00:00 EDT 1993

Document Title: Insp repts 50-220/93-06 & 50-410/93-06 on 930411-0508. Major areas inspected: plant operations, radiological controls, maint, surveillance, emergency planning, security & safety assessment/quality verification activities.

Author Affiliation: NRC OFFICE OF INSPECTION & ENFORCEMENT (IE REGION I)

Accession Number: ML20056C166

Document Date: Fri Mar 12 06:00:00 EST 1993

Document Title: Insp repts 50-220/93-01 & 50-410/93-01 on 930124-0227. Violations

noted.Major areas inspected:plant operations, radiological

controls, maintenance, surveillance, security & safety assessment/quality verification activities.

Author Affiliation: NRC OFFICE OF INSPECTION & ENFORCEMENT (IE REGION I)

Accession Number: ML20062M238

Document Date: Tue Dec 28 06:00:00 EST 1993

Document Title: Provides results of Nine Mile Point Unit 2 plant specific technical assessment for instruments assumed to operate in USAR Chapters 6 & 15 & for which Instrument Setpoint Methodology Group calculations developed, per TR NEDC-31336.

Author Affiliation: NIAGARA MOHAWK POWER CORP.

Accession Number: ML20066G358

Document Date: Tue Jun 11 06:00:00 EDT 1985

Document Title: Forwards proposed implementing license condition & listing of revs to

SER statement for plant re physical security plan.

Author Affiliation: NRC OFFICE OF NUCLEAR MATERIAL SAFETY & SAFEGUARDS

(NMSS)

Accession Number: ML20070D160

Document Date: Fri Jun 24 06:00:00 EDT 1994

Document Title: Insp repts 50-220/94-07 & 50-410/94-07 on 940417-0528. Violations noted.Major areas inspected:plant operations, maint,engineering,plant support & safety

assessment/quality verification.

Author Affiliation: NRC OFFICE OF INSPECTION & ENFORCEMENT (IE REGION I)

Accession Number: ML20073C571

Document Date: Thu Sep 08 06:00:00 EDT 1994

Document Title: Insp repts 50-220/94-13 & 50-410/94-15 on 940710-0820.No violations

noted.Major areas inspected:plant operations, maint,engineering & plant support.

Author Affiliation: NRC OFFICE OF INSPECTION & ENFORCEMENT (IE REGION I)

Accession Number: ML20080H840

Document Date: Thu Jan 26 06:00:00 EST 1984

Document Title: IE Const Appraisal Insp Rept 50-410/83-18 on 831107-19 & 28-1209. Major areas inspected: detailed exam of selected hardware subsequent to QC insps, selective exam of procedures & representative records & observation of in process work.

Author Affiliation: NRC OFFICE OF INSPECTION & ENFORCEMENT (IE REGION I), NRC OFFICE OF INSPECTION & ENFORCEMENT (IE)

Accession Number: ML20087N144

Document Date: Sat Mar 31 06:00:00 EST 1984

Document Title: Suppl 6 to environ rept - OL stage.

Author Affiliation: NIAGARA MOHAWK POWER CORP.

Accession Number: ML20091J357

Document Date: Mon Jan 06 06:00:00 EST 1992

Document Title: Identifies & assigns responsibility for generic & plant-specific actions resulting from investigations of 910813 incident at Unit 2 (NUREG-1455). Staff actions resulting from subj incident encl.

Author Affiliation: NRC OFFICE OF THE EXECUTIVE DIRECTOR FOR OPERATIONS

(EDO)

Accession Number: ML20204C399

Document Date: Wed Mar 18 06:00:00 EST 1987

Document Title: LER 86-011-01:on 861127 & 1208,automatic initiation of standby gas treatment sys Divs I & II occurred. Caused by spurious reactor bldg exhaust ventilation duct high radiation signals. Accumulator added to lines. W/870318 ltr.

Author Affiliation: NIAGARA MOHAWK POWER CORP.

Accession Number: ML031060589

Document Date: Thu Mar 17 00:00:00 EST 1994

Document Title: NRC Information Notice 1994-020: Common-Cause Failures Due to

Inadequate Design Control and Dedication.

Author Affiliation: NRC/NRR

Accession Number: ML031070324

Document Date: Fri Sep 17 00:00:00 EDT 1993

Document Title: NRC Information Notice 1993-075: Spurious Tripping of Low-Voltage

Power Circuit Breakers with GE RMS-9 Digital Trip Units.

Author Affiliation: NRC/NRR

Accession Number: ML031130479

Document Date: Fri Dec 04 00:00:00 EST 1987

Document Title: NRC Information Notice 1987-060: Depressurization of Reactor Coolant

Systems in Pressurized-Water Reactors.

Author Affiliation: NRC/NRR

Accession Number: ML031190235

Document Date: Tue Sep 24 00:00:00 EDT 1991

Document Title: NRC Information Notice 1991-060: False Alarms of Alarm Ratemeters

Because of Radiofrequency Interference.

Author Affiliation: NRC/NMSS/IMNS

Accession Number: ML031190579

Document Date: Tue Mar 05 00:00:00 EST 1991

Document Title: NRC Information Notice 1991-014: Recent Safety-Related Incidents at

Large Irradiators.

Author Affiliation: NRC/NRR

Accession Number: ML031190682

Document Date: Mon Feb 04 00:00:00 EST 1991

Document Title: NRC Information Notice 1991-007: Maintenance Deficiency Associated

with General Electric Horizontal Custom 8000 Induction Motors.

Author Affiliation: NRC/NRR

Accession Number: ML031220597

Document Date: Mon Mar 10 00:00:00 EST 1986

Document Title: NRC Information Notice 1986-015: Loss of Offsite Power Caused by

Problems in Fiber Optics Systems.

Author Affiliation: NRC/IE

Accession Number: ML031250230

Document Date: Tue Dec 02 00:00:00 EST 1986

Document Title: NRC Information Notice 1986-098: Offsite Medical Services.

Author Affiliation: NRC/IE

Accession Number: ML082670424

Document Date: Wed Feb 15 06:00:00 EST 1984

Document Title: IE Info Notice 83-63, Suppl 1, "Potential Failures of Westinghouse Type

SA-1 Differential Relays." Svc list encl.

Author Affiliation: NRC/IE