

NRC INSPECTION MANUAL

IRIB

CHANGE NOTICE 24-008

DELETED:

	<u>Number</u>	<u>Date</u>
1.	IP 30800	10/01/76
2.	IMC 2641	08/25/00

TRANSMITTED:

	<u>Number</u>	<u>Date</u>
--	---------------	-------------

TRAINING: No special training is required for any documents issued with this Change Notice.

REMARKS: IP 30800, "Initial Management Meeting Materials Licensees." This IP is outdated and no longer relevant. The oversight process for materials licensees is currently described in IMC 2800.

IMC 2641, "In-Situ Leach Facilities Inspection Program." Superseded by the new IMC 2801 Uranium Recovery and 11e.(2) Byproduct Material Facility Inspection Program, issued 10/08/2021.

EDITORIAL REVISIONS FROM PREVIOUS CHANGE NOTICES (As Required):

DISTRIBUTION:

- Standard
 Official Use Only (OUO)-Security Related Information.

Please contact: _____ Phone: _____

END