



Materials Inspection Report

1. Licensee/Location Inspected: Integrated Science Support, Inc. 14450 N. 169 Highway Smithville, MO 64089 Report Number(s) 2024001	2. NRC/Regional Office Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352
---	--

3. Docket Number(s) 030-38746	4. License Number(s) 24-35155-01	5. Date(s) of Inspection July 26, 2024
---	--	--

LICENSEE:
 The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

1. Based on the inspection findings, no violations were identified.

2. Previous violation(s) closed.

3. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements, and were assessed at Severity Level IV, in accordance with the NRC Enforcement Policy.

A. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy were satisfied.
 (Non-cited violation(s) was/were discussed involving the following requirement(s))

B. The following violation(s) is/are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
 (Violations and Corrective Actions)

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE AND DATE
LICENSEE'S REPRESENTATIVE		
NRC INSPECTOR	Zahid Sulaiman, Health Physicist	Zahid M. Sulaiman <small>Digitally signed by Zahid M. Sulaiman Date: 2024.08.20 22:09:15 -05'00'</small>
BRANCH CHIEF	Rhex Edwards, Chief, MIB	<i>Rhex Edwards</i> <small>Digitally signed by RYAN CRAFFEY Date: 2024.08.21 07:53:41 -05'00'</small>



Materials Inspection Record

1. Licensee Name: Integrated Science Support, Inc.		2. Docket Number(s): 030-38746		3. License Number(s) 24-35155-01	
4. Report Number(s): 2024001			5. Date(s) of Inspection: July 26, 2024		
6. Inspector(s): Zahid Sulaiman, Health Physicist		7. Program Code(s): 03220	8. Priority: 5	9. Inspection Guidance Used: 87126	
10. Licensee Contact Name(s): Greg Sackett, RSO		11. Licensee E-mail Address: gsackett@issphysics.com		12. Licensee Telephone Number(s): 816-390-9011	

13. Inspection Type: <input type="checkbox"/> Initial		14. Locations Inspected: <input type="checkbox"/> Hybrid		15. Next Inspection Date (MM/DD/YYYY):	
<input checked="" type="checkbox"/> Routine	<input type="checkbox"/> Announced	<input checked="" type="checkbox"/> Main Office	<input type="checkbox"/> Field Office	07/26/2029 <input checked="" type="checkbox"/> Normal <input type="checkbox"/> Extended <input type="checkbox"/> Reduced <input type="checkbox"/> No change	
<input type="checkbox"/> Non-Routine	<input checked="" type="checkbox"/> Unannounced	<input type="checkbox"/> Temporary Job Site	<input type="checkbox"/> Remote		

16. Location(s) Inspected List:
Main office: 14450 N. 169 Highway, Smithville, MO 64089


17. Scope and Observations:
This was an unannounced routine inspection of a licensee that was authorized to possess byproduct material with Atomic Numbers 1-83 incident to the performance of test for leakage on customers sealed sources as a commercial service. The licensee was staffed with three full-time health physicists who performed quarterly audits of nuclear medicine and sealed source leak tests. At the time of the inspection, the licensee had 15 nuclear medicine clients and one industrial facility client in Missouri and Kansas areas.

PERFORMANCE OBSERVATIONS

This inspection consisted of interviews with the RSO; a review of select records; a tour of the facility; and independent measurements. The inspector reviewed radioactive materials inventory, certificates of instrument calibration performed by an authorized outside vendor, and well counter efficiency test records. The RSO described the licensee's internal training program, and routine radiation protection program audits performed for their customers. The inspector performed independent radiation measurements and the results were within the regulatory limits. Interviews with licensee staff and through discussion indicated the licensee's staff to be knowledgeable of radiation protection principles and regulatory requirements.

No violations of NRC requirements were identified as a result of this inspection.

Signature and Date - Branch Chief



Digitally signed by RYAN CRAFFEY
Date: 2024.08.21 07:52:29 -05'00'