

Good morning,

Please see attached service documentation referencing the removal of two Perkin Elmer LSC Ba133 sources, device IDs 414168 and 414169.

Our recipient ID in the general license database is 716170.

Please let me know if you have any questions.

Thank you,

-Rachael

Rachael Perriello

Safety, Health and Environmental Management Program Manager

US EPA | ORD | CCTE

Great Lakes Toxicology & Ecology Division

6201 Congdon Blvd | Duluth, MN 55804

p: 218.529.5050

e: perriello.rachael@epa.gov



Field Service Report

PerkinElmer Health Sciences, Inc. 001
 710 Bridgeport Avenue
 SHELTON
 06484-4794 CT US
 Telephone : (800) 762-4000 Fax : (203) 944-4914
 V.A.T Code

Service Order No.	Activity Code	Desired Start Date	Model	Serial No.
330320752	SLS	23-Mar-2012	TRICARB2500	402895
Engineer Name		Work Center	Contract No.	Expiration Date
YODER, KLAUS M. (VM)		US03339		
Customer Name/Address			Bill To Name/Address	
U S EPA,PROTECTION AGENCY, 6201 CONGDON BLVD, DULUTH, MN, 55804 US			U S EPA,RTP FINANCE CENTER, 4930 OLD PAGE RD (D143-02), DURHAM, NC, 27711 US	
Contact Name	Phone No.	Email Address	Customer PO No.	
DENNY, JEFF	218-529-5124			

Time Confirmation

	Activity Type	Actual Work	Actual Start Date	Actual Start Time	Actual Finish Date	Actual Finish Time	Time Zone	Confirmation Text
x	SRV-SA Inter-department Labor	1	Mar 22, 2012	12:00:00 PM	Mar 22, 2012	01:00:00 PM	CDT	PelleT removal from Tricarb trade in on new installation of

+

Fault Coding

	Symptom Group	Symptom Code	Problem Group	Problem Code	Problem Text	Cause Group	Cause Code	Cause Text
x	Radiometric Detect	Mechanical Proble	RRD Mechanical F	Sample C	Pellet Removal	Job Completion C	Job Completed~J	Removed Source

+

Material Confirmation

	Plant	Storage Location	Material	Material Description	Requirement Quantity	Requirement Quantity Unit	Unit Price	Total Price	Serial/ Batch No.
x	US12	F466	7001394	PELLET RETURN KIT (FIELD)	1	Set of items (r	1663.00	1663	

+

Call Complete	Labor Hours	Travel Hours	Maintenance Performed			
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	1	0	<input type="checkbox"/> Maintenance/IPV PTC Left with Customer			
Service Engineer Signature		Date		Quantity	Unit Price	Total
		Mar 22, 2012	Total Parts			1663.00
			Labor Hours	1	380.00	380.00
Customer Signature		Date	Travel Hours	0	385.00	0.00
		Mar 23, 2012	Total			380
Customer Acknowledgment of receipt of the above repair/replacement.			V.A.T at current ra			0
			Total			2043
Additional Information						
.						

Short description : MD-PELLET REMOVAL per CSE

Mar 23, 2012 02:19:47 PM



Field Service Report

PerkinElmer Health Sciences, Inc.
 710 Bridgeport Avenue
 SHELTON
 06484-4794 CT US

001

Telephone : (800) 762-4000

Fax : (203) 944-4914

V.A.T Code

Service Order No.	Activity Code	Desired Start Date	Model	Serial No.
330320752	SLS	23-Mar-2012	TRICARB2500	402895
Engineer Name		Work Center	Contract No.	Expiration Date
YODER, KLAUS M. (VM)		US03339		
Customer Name/Address			Bill To Name/Address	
U S EPA, PROTECTION AGENCY, 6201 CONGDON BLVD, DULUTH, MN, 55804 US			U S EPA, RTP FINANCE CENTER, 4930 OLD PAGE RD (D143-02), DURHAM, NC, 27711 US	
Contact Name	Phone No.	Email Address	Customer PO No.	
DENNY, JEFF	218-529-5124			

Confirmation Text

SRV-SA 1hrs Mar 22, 2012 12:00:00 PM Mar 22, 2012 01:00:00 PM

Pellet removal from Tricarb trade in on new installation of Tricarb



Field Service Report

PerkinElmer Health Sciences, Inc. 001
 710 Bridgeport Avenue
 SHELTON
 06484-4794 CT US
 Telephone : (800) 762-4000 Fax : (203) 944-4914
 V.A.T Code

Service Order No.	Activity Code	Desired Start Date	Model	Serial No.
330320751	SLS	23-Mar-2012	TRICARB2500	404864
Engineer Name		Work Center	Contract No.	Expiration Date
YODER, KLAUS M. (VM)		US03339		
Customer Name/Address			Bill To Name/Address	
U S EPA, PROTECTION AGENCY, 6201 CONGDON BLVD, DULUTH, MN, 55804 US			U S EPA, RTP FINANCE CENTER, 4930 OLD PAGE RD (D143-02), DURHAM, NC, 27711 US	
Contact Name	Phone No.	Email Address	Customer PO No.	
DENNY, JEFF	218-529-5124			

Time Confirmation

	Activity Type	Actual Work	Actual Start Date	Actual Start Time	Actual Finish Date	Actual Finish Time	Time Zone	Confirmation Text
x	SRV-SA Inter-department Labor	1	Mar 22, 2012	01:00:00 PM	Mar 22, 2012	02:00:00 PM	CDT	Pellet Removal on trade in of new Tricarb

+

Fault Coding

	Symptom Group	Symptom Code	Problem Group	Problem Code	Problem Text	Cause Group	Cause Code	Cause Text
x	Radiometric Detect	Mechanical Proble	RRD Mechanical F	Sample C	Pellet removal	Job Completion C	Job Completed~J	Removed Source

+

Material Confirmation

	Plant	Storage Location	Material	Material Description	Requirement Quantity	Requirement Quantity Unit	Unit Price	Total Price	Serial/ Batch No.
x	US12	F466	7001394	PELLET RETURN KIT (FIELD)	1	Set of items (r	1663.00	1663	

+

Call Complete	Labor Hours	Travel Hours	Maintenance Performed			
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	1	0	<input type="checkbox"/> Maintenance/IPV PTC Left with Customer			
Service Engineer Signature	Date		Quantity	Unit Price	Total	
	Mar 22, 2012		Total Parts		1663.00	
			Labor Hours	1	380.00	380.00
Customer Signature	Date		Travel Hours	0	385.00	0.00
	Mar 23, 2012		Total		380	
Customer Acknowledgment of receipt of the above repair/replacement.			V.A.T at current ra		0	
			Total		2043	
Additional Information						

Short description : MD-PELLET REMOVAL per CSE

Mar 23, 2012 01:57:57 PM



Field Service Report

PerkinElmer Health Sciences, Inc. 001
 710 Bridgeport Avenue
 SHELTON
 06484-4794 CT US
 Telephone : (800) 762-4000 Fax : (203) 944-4914
 V.A.T Code

Service Order No.	Activity Code	Desired Start Date	Model	Serial No.
330320751	SLS	23-Mar-2012	TRICARB2500	404864
Engineer Name		Work Center	Contract No.	Expiration Date
YODER, KLAUS M. (VM)		US03339		
Customer Name/Address			Bill To Name/Address	
U S EPA,PROTECTION AGENCY, 6201 CONGDON BLVD, DULUTH , MN, 55804 US			U S EPA,RTP FINANCE CENTER, 4930 OLD PAGE RD (D143-02), DURHAM , NC, 27711 US	
Contact Name	Phone No.	Email Address	Customer PO No.	
DENNY, JEFF	218-529-5124			

Confirmation Text

SRV-SA 1hrs Mar 22, 2012 01:00:00 PM Mar 22, 2012 02:00:00 PM
 Pellet Removal on trade in of new Tricarb