

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED  CAMC Cardiology - Beckley 1834 Harper Road Beckley, WV 25801-3386		2. NRC/REGIONAL OFFICE  Region 1 475 Allendale Rd Suite 102 King of Prussia, PA 19406	
REPORT NUMBER(s) 2025001			
3. DOCKET NUMBER(S)  030-36541	4. LICENSE NUMBER(S)  47-30903-01	5. DATE(S) OF INSPECTION  12/03/2025	

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE'S REPRESENTATIVE	Jebrian Karam, M.D.		11/21/26
NRC INSPECTOR	Netra Patel	 NETRA PATEL	Digitally signed by NETRA PATEL Date: 2026.01.14 10:48:54 -05'00'
BRANCH CHIEF	Monica Ford	Monica Ford	Digitally signed by Monica Ford Date: 2026.01.15 13:45:07 -05'00'

## SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

<b>1. LICENSEE/LOCATION INSPECTED</b> CAMC Cardiology - Beckley 1834 Harper Road Beckley, WV 25801-3386		<b>2. NRC/REGIONAL OFFICE</b> Region 1 475 Allendale Rd Suite 102 King of Prussia, PA 19406
<b>REPORT NUMBER(s)</b> 2025001		
<b>3. DOCKET NUMBER(S)</b> 030-36541	<b>4. LICENSE NUMBER(S)</b> 47-30903-01	<b>5. DATE(S) OF INSPECTION</b> 12/03/2025; Exit: 01/14/2026

**LICENSEE:**

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violations(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

Non-cited violation(s) were discussed involving the following requirement(s):

- 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with the NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11. (Violations and Corrective Actions)

1. License Condition 14A of NRC License No. 07-16862-01 Amendment No. 47-30903-01 Amendment No.1 requires the licensee to conduct its program in accordance with the statements, representations, and procedures contained in the documents, including any closures.

In application dated June 10, 2024, the license committed to perform a prospective evaluation demonstration that unmonitored individuals are not likely to receive, in any one year, a radiation dose in excess of 10% of the allowable limits in 10 CFR Part 20 or we will provide dosimetry that meets the requirements listed under "Criteria" in NUREG-1556, Vol. 9 "Consolidated Guidance About Materials Licenses: Program-Specific Guidance About Medical Use Licenses" dated September 2019.

Contrary to the above, as of the date of the inspection on December 03, 2025, the licensee failed to perform a prospective evaluation demonstrating that unmonitored individuals are not likely to receive, in one year, a radiation dose in excess of 10% of the allowable limits in 10 CFR Part 20 or provide dosimetry that meets the requirements listed under "Criteria" in NUREG-1556, Vol. 9, Revision 2. Specifically, the licensee did not provide ring dosimeter to an authorized user and did not maintain documentation demonstrating that a prospective evaluation had been performed to confirm that these individuals would not exceed 10 percent of the applicable dose limits.

This is a Severity Level IV violation (Section 6.7.d).

For corrective action, the licensee immediately provided a ring dosimeter to the authorized user.