
RESPONSE TO REQUEST FOR ADDITIONAL INFORMATION

04/13/2026

**SAFETY SYSTEM DIGITAL PLATFORM
- MELTAC (MITSUBISHI ELECTRIC TOTAL ADVANCED CONTROLLER) -
ASPM and CGD**

Mitsubishi Electric Corporation

EPID: L-2024-TOP-0036
RAI NO.: RAI 10
DATE OF RAI ISSUE: 03/10/2026

RAI 10

Background and Issue: Criterion XVI, "Corrective Action," of Appendix B to 10 CFR Part 50 states:

"Measures shall be established to assure that conditions adverse to quality, such as failures, malfunctions, deficiencies, deviations, defective material and equipment, and nonconformances are promptly identified and corrected. In the case of significant conditions adverse to quality, the measures shall assure that the cause of the condition is determined and corrective action taken to preclude repetition. The identification of the significant condition adverse to quality, the cause of the condition, and the corrective action taken shall be documented and reported to appropriate levels of management."

Section 16 of the Quality Manual, Revision 2, states, in part, that [[

]].

The NRC staff reviewed the above information and determined that the wording used is unclear.

Request: Please provide clarification to clarify:


1. What constitutes not meeting "quality requirements."
2. Whether adverse conditions need to be promptly corrected as well.
3. Whether all adverse conditions receive a cause investigation and have corrective actions to preclude recurrence.
4. To what are "these activities" referring.

ANSWER:

1. [[]].
MELCO will revise the Quality Manual to clarify the response above.
2. [[]].
MELCO will revise the Quality Manual to clarify the response above.
3. [[]].
MELCO will revise the Quality Manual to clarify the response above.
4. [[]].
MELCO will revise the Quality Manual to clarify the response above.

Impact on Topical Report and/or Support Documents.

MELCO will revise Section 16 of Part II of the Quality Manual.



RAI 10-1

RAI 10-2

RAI 10-4

RAI 10-3

RAI 10-2