James A. FitzPatrick Nuclear Power Plant 268 Lake Road P.O. Box 41 Lycoming, New York 13093 315-342-3840



Michael J. Colomb Site Executive Officer

October 22, 1999 JAFP-99-0284

U.S. Nuclear Regulatory Commission Attn: Document Control Desk Mail Station P1-137 Washington, D.C. 20555

SUBJECT:

James A. FitzPatrick Nuclear Power Plant

Docket No. 50-333

Change to Commitment Made in Response to NRC Bulletin 96-03

Potential Plugging of ECCS Suction Strainers

Reference:

NYPA Letter, M. J. Colomb to the NRC, "Information Regarding NRC

Bulletin 96-03 Potential Plugging of ECCS Suction Strainers," (JAFP-

98-0306), dated September 16, 1998.

Dear Sir:

The Authority is revising a commitment made in the reference letter. Specifically, the Authority previously committed to desludge the torus and inspect the ECCS suction strainers during the R14/C15 Refueling Outage (RFO). This RFO is scheduled to commence in Fall 2000. The Authority now plans to desludge the torus every other RFO. This is based on the margin in the allowance for sludge accumulation in the design calculations, Foreign Material Exclusion (FME) Controls, Suppression Pool cleanliness, future inspections plans, and the installation of large capacity passive strainers for the Emergency Core Cooling Systems during the R13/C14 RFO.

The Authority will inspect the ECCS suction strainers and supporting structures during the R14/C15 RFO. The Authority believes that adequate controls are in place which ensure suppression pool cleanliness.

Based on the above, implementing this commitment change will not adversely affect Emergency Core Cooling System (ECCS) performance and the ECCS will continue to perform the safety function of long-term decay heat removal following a Loss of Coolant Accident. The Authority has concluded that no safety concerns exist with this commitment change.

100 J

U.S. Nuclear Regulatory Commission

Attn: Document Control Desk

Subject:

Information Regarding NRCB 96-03

Page -2-

Attachment 1 contains the commitment change made by the Authority in this letter. If you have any questions, please contact Mr. George Tasick at (315) 349-6572.

Very Truly Yours,

Michael J. Colomb Site Executive Officer

MJC:JJC:las

cc:

Regional Administrator U.S. Nuclear Regulatory Commission 475 Allendale Road King of Prussia, PA 19406

Office of the Resident Inspector U.S. Nuclear Regulatory Commission P.O. Box 136 Lycoming, New York 13093

Mr. Guy Vissing, Project Manager Project Directorate I Division of Licensing Project Management U.S. Nuclear Regulatory Commission Mail Stop OWFN 8 C2 Washington, DC 20555

Attachment Tto JAFP-99-0284

LIST OF COMMITMENTS

Commitment No.	Description	Due Date
JAFP-99-0284-01	The torus will be desludged.	Every Other RFO starting with the R15/C16 RFO.
JAFP-99-0284-02	The ECCS suction strainers and supporting structures will be inspected.	R14/C15 RFO.