



Gary R. Peterson
Vice President

Duke Power
Catawba Nuclear Station
4800 Concord Road
York, SC 29745
(803) 831-4251 OFFICE
(803) 831-3426 FAX

November 3, 1999

U. S. Nuclear Regulatory Commission
ATTENTION: Document Control Desk
Washington, DC 20555-0001

SUBJECT: Duke Energy Corporation
Catawba Nuclear Station Unit 1 and 2
Docket Nos. 50-413, 50-414
Licensee Event Report 413/99-006-01

Attached please find the supplemental Licensee Event Report 413/99-006-01 entitled "Control Room Ventilation System Inoperability due to Spurious Closure of Intakes Resulting in an Entry into Technical Specification 3.0.3". The causes of this event have been determined to be equipment failure and failure to follow an administrative procedure. The planned corrective actions section of this LER contains the only commitments in this report.

Questions regarding this Licensee Event Report should be directed to M. S. Purser at (803) 831-4015.

Sincerely,

Richard L Swigart for G. R. Peterson

G. R. Peterson

Attachment

IE22