



W. R. McCollum, Jr.
Vice President

Duke Power

Oconee Nuclear Site
7800 Rochester Highway
Seneca, SC 29672
(864) 885-3107 OFFICE
(864) 885-3564 FAX

November 1, 1999


U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Subject: Oconee Nuclear Station, Unit 1
Docket Nos. 50-269
Special Report: Steam Generator Overfill
Protection Inoperable
Problem Investigation Process No.: O-99-3857

In accordance with Selected Licensee Commitment (SLC) 16.7.5, "Steam Generator [SG] Overfill Protection," Required Action B.1, attached is a report concerning inoperability of the Unit 1 overfill protection for Unit 1, SG "B". SLC 16.7.5 requires a report to the NRC if the system is inoperable for greater than 72 hours. This report provides the cause of the inoperability and actions to restore the system.

This event was of little significance to the health and safety of the public.

Very truly yours,



W. R. McCollum, Jr.

Attachment

JE22

USNRC Document Control Desk
November 1, 1999

Page 2

cc: Mr. Luis A. Reyes
Administrator, Region II
U.S. Nuclear Regulatory Commission
61 Forsyth Street, S. W., Suite 23T85
Atlanta, GA 30303

Mr. D. E. LaBarge
U.S. Nuclear Regulatory Commission
Office of Nuclear Reactor Regulation
Washington, D.C. 20555

Mr. M. C. Shannon
NRC Senior Resident Inspector
Oconee Nuclear Station

INPO Records Center
700 Galleria Parkway, NW
Atlanta, GA 30339-5957