

REGION I
NMSS LICENSEE EVENT REPORT

B12

License No. N/A
Docket No. 999-90001
MLER-RI 999

LICENSEE International Paper, Inc

EVENT DESCRIPTION Lost Generally Licensed Gauge

EVENT DATE 3/2/99 REPORT DATE 3/4/99

1. REPORTING REQUIREMENT

- 10 CFR 20.2201 Theft or Loss
- 10 CFR 20.2203 30 Day Report
- 10 CFR 30.50 Report
- 10 CFR 34.101
- Other gauge subsequently found
- 10 CFR 35.33 Misadministration
- License Condition
- 10 CFR 36.83

2. REGION I RESPONSE

- Immediate Site Inspection Inspector/Date _____
- Special Inspection Inspector/Date _____
- Telephone Inquiry Inspector/Date E. Reber
- Preliminary Notification
- Information Entered on the Region I Log
- Review at Next Routine Inspection
- Report Referred to _____
- Daily Report

3. REPORT EVALUATION

- Description of Event
- Levels of RAM Involved
- Cause of Event
- Corrective Actions
- Calculation Adequate
- Letter to Licensee Requesting Additional Information

4. SPECIAL INSTRUCTIONS OR COMMENTS

Completed by Cheryl Burack
Reviewed by E. Miller

Date 4/8/99
Date 4/8/99

IE-72
REGION I

g:\las\mlerform
(Revised 1/6/95)

PPR QA 9999