



Entergy Operations, Inc.
1448 S.R. 333
Russellville, AR 72801
Tel 501 858-5000

December 2, 1999

2CAN129905

U. S. Nuclear Regulatory Commission
Document Control Desk
Mail Station OP1-17
Washington, DC 20555

Subject: Arkansas Nuclear One - Unit 2
Docket No. 50-368
License No. NPF-6
2P99 Steam Generator Plugged Tube Report

Gentlemen:

Tubing inspections of the Arkansas Nuclear One, Unit 2 (ANO-2), steam generators (SGs) were performed during the 2P99 scheduled mid-cycle outage during November 1999. NEI 97-06, "Steam Generator Program Guidelines," Rev. 0, requires the number of tubes plugged in each SG to be reported to the NRC within 15 days of the completion of the inspection. As a result of the 2P99 SG inspections, 60 tubes in the "A" SG and 150 tubes in the "B" SG were plugged. ANO-2 Technical Specification 4.4.5.0 requires the results of the 2P99 inspection to be reported within 30 days of entering Mode 4. This additional report will be submitted by December 21, 1999.

Very truly yours,

Jimmy D. Vandergrift
Director, Nuclear Safety

JDV/jjd

A001

PDL A000005000368

U. S. NRC
December 2, 1999
2CAN129905 Page 2

cc: Mr. Ellis W. Merschoff
Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 400
Arlington, TX 76011-8064

NRC Senior Resident Inspector
Arkansas Nuclear One
P.O. Box 310
London, AR 72847

Mr. Chris Nolan
NRR Project Manager Region IV/ANO-2
U. S. Nuclear Regulatory Commission
NRR Mail Stop 04-D-03
One White Flint North
11555 Rockville Pike
Rockville, MD 20852