

June 20, 2000

MEMORANDUM TO: William D. Beckner, Chief  
Technical Specifications Branch  
Division of Regulatory Improvement Programs  
Office of Nuclear Reactor Regulation

FROM: Guy S. Vissing, Senior Project Manager, Section 1 */RAI/*  
Project Directorate I  
Division of Licensing Project Management  
Office of Nuclear Reactor Regulation

SUBJECT: CLOSURE OF THE FOLLOWING FITZPATRICK ITS BEYOND SCOPE  
ISSUES:

<u>ISSUE</u>	<u>TAC NO.</u>	<u>ITS ISSUE</u>
BSI-01	MA8119	ITS 3.3.5.1-02
BSI-02	MA8120	ITS 3.3.5.1-03
BSI-03	MA8121	ITS 3.3.5.1-04
BSI-04	MA8122	ITS 3.3.5.1-05
BSI-05	MA8123	ITS 3.3.5.1-06
BSI-06	MA8125	ITS 3.3.5.1-06
BSI-07	MA8126	ITS 3.3.6.1-07
BSI-18	MA8137	ITS 3.3.1.1 TABLE, FUNCTION 5
BSI-19	MA8138	ITS 3.3.1.1 TABLE, FUNCTION 10
BSI-23	MA8142	ITS 3.3.4.1-1

The NRC letter dated December 10, 1999, requested additional information (RAI) related to the subject identified ITS sections that were considered beyond the scope of the current technical specification conversion to the improved technical specifications. The Electrical & Instrumentation and Controls Branch (EEIB) was requested to evaluate the subject beyond scope issues (BSIs). The memorandum from Evangelos Marinos, EEIB, dated June 12, 2000, ADAMS Accession No. **ML003721794**, provides safety evaluations (SEs) for these issues. A SE for BSI-03 that addressed the sequential loading timers for the residual heat removal and core spray pump timers was provided by Dale Thatcher's, EEIB memorandum of June 5, 2000, ADAMS Accession No. **ML003720995**. Thus, as these memoranda provide the necessary SEs to close out these issues, we can close the subject TAC Nos.

Docket No. 50-333

June 20, 2000

MEMORANDUM TO: William D. Beckner, Chief  
Technical Specifications Branch  
Division of Regulatory Improvement Programs  
Office of Nuclear Reactor Regulation

FROM: Guy S. Vissing, Senior Project Manager, Section 1 */RAI/*  
Project Directorate I  
Division of Licensing Project Management  
Office of Nuclear Reactor Regulation

SUBJECT: CLOSURE OF THE FOLLOWING FITZPATRICK ITS BEYOND SCOPE  
ISSUES:

<u>ISSUE</u>	<u>TAC NO.</u>	<u>ITS ISSUE</u>
BSI-01	MA8119	ITS 3.3.5.1-02
BSI-02	MA8120	ITS 3.3.5.1-03
BSI-03	MA8121	ITS 3.3.5.1-04
BSI-04	MA8122	ITS 3.3.5.1-05
BSI-05	MA8123	ITS 3.3.5.1-06
BSI-06	MA8125	ITS 3.3.5.1-06
BSI-07	MA8126	ITS 3.3.6.1-07
BSI-18	MA8137	ITS 3.3.1.1 TABLE, FUNCTION 5
BSI-19	MA8138	ITS 3.3.1.1 TABLE, FUNCTION 10
BSI-23	MA8142	ITS 3.3.4.1-1

The NRC letter dated December 10, 1999, requested additional information (RAI) related to the subject identified ITS sections that were considered beyond the scope of the current technical specification conversion to the improved technical specifications. The Electrical & Instrumentation and Controls Branch (EEIB) was requested to evaluate the subject beyond scope issues (BSIs). The memorandum from Evangelos Marinos, EEIB, dated June 12, 2000, ADAMS Accession No. **ML003721794**, provides safety evaluations (SEs) for these issues. A SE for BSI-03 that addressed the sequential loading timers for the residual heat removal and core spray pump timers was provided by Dale Thatcher's, EEIB memorandum of June 5, 2000, ADAMS Accession No. **ML003720995**. Thus, as these memoranda provide the necessary SEs to close out these issues, we can close the subject TAC Nos.

Docket No. 50-333

DISTRIBUTION:

PDI-1 R/F  
RidsNrrPMGVissing  
EMarinos  
DThatcher  
NLe

Accession Number: ML003725449

OFC	PDI-1/PM	PDI-1/LA	PDI-1/SC
NAME	GVissing:bd	SLittle	MGamberoni
DATE	6/19/00	6/19/00	6/19/00

Document Name: C:\BSIA8119.wpd  
OFFICIAL RECORD COPY