



## Emerging Issues: Materials and Mechanical

Michele G. Evans, Session Chair  
2008 RIC

1

---

---

---

---

---

---

---

---



## RIC 2008 Dissimilar Metal Butt Welds

Ted Sullivan, SLS  
Division of Component Integrity  
Office of Nuclear Reactor Regulation  
March 11, 2008

2

---

---

---

---

---

---

---

---



### Background

- Dissimilar metal (DM) welds made with Alloy 82/182 have experienced cracking since mid-1980s
- Cracking in Alloy 82/182 butt welds (BW) has been experienced at many plants since 2000
- Prior to 2006 butt weld inspection schedules based on ASME Code, Section XI

3

---

---

---

---

---

---

---

---

## Pressurizer Top Head Nozzles



4

---

---

---

---

---

---

---

---

## Near Term Approach

- In late 2005 industry implemented initiative MRP-139 with more aggressive inspection schedules
  - Base line inspection schedules based on temperature and size
  - On-going frequency based on mitigation method applied to weld
- Staff relying on MRP-139 in near term
- NRC issued TI 2515-172 to regions

5

---

---

---

---

---

---

---

---

## Longer Term Approach

- NRC staff requested ASME Code, Section XI, to develop a code case for inspection of Alloy 82/182 butt welds
  - Code Case under active development and nearing completion
  - If acceptable, NRC staff will incorporate code case in 10 CFR 50.55a

6

---

---

---

---

---

---

---

---



## Wolf Creek Evaluation

- Inspections in Oct 2006 at Wolf Creek performed prior to weld overlay mitigation per MRP-139
- Apparently large circ flaws found in pressurizer safety, relief, and surge nozzle welds
- Based on industry and NRC advanced finite element fracture mechanics analyses, NRC staff agreed to industry planned inspection schedule

7

---

---

---

---

---

---

---

---