

December 4, 2002

Mr. Otto L. Maynard
President and Chief Executive Officer
Wolf Creek Nuclear Operating Corporation
Post Office Box 411
Burlington, KS 66839

SUBJECT: WOLF CREEK GENERATING STATION - RESPONSE TO NRC BULLETIN
2002-02, "REACTOR PRESSURE VESSEL HEAD AND VESSEL HEAD
PENETRATION NOZZLE INSPECTION PROGRAMS" (TAC NO. MB5938)

Dear Mr. Maynard:

On August 9, 2002, the U.S. Nuclear Regulatory Commission (NRC) issued Bulletin 2002-02, "Reactor Pressure Vessel Head and Vessel Head Penetration Nozzle Inspection Programs." The Bulletin requested addressees to provide information related to their reactor pressure vessel (RPV) head and vessel head penetration (VHP) nozzle inspection programs for their respective facilities, including a summary discussion of inspection program plans to supplement their required visual inspections with non-visual nondestructive examination methods, or justification for reliance on visual examinations as the primary method to detect degradation. Addressees were requested to respond to Item (1) of the Bulletin within 30 days of its issuance, or within 15 days of its issuance, to provide an alternative course of action, including the basis for acceptability of the proposed action.

By letter dated September 11, 2002 (ET 02-0037), you provided a response to Item (1) of the Bulletin, providing your plans to perform RPV head and VHP nozzle inspections at Wolf Creek. The response also indicated that the plant is in the category of plants considered to have low susceptibility to RPV head and VHP cracking, based on a susceptibility ranking of less than 8 effective degradation years (EDY). Specifically, you stated that Wolf Creek had 2.4 EDY as of September 9, 2002, in accordance with the Electric Power Research Institute (EPRI) Materials Reliability Program (MRP) Report MRP-48.

The NRC staff has reviewed your response to Item (1) of the Bulletin. In that response, you stated a 100% bare metal visual examination of the RPV head (i.e., 100% of the carbon steel surface and 100% of the interface area between the head penetrations and the carbon steel on top of the head) was performed during Refueling Outage No. 12, which was conducted in April 2002. The staff finds that this inspection provides reasonable assurance that existing regulatory requirements are met, and there is adequate protection of public health and safety.

The staff notes that your justification for reliance on visual examinations and long-term inspection plans relies on the EPRI MRP inspection plan for pressurized water reactor RPV upper head penetrations. In your letter dated September 11, 2002, you committed to conduct a MRP inspection plan "supplemental visual examination" in Refueling Outage No. 14, which is currently scheduled for Spring 2005, and to submit the inspection scope and results within 30 days after plant restart from that outage. Because the staff has not completed its review of the MRP inspection plan, it has not made a determination on the adequacy of the program for ensuring applicable regulatory requirements are met. Therefore, the staff's assessment of your

Mr. Otto L. Maynard

- 2 -

justification and the adequacy of your long-term inspection program plans will be determined upon completion of the staff's review of the MRP proposed inspection plan.

Also, Item (2) of Bulletin 2002-02 requested that you report to the Commission your inspection scope and results within 30 days after plant restart following the next inspection of the RPV head and VHP nozzles. The inspection conducted in Refueling Outage No. 12 was conducted in response to Bulletin 2002-01 and the results of that inspection were submitted May 24, 2002 (CT 02-0029). The staff finds that your report submitted in response to Item 2.A of Bulletin 2002-01 satisfies the report requested in Item (2) of Bulletin 2002-02.

If you have any questions on this issue or this letter, contact me at (301) 415-1307.

Sincerely,

/RA/

Jack Donohew, Senior Project Manager, Section 2
Project Directorate IV
Division of Licensing Project Management
Office of Nuclear Reactor Regulation

Docket No. 50-482

cc: See next page

Mr. Otto L. Maynard

- 2 -

justification and the adequacy of your long-term inspection program plans will be determined upon completion of the staff's review of the MRP proposed inspection plan.

Also, Item (2) of Bulletin 2002-02 requested that you report to the Commission your inspection scope and results within 30 days after plant restart following the next inspection of the RPV head and VHP nozzles. The inspection conducted in Refueling Outage No. 12 was conducted in response to Bulletin 2002-01 and the results of that inspection were submitted May 24, 2002 (CT 02-0029). The staff finds that your report submitted in response to Item 2.A of Bulletin 2002-01 satisfies the report requested in Item (2) of Bulletin 2002-02.

If you have any questions on this issue or this letter, contact me at (301) 415-1307.

Sincerely,

/RA/

Jack Donohew, Senior Project Manager, Section 2
Project Directorate IV
Division of Licensing Project Management
Office of Nuclear Reactor Regulation

Docket No. 50-482

cc: See next page

DISTRIBUTION

PUBLIC	BPham
PDIV-2 Reading	MMarshall
RidsNrrDlpm (JZwolinski/TMarsh)	
RidsNrrDlpmPdiv(WRuland)	SBloom
RidsNrrPMJDonohew	AMendiola
RidsNrrLAEPeyton	WReckley
RidsOgcRp	AHiser
RidsAcrcAcnwMailCenter	TChan
RidsRgn4MailCenter	TTate
DGraves, RIV	

ACCESSION NO.: ML023450444

NRR-106

OFFICE	PDIV-2/PM	PDIV-2/LA	DLPM/LPM	EMCB/SC	PDIV-2/SC
NAME	JDonohew:rkb	EPeyton	TTate	TChan	SDembek
DATE	11/27/2002	11/27/02	11/27/02	12/03/02	12/4/02

DOCUMENT NAME: C:\ORPCheckout\FileNET\ML023450444.wpd

OFFICIAL RECORD COPY

Wolf Creek Generating Station

cc:

Jay Silberg, Esq.
Shaw, Pittman, Potts & Trowbridge
2300 N Street, NW
Washington, D.C. 20037

Vice President Operations
Wolf Creek Nuclear Operating Corporation
P.O. Box 411
Burlington, KS 66839

Regional Administrator, Region IV
U.S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, TX 76011

Superintendent Licensing
Wolf Creek Nuclear Operating Corporation
P.O. Box 411
Burlington, KS 66839

Senior Resident Inspector
U.S. Nuclear Regulatory Commission
P.O. Box 311
Burlington, KS 66839

U.S. Nuclear Regulatory Commission
Resident Inspectors Office
8201 NRC Road
Steedman, MO 65077-1032

Chief Engineer
Utilities Division
Kansas Corporation Commission
1500 SW Arrowhead Road
Topeka, KS 66604-4027

Office of the Governor
State of Kansas
Topeka, KS 66612

Attorney General
Judicial Center
301 S.W. 10th
2nd Floor
Topeka, KS 66612

County Clerk
Coffey County Courthouse
Burlington, KS 66839

Vick L. Cooper, Chief
Radiation Control Program, RCP
Kansas Department of Health
and Environment
Bureau of Air and Radiation
1000 SW Jackson, Suite 310
Topeka, KS 66612-1366