


### Seabrook 1

#### 1Q/2001 Performance Indicators

Licensee's General Comments: Report of fault exposure hours for EFW Pp "A" due to overspeed trip on 3/5/01.

#### Unplanned Scrams per 7000 Critical Hrs




Thresholds: White > 3.0 Yellow > 6.0 Red > 25.0

#### Notes

Unplanned Scrams per 7000 Critical Hrs	4Q/99	1Q/00	2Q/00	3Q/00	4Q/00	1Q/01
Unplanned scrams	0	0	1.0	0	0	1.0
Critical hours	2209.0	2149.6	2124.2	2208.0	483.9	1310.4
<b>Indicator value</b>	<b>0</b>	<b>0</b>	<b>0.8</b>	<b>0.8</b>	<b>1.0</b>	<b>2.3</b>

Licensee Comments: none

### Scrams with Loss of Normal Heat Removal



Thresholds: White > 2.0 Yellow > 10.0 Red > 20.0


#### Notes

Scrams with Loss of Normal Heat Removal	4Q/99	1Q/00	2Q/00	3Q/00	4Q/00	1Q/01
Scrams	0	0	0	0	0	1.0
Indicator value	0	0	0	0	0	1.0

Licensee Comments:

1Q/01: Momentary loss of offsite power resulted in a loss of main condenser.

### Unplanned Power Changes per 7000 Critical Hrs



Thresholds: White > 6.0


#### Notes

Unplanned Power Changes per 7000 Critical Hrs	4Q/99	1Q/00	2Q/00	3Q/00	4Q/00	1Q/01
Unplanned power changes	0	0	0	0	0	1.0
Critical hours	2209.0	2149.6	2124.2	2208.0	483.9	1310.4
<b>Indicator value</b>	<b>0.9</b>	<b>0.9</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>1.1</b>

Licensee Comments:

1Q/01: EHC Control Valve problem required power reduction to repair.

### Safety System Unavailability, Emergency AC Power




Thresholds: White > 2.5% Yellow > 5.0% Red > 10.0%

#### Notes

Safety System Unavailability, Emergency AC Power	4Q/99	1Q/00	2Q/00	3Q/00	4Q/00	1Q/01
<b>Train 1</b>						
Planned unavailable hours	33.86	6.55	17.88	38.02	1.73	17.78
Unplanned unavailable hours	0	0	0	0	0	0
Fault exposure hours	0	0	0	0	0	0
Effective Reset hours	0	0	0	0	0	0
Required hours	2209.00	2184.00	2183.00	2208.00	1497.27	2150.80
<b>Train 2</b>						
Planned unavailable hours	12.65	7.45	28.48	24.70	0	10.20
Unplanned unavailable hours	22.03	0	0	0	0	0
Fault exposure hours	0	0	0	0	0	0
Effective Reset hours	0	0	0	0	0	0
Required hours	2209.00	2184.00	2183.00	2208.00	586.00	1608.60
<b>Indicator value</b>	<b>0.7%</b>	<b>0.7%</b>	<b>0.7%</b>	<b>0.8%</b>	<b>0.8%</b>	<b>0.8%</b>

Licensee Comments: none

### Safety System Unavailability, High Pressure Injection System (HPSI)



Thresholds: White > 1.5% Yellow > 5.0% Red > 10.0%

**Notes**


Safety System Unavailability, High Pressure Injection System (HPSI)	4Q/99	1Q/00	2Q/00	3Q/00	4Q/00	1Q/01
<b>Train 1</b>						
Planned unavailable hours	1.65	12.95	0.58	0	0	7.07
Unplanned unavailable hours	0	0	0	0	0	0
Fault exposure hours	0	0	0	0	0	0
Effective Reset hours	0	0	0	0	0	0
Required hours	2209.00	2184.00	2183.00	2208.00	498.25	1697.20
<b>Train 2</b>						
Planned unavailable hours	0	14.60	0	2.20	0	0
Unplanned unavailable hours	0	0	0	0	0	0
Fault exposure hours	0	0	0	0	0	0
Effective Reset hours	0	0	0	0	0	0
Required hours	2209.00	2184.00	2183.00	2208.00	498.25	1697.20
<b>Train 3</b>						
Planned unavailable hours	16.48	0	5.70	8.98	0	3.32
Unplanned unavailable hours	0	0	0	0	0	0
Fault exposure hours	0	0	0	0	0	0
Effective Reset hours	0	0	0	0	0	0
Required hours	2209.00	2184.00	2183.00	2208.00	498.25	1409.00
<b>Train 4</b>						
Planned unavailable hours	16.02	12.00	1.95	0	0	0.72
Unplanned unavailable hours	0	0	0	0	0	0
Fault exposure hours	0	0	0	0	0	0
Effective Reset hours	0	0	0	0	0	0
Required hours	2209.00	2184.00	2183.00	2208.00	498.25	1409.00
<b>Indicator value</b>	<b>0.3%</b>	<b>0.3%</b>	<b>0.3%</b>	<b>0.3%</b>	<b>0.3%</b>	<b>0.3%</b>

Licensee Comments:

2Q/00: Number of planned unavailable hours adjusted to account for time equipment was in pull to lock.

2Q/00: Number of planned unavailable hours adjusted to account for time equipment was in pull to lock.

### Safety System Unavailability, Heat Removal System (AFW)



Thresholds: White > 2.0% Yellow > 6.0% Red > 12.0%

### Notes


Safety System Unavailability, Heat Removal System (AFW)	4Q/99	1Q/00	2Q/00	3Q/00	4Q/00	1Q/01
<b>Train 1</b>						
Planned unavailable hours	0	0.33	17.10	0.62	0	15.46
Unplanned unavailable hours	0	0	0	0	0	28.52
Fault exposure hours	0	0	0	0	0	64.55
Effective Reset hours	0	0	0	0	0	0
Required hours	2209.00	2184.00	2183.00	2208.00	498.25	1409.00
<b>Train 2</b>						
Planned unavailable hours	0.53	1.10	13.70	0.57	0	5.10
Unplanned unavailable hours	0	0	0	0	0	0.38
Fault exposure hours	0	0	0	0	0	0
Effective Reset hours	0	0	0	0	0	0
Required hours	2209.00	2184.00	2183.00	2208.00	498.25	1409.00
<b>Indicator value</b>	<b>0.2%</b>	<b>0.2%</b>	<b>0.3%</b>	<b>0.3%</b>	<b>0.3%</b>	<b>0.5%</b>

Licensee Comments:

1Q/01: Fault Exposure Unavailability incurred due to failure of EFW Pp "A". Failure was due to overspeed trip on 3/5/01 at 23:25. Previous successful quarterly surveillance was on 2/28/01 at 14:20, 129.09 hours prior to the failure. One half of this interval is fault exposure time of

64.55 hours.

### Safety System Unavailability, Residual Heat Removal System



Thresholds: White > 1.5% Yellow > 5.0% Red > 10.0%

**Notes**

Safety System Unavailability, Residual Heat Removal System	4Q/99	1Q/00	2Q/00	3Q/00	4Q/00	1Q/01
<b>Train 1</b>						
Planned unavailable hours	14.30	10.17	1.96	1.30	0.87	3.58
Unplanned unavailable hours	0	0	0	0	0	0
Fault exposure hours	0	0	0	0	0	0
Effective Reset hours	0	0	0	0	0	0
Required hours	2209.00	2184.00	2183.00	2208.00	1025.46	1871.80
<b>Train 2</b>						
Planned unavailable hours	7.82	11.61	1.76	10.28	0.77	12.06
Unplanned unavailable hours	0	0	0	0	0	0
Fault exposure hours	0	0	0	0	0	0
Effective Reset hours	0	0	0	0	0	0
Required hours	2209.00	2184.00	2183.00	2208.00	1025.46	1871.80
<b>Indicator value</b>	<b>0.3%</b>	<b>0.4%</b>	<b>0.3%</b>	<b>0.3%</b>	<b>0.3%</b>	<b>0.4%</b>

Licensee Comments:

4Q/00: Number of planned unavailable hours adjusted to account for time equipment was in pull to lock.


3Q/00: Number of planned unavailable hours adjusted to account for time equipment was in pull to lock.

2Q/00: Number of planned unavailable hours adjusted to account for time equipment was in pull to lock.

2Q/00: Number of planned unavailable hours adjusted to account for time equipment was in pull to lock.

1Q/00: Number of planned unavailable hours adjusted to account for time equipment was in pull to lock.

### Safety System Functional Failures (PWR)



Thresholds: White > 5.0


### Notes

Safety System Functional Failures (PWR)	4Q/99	1Q/00	2Q/00	3Q/00	4Q/00	1Q/01
Safety System Functional Failures	0	0	0	0	0	0
Indicator value	1	1	0	0	0	0

Licensee Comments: none



### Reactor Coolant System Activity



Thresholds: White > 50.0 Yellow > 100.0


#### Notes

Reactor Coolant System Activity	10/99	11/99	12/99	1/00	2/00	3/00	4/00	5/00	6/00	7/00	8/00	9/00
Maximum activity	0.000600	0.000600	0.000600	0.000600	0.000700	0.001600	0.000700	0.000700	0.000700	0.000700	0.000700	0.000700
Technical specification limit	1.0	1.0	1.0	1.0	1.0	1.0	1.0	1.0	1.0	1.0	1.0	1.0
Indicator value	0.1	0.1	0.1	0.1	0.1	0.2	0.1	0.1	0.1	0.1	0.1	0.1

Reactor Coolant System Activity	10/00	11/00	12/00	1/01	2/01	3/01
Maximum activity	0.000700	N/A	N/A	0.000138	0.000362	0.000234
Technical specification limit	1.0	1.0	1.0	1.0	1.0	1.0
Indicator value	0.1	N/A	N/A	0	0	0

Licensee Comments: none

### Reactor Coolant System Leakage



Thresholds: White > 50.0 Yellow > 100.0

**Notes**


Reactor Coolant System Leakage	10/99	11/99	12/99	1/00	2/00	3/00	4/00	5/00	6/00	7/00	8/00	9/00
Maximum leakage	0.110	0.120	0.130	0.140	0.140	0.360	0.150	0.150	0.150	0.200	0.200	0.210
Technical specification limit	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0
Indicator value	1.1	1.2	1.3	1.4	1.4	3.6	1.5	1.5	1.5	2.0	2.0	2.1

Reactor Coolant System Leakage	10/00	11/00	12/00	1/01	2/01	3/01
Maximum leakage	0.200	N/A	N/A	0.260	0.320	0.320
Technical specification limit	10.0	10.0	10.0	10.0	10.0	10.0
Indicator value	2.0	N/A	N/A	2.6	3.2	3.2

Licensee Comments:

3/01: .99 and .77 values on 3/6/01 were during non steady state conditions.

### Drill/Exercise Performance




Thresholds: White < 90.0% Yellow < 70.0%

#### Notes

Drill/Exercise Performance	4Q/99	1Q/00	2Q/00	3Q/00	4Q/00	1Q/01
Successful opportunities	44.0	20.0	48.0	22.0	32.0	13.0
Total opportunities	45.0	22.0	48.0	22.0	34.0	13.0
Indicator value	95.8%	94.6%	96.0%	96.6%	96.1%	97.3%

Licensee Comments: none

### ERO Drill Participation




Thresholds: White < 80.0% Yellow < 60.0%

#### Notes

ERO Drill Participation	4Q/99	1Q/00	2Q/00	3Q/00	4Q/00	1Q/01
Participating Key personnel	91.0	81.0	86.0	96.0	88.0	86.0
Total Key personnel	104.0	86.0	95.0	105.0	95.0	93.0
Indicator value	87.5%	94.2%	90.5%	91.4%	92.6%	92.5%

Licensee Comments: none

### Alert & Notification System



Thresholds: White < 94.0% Yellow < 90.0%

#### Notes

Alert & Notification System	4Q/99	1Q/00	2Q/00	3Q/00	4Q/00	1Q/01
Successful siren-tests	847	725	844	720	846	725
Total sirens-tests	847	726	847	726	847	726
Indicator value	99.6%	99.6%	99.6%	99.7%	99.7%	99.7%

Licensee Comments: none

### Occupational Exposure Control Effectiveness



Thresholds: White > 2.0 Yellow > 5.0

#### Notes

Occupational Exposure Control Effectiveness	4Q/99	1Q/00	2Q/00	3Q/00	4Q/00	1Q/01
High radiation area occurrences	0	0	0	0	0	0
Very high radiation area occurrences	0	0	0	0	0	0
Unintended exposure occurrences	0	0	0	0	0	0
<b>Indicator value</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>

Licensee Comments: none

### RETS/ODCM Radiological Effluent




Thresholds: White > 1.0 Yellow > 3.0

#### Notes

RETS/ODCM Radiological Effluent	4Q/99	1Q/00	2Q/00	3Q/00	4Q/00	1Q/01
RETS/ODCM occurrences	0	0	0	0	0	0
Indicator value	0	0	0	0	0	0

Licensee Comments: none

### Protected Area Security Performance Index



Thresholds: White > 0.080

#### Notes

Protected Area Security Performance Index	4Q/99	1Q/00	2Q/00	3Q/00	4Q/00	1Q/01
IDS compensatory hours	230.75	312.30	8.00	123.90	40.70	91.10
CCTV compensatory hours	0	16.4	0	0	0	0
IDS normalization factor	1.30	1.30	1.30	1.30	1.30	1.30
CCTV normalization factor	1.0	1.0	1.0	1.0	1.0	1.0
<b>Index Value</b>	<b>0.027</b>	<b>0.036</b>	<b>0.032</b>	<b>0.031</b>	<b>0.022</b>	<b>0.012</b>

Licensee Comments: none



### Personnel Screening Program



Thresholds: White > 2.0 Yellow > 5.0

#### Notes

Personnel Screening Program	4Q/99	1Q/00	2Q/00	3Q/00	4Q/00	1Q/01
Program failures	0	0	0	0	0	0
Indicator value	0	0	0	0	0	0

Licensee Comments: none

### FFD/Personnel Reliability



Thresholds: White > 2.0 Yellow > 5.0

#### Notes

FFD/Personnel Reliability	4Q/99	1Q/00	2Q/00	3Q/00	4Q/00	1Q/01
Program Failures	0	0	0	0	0	0
Indicator value	0	0	0	0	0	0

Licensee Comments: none

▲ [PI Summary](#) | [Inspection Findings Summary](#) | [Action Matrix Summary](#) | [Reactor Oversight Process](#)

Last Modified: March 28, 2002