


Quad Cities 2

3Q/2001 Performance Indicators

Licensee's General Comments: none

Unplanned Scrams per 7000 Critical Hrs




Thresholds: White > 3.0 Yellow > 6.0 Red > 25.0

Notes

Unplanned Scrams per 7000 Critical Hrs	4Q/99	1Q/00	2Q/00	3Q/00	4Q/00	1Q/01	2Q/01	3Q/01
Unplanned scrams	0	0	2.0	1.0	0	0	0	1.0
Critical hours	2209.0	1688.2	2132.0	2181.0	2209.0	2097.5	2183.0	1616.2
Indicator value	0	0	1.7	2.6	2.6	2.4	0.8	0.9

Licensee Comments: none

Scrams with Loss of Normal Heat Removal




Thresholds: White > 2.0 Yellow > 10.0 Red > 20.0

Notes

Scrams with Loss of Normal Heat Removal	4Q/99	1Q/00	2Q/00	3Q/00	4Q/00	1Q/01	2Q/01	3Q/01
Scrams	0	0	1.0	0	0	0	0	1.0
Indicator value	0	0	1.0	1.0	1.0	1.0	1.0	2.0

Licensee Comments: none

Unplanned Power Changes per 7000 Critical Hrs



Thresholds: White > 6.0

Notes


Unplanned Power Changes per 7000 Critical Hrs	4Q/99	1Q/00	2Q/00	3Q/00	4Q/00	1Q/01	2Q/01	3Q/01
Unplanned power changes	0	1.0	1.0	1.0	1.0	0	0	1.0
Critical hours	2209.0	1688.2	2132.0	2181.0	2209.0	2097.5	2183.0	1616.2
Indicator value	0	0.8	1.7	2.6	3.4	2.4	1.6	1.7

Licensee Comments:

3Q/01: An FAQ has been submitted for this indicator. During third quarter 2001, the station dropped power greater than 20% on one occasion due to river water temperature. The power change was anticipated in accordance with station procedures, but due to the complexity of predicting river temperature could not be specifically planned 72 hours in advance. The FAQ was submitted in accordance with the guidance of NEI 99-02, Revision 1. {Note - With the fourth quarter 2001 submittal, the July 2001 data was changed to include a power change that occurred as a result of environmental effects. An FAQ was submitted in November 2001, and is currently under review.}

3Q/01: An FAQ has been submitted for this indicator. During third quarter 2001, the station dropped power greater than 20% on one occasion due to river water temperature. The power change was anticipated in accordance with station procedures, but due to the complexity of predicting river temperature could not be specifically planned 72 hours in advance. The FAQ was submitted in accordance with the guidance of NEI 99-02, Revision 1.

Safety System Unavailability, Emergency AC Power




Thresholds: White > 2.5% Yellow > 5.0% Red > 10.0%

Notes

Safety System Unavailability, Emergency AC Power	4Q/99	1Q/00	2Q/00	3Q/00	4Q/00	1Q/01	2Q/01	3Q/01
Train 1								
Planned unavailable hours	9.52	36.53	72.54	52.84	14.39	77.72	47.60	23.15
Unplanned unavailable hours	0	0	0	58.18	0	0	78.30	0
Fault exposure hours	0	0	0	0	0	0	0	0
Effective Reset hours	0	0	0	0	0	0	0	0
Required hours	2209.00	2184.00	2183.00	2208.00	2209.00	2160.00	2183.00	2208.00
Train 2								
Planned unavailable hours	18.26	11.23	11.32	69.70	64.85	33.45	57.50	23.77
Unplanned unavailable hours	0	0	0	3.30	0	2.62	0	0
Fault exposure hours	0	0	0	0	0	0	0	0
Effective Reset hours	0	0	0	0	0	0	0	0
Required hours	2209.00	2184.00	2183.00	2208.00	2209.00	2160.00	2183.00	2208.00
Indicator value	1.6%	1.3%	1.3%	1.6%	1.6%	1.7%	1.9%	2.0%

Licensee Comments: none

Safety System Unavailability, High Pressure Injection System (HPCI)




Thresholds: White > 4.0% Yellow > 12.0% Red > 50.0%

Notes

Safety System Unavailability, High Pressure Injection System (HPCI)	4Q/99	1Q/00	2Q/00	3Q/00	4Q/00	1Q/01	2Q/01	3Q/01
Train 1								
Planned unavailable hours	6.47	6.52	76.61	6.15	86.86	71.66	10.50	4.79
Unplanned unavailable hours	17.10	0.72	0	0	0	195.83	42.81	0
Fault exposure hours	0	1.67	0	0	0	0	0	0
Effective Reset hours	0	0	0	0	0	0	0	0
Required hours	2209.00	1688.20	2132.00	2181.00	2209.00	2097.50	2183.00	1616.20
Indicator value	1.8%	1.8%	1.9%	1.9%	2.1%	3.0%	3.1%	2.8%

Licensee Comments: none

Safety System Unavailability, Heat Removal System (RCIC)




Thresholds: White > 4.0% Yellow > 12.0% Red > 50.0%

Notes

Safety System Unavailability, Heat Removal System (RCIC)	4Q/99	1Q/00	2Q/00	3Q/00	4Q/00	1Q/01	2Q/01	3Q/01
Train 1								
Planned unavailable hours	13.66	10.34	23.44	47.53	23.26	34.53	11.78	3.33
Unplanned unavailable hours	0	0.80	0	0	0	0	0	0
Fault exposure hours	0	0	0	0	0	0	0	0
Effective Reset hours	0	0	0	0	0	0	0	0
Required hours	2209.00	1688.20	2132.00	2181.00	2209.00	2097.50	2183.00	1616.20
Indicator value	1.3%	1.4%	1.3%	1.5%	1.5%	1.5%	1.4%	1.4%

Licensee Comments: none

Safety System Unavailability, Residual Heat Removal System




Thresholds: White > 1.5% Yellow > 5.0% Red > 10.0%

Notes

Safety System Unavailability, Residual Heat Removal System	4Q/99	1Q/00	2Q/00	3Q/00	4Q/00	1Q/01	2Q/01	3Q/01
Train 1								
Planned unavailable hours	7.02	0	0.05	0	19.37	19.15	0	3.88
Unplanned unavailable hours	4.52	3.83	0	0.47	0	0	0	0
Fault exposure hours	0	161.87	0	0	0	0	0	0
Effective Reset hours	0	0	0	0	0	0	0	0
Required hours	2209.00	2184.00	2183.00	2208.00	2209.00	2160.00	2183.00	2208.00
Train 2								
Planned unavailable hours	0	0	0	2.13	9.62	16.73	5.20	0
Unplanned unavailable hours	5.30	0	0	0	0	0	0	0
Fault exposure hours	0	0	0	0	0	0	0	0
Effective Reset hours	0	0	0	0	0	0	0	0
Required hours	2209.00	2184.00	2183.00	2208.00	2209.00	2160.00	2183.00	2208.00
Indicator value	0.3%	0.6%	0.6%	0.6%	0.6%	0.7%	0.7%	0.7%

Licensee Comments: none

Safety System Functional Failures (BWR)



Thresholds: White > 6.0

Notes

Safety System Functional Failures (BWR)	4Q/99	1Q/00	2Q/00	3Q/00	4Q/00	1Q/01	2Q/01	3Q/01
Safety System Functional Failures	3	4	1	0	0	0	0	0
Indicator value	3	7	8	8	5	1	0	0

Licensee Comments:

4Q/00: One Safety System Functional Failure has been added to the fourth quarter 2000 indicator in response to Inspection Report 50-265/01-08. Licensee review of the events is ongoing. {With the fourth quarter 2001 submittal, the abovementioned Safety System Functional Failure was withdrawn in accordance with a 12/4/01 NRC letter concerning IR 50-254(265)/01-08.}

1Q/00: Two Safety System Functional Failures have been added to the first quarter 2000 indicator in response to Inspection Report 50-265/01-08. Licensee review of the events is ongoing. {With the fourth quarter 2001 submittal, one of the two abovementioned Safety System Functional Failures was withdrawn in accordance with a 12/4/01 NRC letter concerning IR 50-254(265)/01-08.}

Reactor Coolant System Activity



Thresholds: White > 50.0 Yellow > 100.0


Notes

Reactor Coolant System Activity	10/99	11/99	12/99	1/00	2/00	3/00	4/00	5/00	6/00	7/00	8/00	9/00
Maximum activity	0.000280	0.000269	0.000242	0.000805	0.000104	0.000196	0.000264	0.000273	0.000168	0.000225	0.000207	0.000186
Technical specification limit	0.2	0.2	0.2	0.2	0.2	0.2	0.2	0.2	0.2	0.2	0.2	0.2
Indicator value	0.1	0.1	0.1	0.4	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1

Reactor Coolant System Activity	10/00	11/00	12/00	1/01	2/01	3/01	4/01	5/01	6/01	7/01	8/01	9/01
Maximum activity	0.000247	0.000129	0.000355	0.000109	0.000143	0.000088	0.000107	0.000136	0.000235	0.000333	0.000093	0.000097
Technical specification limit	0.2	0.2	0.2	0.2	0.2	0.2	0.2	0.2	0.2	0.2	0.2	0.2
Indicator value	0.1	0.1	0.2	0.1	0.1	0	0.1	0.1	0.1	0.2	0	0

Licensee Comments: none

Reactor Coolant System Leakage



Thresholds: White > 50.0 Yellow > 100.0


Notes

Reactor Coolant System Leakage	10/99	11/99	12/99	1/00	2/00	3/00	4/00	5/00	6/00	7/00	8/00	9/00
Maximum leakage	1.850	1.940	1.850	1.850	1.740	1.540	1.530	2.040	2.120	2.260	2.380	2.530
Technical specification limit	25.0	25.0	25.0	25.0	25.0	25.0	25.0	25.0	25.0	25.0	25.0	25.0
Indicator value	7.4	7.8	7.4	7.4	7.0	6.2	6.1	8.2	8.5	9.0	9.5	10.1

Reactor Coolant System Leakage	10/00	11/00	12/00	1/01	2/01	3/01	4/01	5/01	6/01	7/01	8/01	9/01
Maximum leakage	2.720	2.970	3.080	3.400	3.910	4.250	1.740	1.880	2.020	2.080	2.400	2.400
Technical specification limit	25.0	25.0	25.0	25.0	25.0	25.0	25.0	25.0	25.0	25.0	25.0	25.0
Indicator value	10.9	11.9	12.3	13.6	15.6	17.0	7.0	7.5	8.1	8.3	9.6	9.6

Licensee Comments: none

Drill/Exercise Performance



Thresholds: White < 90.0% Yellow < 70.0%

Notes


Drill/Exercise Performance	4Q/99	1Q/00	2Q/00	3Q/00	4Q/00	1Q/01	2Q/01	3Q/01
Successful opportunities	56.0	15.0	59.0	50.0	39.0	0	45.0	7.0
Total opportunities	57.0	17.0	62.0	53.0	39.0	0	46.0	10.0
Indicator value	96.9%	96.2%	96.0%	96.4%	96.8%	96.8%	97.0%	95.4%

Licensee Comments:

3Q/01: With the fourth quarter 2001 submittal, the September 2001 data was revised to correct an error.

2Q/01: This indicator is changed to reflect the results of a June 26, 2001, evaluation that were not provided in the second quarter submittal. This change does not affect the color.

ERO Drill Participation




Thresholds: White < 80.0% Yellow < 60.0%

Notes

ERO Drill Participation	4Q/99	1Q/00	2Q/00	3Q/00	4Q/00	1Q/01	2Q/01	3Q/01
Participating Key personnel	64.0	61.0	69.0	69.0	70.0	65.0	66.0	67.0
Total Key personnel	65.0	67.0	72.0	71.0	70.0	65.0	66.0	67.0
Indicator value	98.5%	91.0%	95.8%	97.2%	100.0%	100.0%	100.0%	100.0%

Licensee Comments: none

Alert & Notification System




Thresholds: White < 94.0% Yellow < 90.0%

Notes

Alert & Notification System	4Q/99	1Q/00	2Q/00	3Q/00	4Q/00	1Q/01	2Q/01	3Q/01
Successful siren-tests	3219	3321	3190	3150	3202	3285	3299	3256
Total sirens-tests	3276	3380	3328	3276	3276	3328	3328	3276
Indicator value	97.8%	97.7%	97.5%	97.1%	97.0%	97.1%	97.9%	98.7%

Licensee Comments: none

Occupational Exposure Control Effectiveness




Thresholds: White > 2.0 Yellow > 5.0

Notes

Occupational Exposure Control Effectiveness	4Q/99	1Q/00	2Q/00	3Q/00	4Q/00	1Q/01	2Q/01	3Q/01
High radiation area occurrences	0	0	0	0	0	0	0	0
Very high radiation area occurrences	0	0	0	0	0	0	0	0
Unintended exposure occurrences	0	0	0	0	0	0	0	0
Indicator value	0	0	0	0	0	0	0	0

Licensee Comments: none

RETS/ODCM Radiological Effluent




Thresholds: White > 1.0 Yellow > 3.0

Notes

RETS/ODCM Radiological Effluent	4Q/99	1Q/00	2Q/00	3Q/00	4Q/00	1Q/01	2Q/01	3Q/01
RETS/ODCM occurrences	0	0	0	0	0	0	0	0
Indicator value	0	0	0	0	0	0	0	0

Licensee Comments: none

Protected Area Security Performance Index




Thresholds: White > 0.080

Notes

Protected Area Security Performance Index	4Q/99	1Q/00	2Q/00	3Q/00	4Q/00	1Q/01	2Q/01	3Q/01
IDS compensatory hours	22.10	28.50	82.20	24.32	52.19	30.70	37.60	80.50
CCTV compensatory hours	2.2	0	4.3	1.6	0	0.1	0	13.9
IDS normalization factor	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00
CCTV normalization factor	1.0	1.0	1.0	1.0	1.0	1.0	1.0	1.0
Index Value	0.029	0.021	0.011	0.009	0.011	0.011	0.008	0.012

Licensee Comments: none

Personnel Screening Program




Thresholds: White > 2.0 Yellow > 5.0

Notes

Personnel Screening Program	4Q/99	1Q/00	2Q/00	3Q/00	4Q/00	1Q/01	2Q/01	3Q/01
Program failures	0	0	0	0	0	0	0	0
Indicator value	0	0	0	0	0	0	0	0

Licensee Comments: none

FFD/Personnel Reliability



Thresholds: White > 2.0 Yellow > 5.0

Notes

FFD/Personnel Reliability	4Q/99	1Q/00	2Q/00	3Q/00	4Q/00	1Q/01	2Q/01	3Q/01
Program Failures	0	0	0	0	0	0	0	0
Indicator value	0	0	0	0	0	0	0	0

Licensee Comments: none

▲ [PI Summary](#) | [Inspection Findings Summary](#) | [Action Matrix Summary](#) | [Reactor Oversight Process](#)

Last Modified: March 26, 2002