


South Texas 2

4Q/2002 Performance Indicators

Licensee's General Comments: none

Unplanned Scrams per 7000 Critical Hrs




Thresholds: White > 3.0 Yellow > 6.0 Red > 25.0

Notes

Unplanned Scrams per 7000 Critical Hrs	1Q/01	2Q/01	3Q/01	4Q/01	1Q/02	2Q/02	3Q/02	4Q/02
Unplanned scrams	2.0	1.0	0	0	0	1.0	1.0	1.0
Critical hours	1499.2	2100.9	2208.0	2072.6	2160.0	2114.9	2181.2	287.6
Indicator value	1.7	2.6	2.6	2.7	0.8	0.8	1.6	3.1

Licensee Comments: none

Scrams with Loss of Normal Heat Removal



Thresholds: White > 2.0 Yellow > 10.0 Red > 20.0


Notes

Scrams with Loss of Normal Heat Removal	1Q/01	2Q/01	3Q/01	4Q/01	1Q/02	2Q/02	3Q/02	4Q/02
Scrams	1.0	0	0	0	0	0	0	0
Indicator value	1.0	1.0	1.0	1.0	1.0	1.0	1.0	1.0

Licensee Comments:

4Q/02: On 12/15/02, the reactor was manually tripped, and we made a decision to break condenser vacuum. We do not believe this counts in this indicator, however, the guidance isn't sufficiently clear for the specific details related to this event. We are submitting a FAQ for clarification.

Unplanned Power Changes per 7000 Critical Hrs




Thresholds: White > 6.0

Notes

Unplanned Power Changes per 7000 Critical Hrs	1Q/01	2Q/01	3Q/01	4Q/01	1Q/02	2Q/02	3Q/02	4Q/02
Unplanned power changes	1.0	1.0	0	1.0	0	0	0	0
Critical hours	1499.2	2100.9	2208.0	2072.6	2160.0	2114.9	2181.2	287.6
Indicator value	0.9	1.7	1.7	2.7	1.6	0.8	0.8	0

Licensee Comments: none

Safety System Unavailability, Emergency AC Power, >2EDG



Thresholds: White > 2.5% Yellow > 10.0% Red > 20.0%


Notes

Safety System Unavailability, Emergency AC Power, >2EDG	1Q/01	2Q/01	3Q/01	4Q/01	1Q/02	2Q/02	3Q/02	4Q/02
Train 1								
Planned unavailable hours	11.50	16.00	8.30	53.20	18.47	44.00	15.50	0
Unplanned unavailable hours	0	0	0	0	0	26.43	0	0
Fault exposure hours	0	0	0	0	0	0	0	0
Effective Reset hours	0	0	0	0	0	0	0	0
Required hours	2160.00	2183.00	2208.00	2209.00	2160.00	2183.00	2208.00	2209.00
Train 2								
Planned unavailable hours	22.02	23.20	4.20	141.80	39.10	20.55	18.00	0
Unplanned unavailable hours	0	0	0	0	0	0	0	0
Fault exposure hours	0	0	0	0	0	0	0	0
Effective Reset hours	0	0	0	0	0	0	0	0
Required hours	2160.00	2183.00	2208.00	2209.00	2160.00	2183.00	2208.00	2209.00
Train 3								
Planned unavailable hours	52.70	58.50	21.90	0	33.33	100.00	12.95	0
Unplanned unavailable hours	0	0	0	0	0	132.73	0	0
Fault exposure hours	0	0	0	0	0	0	0	0
Effective Reset hours	0	0	0	0	0	0	0	0
Required hours	2160.00	2183.00	2208.00	2209.00	2160.00	2183.00	2208.00	2209.00
Indicator value	1.5%	1.5%	1.4%	1.6%	1.3%	1.7%	1.7%	1.7%

Licensee Comments:

4Q/02: 11/02 - Hours train required for service is less than the number of hours in the reporting period because of the steam generator replacement outage, and the nuclear fuel was offloaded to the spent fuel pool until Nov. 20, at 1503 when the unit entered Mode 6.

Safety System Unavailability, High Pressure Injection System (HPSI)



Thresholds: White > 1.5% Yellow > 5.0% Red > 10.0%

Notes


Safety System Unavailability, High Pressure Injection System (HPSI)	1Q/01	2Q/01	3Q/01	4Q/01	1Q/02	2Q/02	3Q/02	4Q/02
Train 1								
Planned unavailable hours	0.50	1.10	35.00	14.80	1.20	18.77	52.87	0
Unplanned unavailable hours	0	0	0	0	0	0	0	0
Fault exposure hours	0	0	0	0	0	0	0	0
Effective Reset hours	0	0	0	0	0	0	0	0
Required hours	1499.20	2100.90	2208.00	2072.60	2160.00	2183.00	2208.00	445.52
Train 2								
Planned unavailable hours	12.33	48.00	17.70	0.50	11.50	14.50	38.43	0
Unplanned unavailable hours	0	0	0	0	0	0	0	0
Fault exposure hours	0	0	0	0	0	0	0	0
Effective Reset hours	0	0	0	0	0	0	0	0
Required hours	1499.20	2100.90	2208.00	2072.60	2160.00	2183.00	2208.00	445.52
Train 3								
Planned unavailable hours	14.80	56.30	51.90	0	14.88	63.13	89.79	0
Unplanned unavailable hours	0	0	0	0	0	0	0	0
Fault exposure hours	0	0	0	0	0	0	0	0
Effective Reset hours	0	0	0	0	0	0	0	0
Required hours	1499.20	2100.90	2208.00	2072.60	2160.00	2183.00	2208.00	445.52
Indicator value	0.9%	0.9%	1.0%	0.9%	1.0%	1.1%	1.2%	1.3%

Licensee Comments:

4Q/02: 10/02 - Hours train required for service is less than number of hours in the reporting period because of a steam generator replacement outage, and the nuclear fuel was offloaded to the spent fuel pool.

Licensee Comments: none

Safety System Unavailability, Residual Heat Removal System



Thresholds: White > 1.5% Yellow > 5.0% Red > 10.0%

Notes


Safety System Unavailability, Residual Heat Removal System	1Q/01	2Q/01	3Q/01	4Q/01	1Q/02	2Q/02	3Q/02	4Q/02
Train 1								
Planned unavailable hours	0.50	0	35.00	0.80	1.20	43.17	52.87	0
Unplanned unavailable hours	0	0	0	0	0	0	0	0
Fault exposure hours	0	0	0	0	0	0	0	0
Effective Reset hours	0	0	0	0	0	0	0	0
Required hours	2124.30	2183.00	2208.00	2209.00	2160.00	2183.00	2208.00	1251.95
Train 2								
Planned unavailable hours	21.67	0	0.40	0.50	25.00	49.62	83.03	0
Unplanned unavailable hours	0	0	0	0	0	0	0	0
Fault exposure hours	0	0	0	0	0	0	0	0
Effective Reset hours	0	0	0	0	0	0	0	0
Required hours	2124.30	2183.00	2208.00	2209.00	2160.00	2183.00	2208.00	1251.95
Train 3								
Planned unavailable hours	13.50	0	4.50	0	21.30	63.13	109.53	0
Unplanned unavailable hours	0	0	0	0	0	0	0	0
Fault exposure hours	0	0	0	0	0	0	0	0
Effective Reset hours	0	0	0	0	0	0	0	0
Required hours	2124.30	2183.00	2208.00	2209.00	2160.00	2183.00	2208.00	1251.95
Indicator value	1.2%	1.1%	1.0%	1.0%	1.1%	1.1%	1.2%	1.2%

Licensee Comments:

4Q/02: 10/02 - Hours train required for service is less than number of hours in the reporting period because of a steam generator replacement outage, and the nuclear fuel was offloaded to the spent fuel pool. 11/02 - Hours train required for service is less than the number of hours in the reporting period because of the steam generator replacement outage, and the nuclear fuel was offloaded to the spent fuel pool until Nov. 20, at 1503 when the unit entered Mode 6.

4Q/02: 10/02 - Hours train required for service is less than number of hours in the reporting period because of a steam generator replacement outage, and the nuclear fuel was offloaded to the spent fuel pool. 11/02 - Hours train required for service is less than the number of hours in the reporting period because of the steam generator replacement outage, and the nuclear fuel was offloaded to the spent fuel pool until Nov. 20, at 1503 when the unit entered Mode 6.

Safety System Functional Failures (PWR)




Thresholds: White > 5.0

Notes

Safety System Functional Failures (PWR)	1Q/01	2Q/01	3Q/01	4Q/01	1Q/02	2Q/02	3Q/02	4Q/02
Safety System Functional Failures	0	0	0	0	0	0	0	0
Indicator value	0	0	0	0	0	0	0	0

Licensee Comments: none

Reactor Coolant System Leakage



Thresholds: White > 50.0 Yellow > 100.0


Notes

Reactor Coolant System Leakage	1/01	2/01	3/01	4/01	5/01	6/01	7/01	8/01	9/01	10/01	11/01	12/01
Maximum leakage	0.524	0.320	0.345	0.318	0.273	0.270	0.295	0.289	0.310	0.283	0.294	0.309
Technical specification limit	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0
Indicator value	5.2	3.2	3.5	3.2	2.7	2.7	3.0	2.9	3.1	2.8	2.9	3.1

Reactor Coolant System Leakage	1/02	2/02	3/02	4/02	5/02	6/02	7/02	8/02	9/02	10/02	11/02	12/02
Maximum leakage	0.329	0.331	0.317	0.325	0.344	0.351	0.361	0.415	0.458	0.410	0	0.302
Technical specification limit	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0
Indicator value	3.3	3.3	3.2	3.3	3.4	3.5	3.6	4.2	4.6	4.1	0	3.0

Licensee Comments: none

Drill/Exercise Performance




Thresholds: White < 90.0% Yellow < 70.0%

Notes

Drill/Exercise Performance	1Q/01	2Q/01	3Q/01	4Q/01	1Q/02	2Q/02	3Q/02	4Q/02
Successful opportunities	0	94.0	19.0	78.0	33.0	28.0	56.0	0
Total opportunities	0	100.0	20.0	80.0	37.0	28.0	58.0	0
Indicator value	96.8%	96.1%	95.8%	96.0%	94.3%	95.0%	95.2%	95.4%

Licensee Comments: none

ERO Drill Participation




Thresholds: White < 80.0% Yellow < 60.0%

Notes

ERO Drill Participation	1Q/01	2Q/01	3Q/01	4Q/01	1Q/02	2Q/02	3Q/02	4Q/02
Participating Key personnel	96.0	111.0	111.0	120.0	112.0	111.0	113.0	111.0
Total Key personnel	102.0	121.0	122.0	125.0	124.0	118.0	120.0	118.0
Indicator value	94.1%	91.7%	91.0%	96.0%	90.3%	94.1%	94.2%	94.1%

Licensee Comments: none

Alert & Notification System




Thresholds: White < 94.0% Yellow < 90.0%

Notes

Alert & Notification System	1Q/01	2Q/01	3Q/01	4Q/01	1Q/02	2Q/02	3Q/02	4Q/02
Successful siren-tests	189	223	189	220	186	218	190	253
Total sirens-tests	190	224	192	224	192	224	192	256
Indicator value	99.3%	99.1%	98.8%	98.9%	98.3%	97.7%	97.8%	98.0%

Licensee Comments: none

Occupational Exposure Control Effectiveness




Thresholds: White > 2.0 Yellow > 5.0

Notes

Occupational Exposure Control Effectiveness	1Q/01	2Q/01	3Q/01	4Q/01	1Q/02	2Q/02	3Q/02	4Q/02
High radiation area occurrences	0	0	0	0	0	0	0	0
Very high radiation area occurrences	0	0	0	0	0	0	0	0
Unintended exposure occurrences	0	0	0	0	0	0	0	0
Indicator value	0	0	0	0	0	0	0	0

Licensee Comments: none

RETS/ODCM Radiological Effluent




Thresholds: White > 1.0 Yellow > 3.0

Notes

RETS/ODCM Radiological Effluent	1Q/01	2Q/01	3Q/01	4Q/01	1Q/02	2Q/02	3Q/02	4Q/02
RETS/ODCM occurrences	0	0	0	0	0	0	0	0
Indicator value	0	0	0	0	0	0	0	0

Licensee Comments: none

Protected Area Security Performance Index




Thresholds: White > 0.080

Notes

Protected Area Security Performance Index	1Q/01	2Q/01	3Q/01	4Q/01	1Q/02	2Q/02	3Q/02	4Q/02
IDS compensatory hours	251.50	106.10	145.80	143.90	77.50	139.70	107.90	82.10
CCTV compensatory hours	163.5	41.4	66.3	16.6	11.9	41.3	97.0	4.8
IDS normalization factor	2.20	2.20	2.20	2.20	2.20	2.20	2.20	2.20
CCTV normalization factor	1.3	1.3	1.3	1.3	1.3	1.3	1.3	1.3
Index Value	0.032	0.034	0.035	0.029	0.018	0.019	0.019	0.017

Licensee Comments: none

Personnel Screening Program




Thresholds: White > 2.0 Yellow > 5.0

Notes

Personnel Screening Program	1Q/01	2Q/01	3Q/01	4Q/01	1Q/02	2Q/02	3Q/02	4Q/02
Program failures	0	0	0	0	0	0	0	0
Indicator value	0	0	0	0	0	0	0	0

Licensee Comments: none

FFD/Personnel Reliability



Thresholds: White > 2.0 Yellow > 5.0

Notes

FFD/Personnel Reliability	1Q/01	2Q/01	3Q/01	4Q/01	1Q/02	2Q/02	3Q/02	4Q/02
Program Failures	0	0	0	0	0	0	0	0
Indicator value	0	0	0	0	0	0	0	0

Licensee Comments: none

▲ [PI Summary](#) | [Inspection Findings Summary](#) | [Reactor Oversight Process](#)

Last Modified: January 30, 2003