

Hatch 1

1Q/2009 Plant Inspection Findings

Initiating Events

Mitigating Systems

Barrier Integrity

Significance:  Sep 19, 2008

Identified By: NRC

Item Type: NCV NonCited Violation

Incomplete Mitigating Strategy Required by Facility Operating License (Section 4A05.2 c)

This B.5.b Pas 2 and 3 Mitigating Strategy Finding has been classified as OUO containing sensitive information classified under 2.390 - see inspection report for details.

Inspection Report# : [2008007](#) (*pdf*)

Emergency Preparedness

Occupational Radiation Safety

Significance:  Mar 31, 2009

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to provide training to users of powered air-purifying respirators

The inspectors identified a Green non-cited violation (NCV) of TS 5.4, Procedures, for failure to provide training to users of Powered Air-purifying Respirator (PAPR) type respiratory protection devices as required by procedure 10AC-MGR-026-0, Respiratory Protection Program, revision 1.0. The licensee has entered this issue into the Corrective Action Program as Condition Report 2009102825.

This finding is greater than minor because it is associated with the Occupational Radiation Safety Cornerstone attribute of Human Performance (Training) and adversely affects the cornerstone objective of ensuring adequate protection of worker health and safety from exposure to radiation from radioactive material during routine civilian nuclear reactor operation. The finding was evaluated using the Occupational Radiation Safety SDP and determined to be of very low safety significance (Green). The finding was not related to ALARA planning, nor did it involve an overexposure or substantial potential for overexposure, and the ability to assess dose was not compromised. This finding involved the cross-cutting aspect of Human Performance, Resources [H.2.b] because there was no formal training program provided to users of PAPR type respiratory protection devices. (Section 2OS3)

Violations of very low safety significance, which were identified by the licensee, have been reviewed by the inspectors. Corrective actions taken or planned by the licensee have been entered into the licensee's corrective action

program. These violations and corrective actions are listed in Section 4OA7 of this report

Inspection Report# : [2009002](#) (*pdf*)

Public Radiation Safety

Physical Protection

Although the NRC is actively overseeing the Security cornerstone, the Commission has decided that certain findings pertaining to security cornerstone will not be publicly available to ensure that potentially useful information is not provided to a possible adversary. Therefore, the [cover letters](#) to security inspection reports may be viewed.

Miscellaneous

Last modified : May 28, 2009