

August 26, 2002

Mr. Peter E. Katz  
Vice President - Calvert Cliffs Nuclear Power Plant  
Constellation Generation Group  
Calvert Cliffs Nuclear Power Plant, Inc.  
1650 Calvert Cliffs Parkway  
Lusby, MD 20657-4702

SUBJECT: MID-CYCLE PERFORMANCE REVIEW AND INSPECTION PLAN -  
CALVERT CLIFFS NUCLEAR POWER PLANT

Dear Mr. Katz:

On August 6, 2002, the NRC staff completed its mid-cycle plant performance assessment of Calvert Cliffs Nuclear Power Plant. In accordance with NRC Inspection Manual Chapter 0305 "Operating Reactor Assessment Program," the mid-cycle review involved the participation of all technical divisions in evaluating the performance of the Calvert Cliffs facility for the first half of the current assessment cycle, January 1 - December 31, 2002. The purpose of this letter is to inform you of our assessment of your safety performance during this period and our plans for future inspections at your facility so that you will have an opportunity to prepare for these inspections and to inform us of any planned inspections which may conflict with your plant activities.

Plant performance for the most recent quarter was within the Degraded Cornerstone Column of the NRC's Action Matrix, based on the Unit 1 finding of substantial safety significance (Yellow) in the mitigating systems cornerstone. This finding was associated with the May 16, 2001, failure of the No. 11 turbine-driven auxiliary feedwater (AFW) pump. Calvert Cliffs Unit 2 was within the Regulatory Response Column of the Action Matrix based on one inspection finding of low to moderate safety significance (White). This finding applies to both units and was associated with the May 23, 2002, shipment of radioactive material to a waste processing facility, which was not properly prepared, resulting in an external radiation limit being exceeded.

The Unit 1 Yellow inspection finding associated with the pump failure was identified during a Special Inspection (reference Inspection Report 50-317/01-09, dated August 24, 2001) conducted in June-July 2001. A 95002 supplemental inspection (reference Inspection Report 50-317/01-13, dated January 14, 2002) identified that the Calvert Cliffs staff had adequately identified the underlying causes for the failed AFW pump and that the corrective actions were appropriately broad to provide reasonable assurance that failure would not recur. Therefore, at the end of the third quarter of 2002, the finding will no longer be considered in assessing plant performance.

The Unit 1 and 2 White inspection finding associated with the May 23, 2002, shipment of radioactive material was identified during an inspection (reference Inspection Report 50-317/02-04, 50-318/02-04, dated August 24, 2001) conducted in June 2002. We understand that your staff has initiated corrective actions regarding this finding. Therefore, we have scheduled

supplemental inspection procedure 95001 to be conducted in October 2002, to address this finding, in accordance with the NRC Manual Chapter 0305, Action Matrix. This inspection procedure is conducted to provide assurance that the root and contributing causes of risk-significant performance issues are understood, the extent of condition is identified, and the corrective actions are sufficient to prevent recurrence.

During the most recent quarter, one Unit 1 performance indicator (PI), AFW system unavailability, crossed the threshold from Green to White (increased regulatory response band) in the mitigating systems cornerstone. Although the AFW system unavailability stemmed largely from the above-noted AFW pump failure, the indicator crossed the threshold in the past quarter due to the way the recent extended refueling outage factored into system unavailability calculations. The PI is expected to return to Green during the third quarter. No supplemental inspection will be conducted for this PI, since it does not reflect recent performance, and follow-up was already conducted regarding the AFW system Yellow finding.

The Unit 1 "Scram with Loss of Normal Heat Removal" PI has been White since the first quarter of 2000. This PI, in the initiating events cornerstone, may return to Green as early as the third quarter of 2002. Follow-up inspection for this White PI has already been completed satisfactorily.

In our Annual Assessment Letter dated March 4, 2002, we advised you of a substantive cross-cutting issue in the area of Problem Identification and Resolution. Specifically, the staff had identified seven findings in the mitigating systems cornerstone in which Calvert Cliffs personnel did not consistently and thoroughly assess degraded or non-conforming structures, systems, and components. No new examples have been identified in our recent inspections, which may indicate that you are making progress in this area. However, our mid-cycle assessments review findings over a twelve month period, and over that period, the findings still reflect the same cross-cutting theme. Accordingly, the Problem Identification and Resolution inspection scheduled for November 2002, as well as other baseline inspections, will provide a basis for an NRC determination in the next annual assessment letter of whether you have effectively addressed this cross-cutting issue.

The enclosed inspection plan details the inspections scheduled through September 30, 2003. The inspection plan is provided to minimize the resource impact on your staff, and to allow for scheduling conflicts and personnel availability to be resolved in advance of inspector arrival on site. Routine resident inspections are not listed due to their ongoing and continuous nature. The last six months of the inspection plan is tentative and may be revised at the end-of-cycle review.

In addition, the NRC is in the process of finalizing a Temporary Instruction (TI) that will be used to review implementation of the Interim Compensatory Measures required by the Agency's Security Order to all commercial nuclear power plants dated February 25, 2002. Schedules have not yet been finalized, but it is anticipated that these inspections will begin within the next calendar quarter. Once finalized, the details will be communicated by separate correspondence.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be made available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's

Peter E. Katz

3

document system (ADAMS). ADAMS is accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room).

If circumstances arise which cause us to change the inspection plan, we will contact you to discuss the change as soon as possible. Please contact Michele G. Evans, Chief, Reactor Projects Branch 1, at 610-337-5224 with any questions you may have regarding this letter or the inspection plan.

Sincerely,

/RA/

Hubert J. Miller  
Regional Administrator

Docket Nos. 50-317, 50-318  
Licensee Nos. DPR-53, DPR-69

Enclosure: Calvert Cliffs Inspection/ Activity Plan

cc w/encl: M. Geckle, Director, Nuclear Regulatory Matters (CCNPPI)  
R. McLean, Administrator, Nuclear Evaluations  
K. Burger, Esquire, Maryland People's Counsel  
R. Ochs, Maryland Safe Energy Coalition  
J. Petro, Constellation Power Source  
State of Maryland (2)

Distribution w/encl: H. Miller, RA/J. Wiggins, DRA (1)  
 A. Blough, DRP  
 W. Lanning, DRS  
 J. Clifford, DRP  
 R. Crlenjak, DRS  
 H. Nieh, RI EDO Coordinator  
 D. Beaulieu - SRI - Calvert Cliffs  
 S. Richards, NRR (ridsnrrdlpmlpdi)  
 D. Skay, PM, NRR  
 P. Tam, PM, NRR (Backup)  
 Ridsnrrdipmlpb  
 D. Screnci, PAO  
 N. Sheehan, PAO  
 M. Evans, DRP  
 DRS Branch Chiefs (5)  
 N. Perry, DRP  
 P. Torres, DRP  
 R. Junod, DRP  
 M. Modes, DRS  
 R. Nimitz, DRS  
 P. Frechette, DRS  
 N. McNamara, DRS  
 B. Platchek, DRP  
 Region I Docket Room (with concurrences)

DOCUMENT NAME: G:\BRANCH1\ROP3mid-cycle\CCmidcycleltr2002.wpd

After declaring this document "An Official Agency Record" it **will/will not** be released to the Public. **To receive a copy of this document, indicate in the box: "C" = Copy without attachment/enclosure "E" = Copy with attachment/enclosure "N" = No copy**

OFFICE	RI/DRP	RI/DRP	RI/DRP	RI/ORA
NAME	NPerry/NSP	MEvans/MGE	ABlough/AB	HMiller/HM
DATE	0821/02	08/21/02	08/23/02	08/24/02

OFFICIAL RECORD COPY

**Calvert Cliffs**  
**Inspection / Activity Plan**  
**06/30/2002 - 09/30/2003**

Unit Number	Inspection Activity	Title	No. of Staff on Site	Planned Dates		Inspection Type
				Start	End	
<b>7/15 EXM - OPERATOR LICENSING INITIAL EXAMS</b>			<b>4</b>			
1	U01442	CALVERT CLIFFS 1&2 O/L INITIAL EXAM 7/15-18/2002		07/15/2002	07/19/2002	Not Applicable
<b>71114 - EP PROGRAM REVIEW &amp; EP PI VERIFICATION</b>			<b>1</b>			
1, 2	IP 7111402	Alert and Notification System Testing		07/15/2002	07/19/2002	Baseline Inspections
1, 2	IP 7111403	Emergency Response Organization Augmentation Testing		07/15/2002	07/19/2002	Baseline Inspections
1, 2	IP 7111404	Emergency Action Level and Emergency Plan Changes		07/15/2002	07/19/2002	Baseline Inspections
1, 2	IP 7111405	Correction of Emergency Preparedness Weaknesses and Deficiencies		07/15/2002	07/19/2002	Baseline Inspections
1, 2	IP 71151	Performance Indicator Verification		07/15/2002	07/19/2002	Baseline Inspections
<b>7111401 - EP EXERCISE EVALUATION</b>			<b>4</b>			
1, 2	IP 7111401	Exercise Evaluation		09/09/2002	09/13/2002	Baseline Inspections
1, 2	IP 71151	Performance Indicator Verification		09/09/2002	09/13/2002	Baseline Inspections
1, 2	IP 71153	Event Followup		09/09/2002	09/13/2002	Baseline Inspections
<b>7112203 - PUB RAD SAFETY - REMP</b>			<b>1</b>			
1, 2	IP 7112203	Radiological Environmental Monitoring Program		09/30/2002	10/04/2002	Baseline Inspections
<b>7112103 - OCC RAD SAFETY - INSTRUMENTATION</b>			<b>2</b>			
1, 2	IP 7112103	Radiation Monitoring Instrumentation and Protective Equipment		10/07/2002	10/11/2002	Baseline Inspections
1, 2	IP 95001	Supplemental Inspection For One Or Two White Inputs In A Strategic Performance Area		10/07/2002	10/11/2002	Supplemental Program
<b>71152B - PROBLEM IDENTIFICATION AND RESOLUTION</b>			<b>3</b>			
1, 2	IP 71152B	Identification and Resolution of Problems		11/04/2002	11/08/2002	Baseline Inspections
1, 2	IP 71152B	Identification and Resolution of Problems		11/18/2002	11/22/2002	Baseline Inspections
<b>60855 - ISFSI</b>			<b>1</b>			
2	IP 60855	Operation Of An ISFSI		11/18/2002	11/22/2002	Other Routine
<b>71121 - OCC RAD SAFETY</b>			<b>1</b>			
1, 2	IP 7112101	Access Control to Radiologically Significant Areas		12/09/2002	12/13/2002	Baseline Inspections
1, 2	IP 7112102	ALARA Planning and Controls		12/09/2002	12/13/2002	Baseline Inspections
1, 2	IP 7112103	Radiation Monitoring Instrumentation and Protective Equipment		12/09/2002	12/13/2002	Baseline Inspections
<b>711117B - MODS</b>			<b>3</b>			
1, 2	IP 7111102	Evaluation of Changes, Tests, or Experiments		12/16/2002	12/20/2002	Baseline Inspections
1, 2	IP 711117B	Permanent Plant Modifications		12/16/2002	12/20/2002	Baseline Inspections
<b>711112B - MAINTENANCE RULE</b>			<b>1</b>			
1, 2	IP 711112B	Maintenance Effectiveness		12/16/2002	12/20/2002	Baseline Inspections
<b>50001 - U2 SG REPLACEMENT INSPECTION</b>			<b>1</b>			
2	IP 50001	Steam Generator Replacement Inspection		01/01/2003	05/15/2003	Other Routine

This report does not include INPO and OUTAGE activities.  
This report shows only on-site and announced inspection procedures.

**Calvert Cliffs**  
**Inspection / Activity Plan**  
**06/30/2002 - 09/30/2003**

Unit Number	Inspection Activity	Title	No. of Staff on Site	Planned Dates		Inspection Type
				Start	End	
	<b>71121</b>	<b>- OCC RAD SAFETY</b>	<b>1</b>			
2	IP 50001	Steam Generator Replacement Inspection		03/03/2003	03/07/2003	Other Routine
1, 2	IP 7112101	Access Control to Radiologically Significant Areas		03/03/2003	03/07/2003	Baseline Inspections
1, 2	IP 7112102	ALARA Planning and Controls		03/03/2003	03/07/2003	Baseline Inspections
1, 2	IP 7112103	Radiation Monitoring Instrumentation and Protective Equipment		03/03/2003	03/07/2003	Baseline Inspections
1	IP 71151	Performance Indicator Verification		03/03/2003	03/07/2003	Baseline Inspections
	<b>7111108</b>	<b>- INSERVICE INSPECTION</b>	<b>2</b>			
2	IP 2515/145	Circumferential Cracking of Reactor Pressure Vessel Head Penetration Nozzles (NRC Bulletin :		03/10/2003	03/14/2003	Safety Issues
2	IP 7111108	Inservice Inspection Activities		03/31/2003	04/04/2003	Baseline Inspections
	<b>71121</b>	<b>- OCC RAD SAFETY</b>	<b>1</b>			
2	IP 50001	Steam Generator Replacement Inspection		04/14/2003	04/18/2003	Other Routine
1, 2	IP 7112101	Access Control to Radiologically Significant Areas		04/14/2003	04/18/2003	Baseline Inspections
1, 2	IP 7112102	ALARA Planning and Controls		04/14/2003	04/18/2003	Baseline Inspections
1, 2	IP 7112103	Radiation Monitoring Instrumentation and Protective Equipment		04/14/2003	04/18/2003	Baseline Inspections
1, 2	IP 71151	Performance Indicator Verification		04/14/2003	04/18/2003	Baseline Inspections
	<b>71122.02</b>	<b>- RADWASTE</b>	<b>1</b>			
1, 2	IP 7112202	Radioactive Material Processing and Transportation		06/02/2003	06/06/2003	Baseline Inspections
	<b>71130</b>	<b>- SECURITY</b>	<b>1</b>			
1, 2	IP 7113001	Access Authorization Program (Behavior Observation Only)		06/16/2003	06/20/2003	Baseline Inspections
1, 2	IP 7113002	Access Control (Search of Personnel, Packages, and Vehicles: Identification and Authorizatio		06/16/2003	06/20/2003	Baseline Inspections

This report does not include INPO and OUTAGE activities.  
This report shows only on-site and announced inspection procedures.