

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 21

National Average: 43

2x National Average: 86

National Median: 24

Average for Selected Dockets: 21

Facility Name: Pilgrim 1 Docket (050- 00293)

Details	Department	Work Type	Docket/Report
Communication / IR			
160 - No communication / information not communicated	M - Mechanical	M - Maintenance / Repair	050-00293/2006-002
Number of Items for this Docket: 1			
Percent of Total for this Docket: 5			
<hr/>			
Procedures & Reference Document / IR			
111 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00293/2005-005
Number of Items for this Docket: 1			
Percent of Total for this Docket: 5			
<hr/>			
Problem Identification & Resolution / IR			
146 - Evaluation LTA	G - Engineering	G - Design	050-00293/2006-003
146 - Evaluation LTA	G - Engineering	G - Design	050-00293/2006-006
146 - Evaluation LTA	M - Mechanical	M - Maintenance / Repair	050-00293/2006-002
148 - Action not yet started or untimely	M - Mechanical	M - Maintenance / Repair	050-00293/2005-005
150 - Programmatic deficiency	M - Mechanical	M - Maintenance / Repair	050-00293/2005-005
Number of Items for this Docket: 5			
Percent of Total for this Docket: 24			
<hr/>			
Work Planning & Practices / IR			
185 - Procedural adherence LTA	D - Emergency Planning	D - Emergency Drill	050-00293/2006-009
185 - Procedural adherence LTA	I - Instrumentation & Control	S - Surveillance	050-00293/2006-004
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00293/2006-004
185 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00293/2006-002
185 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00293/2006-002
187 - Action implementation LTA	G - Engineering	G - Design	050-00293/2006-006
187 - Action implementation LTA	H - Health Physics	H - Health Physics	050-00293/2006-003
188 - Work practice or craft skill LTA	D - Emergency Planning	D - Emergency Drill	050-00293/2005-005
188 - Work practice or craft skill LTA	I - Instrumentation & Control	T - Testing	050-00293/2005-005
190 - Failure to stop work / non-conservative decision making	C - Chemistry	M - Maintenance / Repair	050-00293/2005-005
190 - Failure to stop work / non-conservative decision making	G - Engineering	G - Design	050-00293/2006-006
198 - Worker distracted / interrupted	H - Health Physics	H - Health Physics	050-00293/2005-005
Number of Items for this Docket: 12			
Percent of Total for this Docket: 57			

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 21
National Average: 43
2x National Average: 86
National Median: 24
Average for Selected Dockets: 21

Facility Name: Pilgrim 1 Docket (050- 00293)

Details	Department	Work Type	Docket/Report
Procedures & Reference Document / LER			
110 - No procedure / reference documents	M - Mechanical	M - Maintenance / Repair	050-00293/2006-001-00
Number of Items for this Docket: 1			
Percent of Total for this Docket: 5			
Problem Identification & Resolution / LER			
140 - Problem not completely or accurately identified	O - Operations	V - Troubleshooting	050-00293/2006-001-00
Number of Items for this Docket: 1			
Percent of Total for this Docket: 5			
Total Items for this Docket: 21			
