

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 11

National Average: 41

2x National Average: 82

National Median: 24

Average for Selected Dockets: 11

Facility Name: Robinson 2 Docket (050- 00261)

Details	Department	Work Type	Docket/Report
Procedures & Reference Document / IR			
111 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00261/2006-005
111 - Procedure / reference document technical content	O - Operations	O - Control Room Ops	050-00261/2007-006
Number of Items for this Docket: 2			
Percent of Total for this Docket: 18			
Problem Identification & Resolution / IR			
142 - Operating experience (OE) review LTA	E - Electrical	M - Maintenance / Repair	050-00261/2006-005
146 - Evaluation LTA	E - Electrical	M - Maintenance / Repair	050-00261/2006-005
Number of Items for this Docket: 2			
Percent of Total for this Docket: 18			
Work Planning & Practices / IR			
185 - Procedural adherence LTA	G - Engineering	F - Modification	050-00261/2007-006
186 - Failure to take action / meet requirements	D - Emergency Planning	Q - Fire Protection	050-00261/2007-007
186 - Failure to take action / meet requirements	D - Emergency Planning	Q - Fire Protection	050-00261/2007-007
186 - Failure to take action / meet requirements	E - Electrical	A - Administrative	050-00261/2007-006
186 - Failure to take action / meet requirements	G - Engineering	F - Modification	050-00261/2007-006
189 - Recognition of adverse condition / questioning attitude LTA	G - Engineering	F - Modification	050-00261/2007-006
194 - Housekeeping LTA	M - Mechanical	M - Maintenance / Repair	050-00261/2007-003
Number of Items for this Docket: 7			
Percent of Total for this Docket: 64			
Total Items for this Docket: 11			
