

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 3662

National Average: 35

2x National Average: 70

National Median: 21

Average for Selected Dockets: 35

Facility Name: Hatch 1 Docket (050- 00321)

| Details | Department | Work Type | Docket/Report |
|--|-------------------|--------------------------|--------------------|
| Communication / IR | | | |
| 160 - No communication / information not communicated | M - Mechanical | M - Maintenance / Repair | 050-00321/2008-008 |
| 160 - No communication / information not communicated | M - Mechanical | M - Maintenance / Repair | 050-00321/2008-008 |
| Number of Items for this Docket: 2 | | | |
| Percent of Total for this Docket: 8 | | | |
| <hr/> | | | |
| Human-System Interface & Environmnt / IR | | | |
| 170 - HSI or information availability / quality LTA | M - Mechanical | M - Maintenance / Repair | 050-00321/2008-004 |
| 170 - HSI or information availability / quality LTA | M - Mechanical | M - Maintenance / Repair | 050-00321/2008-008 |
| Number of Items for this Docket: 2 | | | |
| Percent of Total for this Docket: 8 | | | |
| <hr/> | | | |
| Oversight / IR | | | |
| 131 - Management expectations or directions LTA | O - Operations | O - Control Room Ops | 050-00321/2007-005 |
| Number of Items for this Docket: 1 | | | |
| Percent of Total for this Docket: 4 | | | |
| <hr/> | | | |
| Procedures & Reference Document / IR | | | |
| 111 - Procedure / reference document technical content | F - Fuel Handling | R - Refueling | 050-00321/2008-002 |
| 113 - Procedure / reference document development and maintenance L | F - Fuel Handling | R - Refueling | 050-00321/2008-002 |
| 113 - Procedure / reference document development and maintenance L | M - Mechanical | M - Maintenance / Repair | 050-00321/2008-008 |
| Number of Items for this Docket: 3 | | | |
| Percent of Total for this Docket: 12 | | | |
| <hr/> | | | |
| Problem Identification & Resolution / IR | | | |
| 140 - Problem not completely or accurately identified | M - Mechanical | M - Maintenance / Repair | 050-00321/2008-008 |
| 142 - Operating experience (OE) review LTA | M - Mechanical | M - Maintenance / Repair | 050-00321/2008-008 |
| 145 - Causal development LTA | M - Mechanical | M - Maintenance / Repair | 050-00321/2008-008 |
| 146 - Evaluation LTA | M - Mechanical | M - Maintenance / Repair | 050-00321/2008-008 |
| 148 - Action not yet started or untimely | M - Mechanical | M - Maintenance / Repair | 050-00321/2008-008 |
| Number of Items for this Docket: 5 | | | |
| Percent of Total for this Docket: 20 | | | |
| <hr/> | | | |
| Work Planning & Practices / IR | | | |
| 183 - Pre-job activities LTA | M - Mechanical | M - Maintenance / Repair | 050-00321/2008-002 |
| 185 - Procedural adherence LTA | M - Mechanical | F - Modification | 050-00321/2008-002 |
| 185 - Procedural adherence LTA | O - Operations | O - Control Room Ops | 050-00321/2007-005 |
| 186 - Failure to take action / meet requirements | M - Mechanical | F - Modification | 050-00321/2008-003 |

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 3662

National Average: 35

2x National Average: 70

National Median: 21

Average for Selected Dockets: 35

Facility Name: Hatch 1 Docket (050- 00321)

Details**Work Planning & Practices / IR**

| | Department | Work Type | Docket/Report |
|---|-------------------|--------------------------|----------------------|
| 186 - Failure to take action / meet requirements | M - Mechanical | M - Maintenance / Repair | 050-00321/2008-002 |
| 187 - Action implementation LTA | G - Engineering | G - Design | 050-00321/2008-002 |
| 187 - Action implementation LTA | G - Engineering | G - Design | 050-00321/2008-002 |
| 187 - Action implementation LTA | G - Engineering | G - Design | 050-00321/2008-004 |
| 187 - Action implementation LTA | G - Engineering | G - Design | 050-00321/2008-008 |
| 189 - Recognition of adverse condition / questioning attitude LTA | M - Mechanical | M - Maintenance / Repair | 050-00321/2008-002 |
| 189 - Recognition of adverse condition / questioning attitude LTA | M - Mechanical | M - Maintenance / Repair | 050-00321/2008-008 |
| 194 - Housekeeping LTA | M - Mechanical | M - Maintenance / Repair | 050-00321/2008-004 |

Number of Items for this Docket: 12**Percent of Total for this Docket:** 48

Total Items for this Docket: 25
