

**U.S. Nuclear Regulatory Commission  
Human Factors Information System (HFIS)  
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 3662  
National Average: 35  
2x National Average: 70  
National Median: 21  
Average for Selected Dockets: 35

**Facility Name: North Anna 2 Docket (050- 00339)**

Details	Department	Work Type	Docket/Report
<b>Communication / IR</b>			
160 - No communication / information not communicated	O - Operations	O - Control Room Ops	050-00339/2008-004
<b>Number of Items for this Docket: 1</b> <b>Percent of Total for this Docket: 7</b>			
<b>Fitness for Duty / IR</b>			
123 - Self-declaration LTA	O - Operations	O - Control Room Ops	050-00339/2008-002
128 - Non-compliance	O - Operations	O - Control Room Ops	050-00339/2008-004
<b>Number of Items for this Docket: 2</b> <b>Percent of Total for this Docket: 14</b>			
<b>Human-System Interface &amp; Environmnt / IR</b>			
170 - HSI or information availability / quality LTA	M - Mechanical	M - Maintenance / Repair	050-00339/2008-002
<b>Number of Items for this Docket: 1</b> <b>Percent of Total for this Docket: 7</b>			
<b>Procedures &amp; Reference Document / IR</b>			
111 - Procedure / reference document technical content	D - Emergency Planning	Q - Fire Protection	050-00339/2008-002
111 - Procedure / reference document technical content	E - Electrical	M - Maintenance / Repair	050-00339/2008-002
111 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00339/2008-002
<b>Number of Items for this Docket: 3</b> <b>Percent of Total for this Docket: 21</b>			
<b>Work Planning &amp; Practices / IR</b>			
182 - Work package quality LTA	M - Mechanical	M - Maintenance / Repair	050-00339/2008-002
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00339/2008-002
186 - Failure to take action / meet requirements	D - Emergency Planning	Q - Fire Protection	050-00339/2008-002
186 - Failure to take action / meet requirements	O - Operations	O - Control Room Ops	050-00339/2008-004
187 - Action implementation LTA	G - Engineering	G - Design	050-00339/2008-002
187 - Action implementation LTA	M - Mechanical	M - Maintenance / Repair	050-00339/2008-002
189 - Recognition of adverse condition / questioning attitude LTA	M - Mechanical	M - Maintenance / Repair	050-00339/2008-002
<b>Number of Items for this Docket: 7</b> <b>Percent of Total for this Docket: 50</b>			

**Total Items for this Docket: 14**