

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 3662

National Average: 35

2x National Average: 70

National Median: 21

Average for Selected Dockets: 35

Facility Name: Oyster Creek Docket (050- 00219)

Details	Department	Work Type	Docket/Report
Human-System Interface & Environmnt / IR			
170 - HSI or information availability / quality LTA	M - Mechanical	M - Maintenance / Repair	050-00219/2008-002
170 - HSI or information availability / quality LTA	M - Mechanical	M - Maintenance / Repair	050-00219/2008-004
170 - HSI or information availability / quality LTA	O - Operations	O - Control Room Ops	050-00219/2007-005
Number of Items for this Docket: 3			
Percent of Total for this Docket: 6			
<hr/>			
Procedures & Reference Document / IR			
111 - Procedure / reference document technical content	I - Instrumentation & Control	T - Testing	050-00219/2008-003
111 - Procedure / reference document technical content	O - Operations	O - Control Room Ops	050-00219/2007-005
113 - Procedure / reference document development and maintenance L	E - Electrical	Q - Fire Protection	050-00219/2008-008
Number of Items for this Docket: 3			
Percent of Total for this Docket: 6			
<hr/>			
Problem Identification & Resolution / IR			
140 - Problem not completely or accurately identified	C - Chemistry	Z - Other / Unknown	050-00219/2008-004
140 - Problem not completely or accurately identified	M - Mechanical	M - Maintenance / Repair	050-00219/2007-005
140 - Problem not completely or accurately identified	O - Operations	O - Control Room Ops	050-00219/2008-003
142 - Operating experience (OE) review LTA	M - Mechanical	M - Maintenance / Repair	050-00219/2007-005
143 - Tracking / trending LTA	C - Chemistry	M - Maintenance / Repair	050-00219/2007-005
146 - Evaluation LTA	E - Electrical	Q - Fire Protection	050-00219/2008-008
146 - Evaluation LTA	O - Operations	O - Control Room Ops	050-00219/2007-005
146 - Evaluation LTA	S - Specialized task force	W - Assessment	050-00219/2007-005
147 - Individual corrective action LTA	M - Mechanical	M - Maintenance / Repair	050-00219/2007-005
147 - Individual corrective action LTA	M - Mechanical	M - Maintenance / Repair	050-00219/2007-005
Number of Items for this Docket: 10			
Percent of Total for this Docket: 21			
<hr/>			
Training / IR			
100 - Training LTA	I - Instrumentation & Control	T - Testing	050-00219/2008-003
100 - Training LTA	M - Mechanical	M - Maintenance / Repair	050-00219/2008-003
100 - Training LTA	O - Operations	O - Control Room Ops	050-00219/2008-003
101 - Training process problem	O - Operations	O - Control Room Ops	050-00219/2007-005
Number of Items for this Docket: 4			
Percent of Total for this Docket: 9			

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 3662

National Average: 35

2x National Average: 70

National Median: 21

Average for Selected Dockets: 35

Facility Name: Oyster Creek Docket (050- 00219)

Details	Department	Work Type	Docket/Report
Work Planning & Practices / IR			
180 - Scheduling and planning LTA	E - Electrical	Q - Fire Protection	050-00219/2008-008
181 - Inadequate staffing / task allocation	D - Emergency Planning	D - Emergency Drill	050-00219/2008-002
181 - Inadequate staffing / task allocation	E - Electrical	Q - Fire Protection	050-00219/2008-008
181 - Inadequate staffing / task allocation	H - Health Physics	H - Health Physics	050-00219/2008-002
181 - Inadequate staffing / task allocation	O - Operations	O - Control Room Ops	050-00219/2008-002
181 - Inadequate staffing / task allocation	O - Operations	O - Control Room Ops	050-00219/2008-002
181 - Inadequate staffing / task allocation	O - Operations	O - Control Room Ops	050-00219/2008-002
181 - Inadequate staffing / task allocation	O - Operations	O - Control Room Ops	050-00219/2008-002
181 - Inadequate staffing / task allocation	O - Operations	O - Control Room Ops	050-00219/2008-002
183 - Pre-job activities LTA	M - Mechanical	M - Maintenance / Repair	050-00219/2008-002
183 - Pre-job activities LTA	M - Mechanical	S - Surveillance	050-00219/2008-003
185 - Procedural adherence LTA	I - Instrumentation & Control	T - Testing	050-00219/2008-003
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00219/2007-005
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00219/2008-002
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00219/2008-003
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00219/2008-004
185 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00219/2007-005
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00219/2008-002
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00219/2008-002
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00219/2008-003
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00219/2008-004
186 - Failure to take action / meet requirements	M - Mechanical	T - Testing	050-00219/2008-004
187 - Action implementation LTA	E - Electrical	Q - Fire Protection	050-00219/2008-008
187 - Action implementation LTA	G - Engineering	G - Design	050-00219/2007-005
187 - Action implementation LTA	G - Engineering	G - Design	050-00219/2008-004
188 - Work practice or craft skill LTA	M - Mechanical	M - Maintenance / Repair	050-00219/2008-003
189 - Recognition of adverse condition / questioning attitude LTA	O - Operations	O - Control Room Ops	050-00219/2008-003
191 - Team interactions LTA	M - Mechanical	S - Surveillance	050-00219/2008-003

Number of Items for this Docket: 27

Percent of Total for this Docket: 57

Total Items for this Docket: 47
