

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 3662
National Average: 35
2x National Average: 70
National Median: 21
Average for Selected Dockets: 35

Facility Name: Robinson 2 Docket (050- 00261)

Details	Department	Work Type	Docket/Report
Communication / IR			
160 - No communication / information not communicated	M - Mechanical	O - Control Room Ops	050-00261/2008-002
160 - No communication / information not communicated	O - Operations	O - Control Room Ops	050-00261/2008-002
Number of Items for this Docket: 2			
Percent of Total for this Docket: 11			
<hr/>			
Human-System Interface & Environmnt / IR			
170 - HSI or information availability / quality LTA	M - Mechanical	T - Testing	050-00261/2007-005
Number of Items for this Docket: 1			
Percent of Total for this Docket: 6			
<hr/>			
Procedures & Reference Document / IR			
111 - Procedure / reference document technical content	M - Mechanical	T - Testing	050-00261/2007-005
Number of Items for this Docket: 1			
Percent of Total for this Docket: 6			
<hr/>			
Problem Identification & Resolution / IR			
140 - Problem not completely or accurately identified	M - Mechanical	T - Testing	050-00261/2007-005
141 - Problem not properly classified or prioritized	O - Operations	O - Control Room Ops	050-00261/2008-002
145 - Causal development LTA	M - Mechanical	M - Maintenance / Repair	050-00261/2008-002
146 - Evaluation LTA	M - Mechanical	M - Maintenance / Repair	050-00261/2007-005
146 - Evaluation LTA	M - Mechanical	M - Maintenance / Repair	050-00261/2008-002
146 - Evaluation LTA	O - Operations	O - Control Room Ops	050-00261/2008-002
147 - Individual corrective action LTA	M - Mechanical	T - Testing	050-00261/2007-005
149 - No action planned	M - Mechanical	M - Maintenance / Repair	050-00261/2008-002
Number of Items for this Docket: 8			
Percent of Total for this Docket: 44			
<hr/>			
Work Planning & Practices / IR			
183 - Pre-job activities LTA	O - Operations	O - Control Room Ops	050-00261/2008-002
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00261/2008-002
186 - Failure to take action / meet requirements	M - Mechanical	T - Testing	050-00261/2007-005
194 - Housekeeping LTA	M - Mechanical	M - Maintenance / Repair	050-00261/2007-005
Number of Items for this Docket: 4			
Percent of Total for this Docket: 22			

U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report

Total Number of Hits: 3662
National Average: 35
2x National Average: 70
National Median: 21
Average for Selected Dockets: 35

Facility Name: Robinson 2 Docket (050- 00261)

Details	Department	Work Type	Docket/Report
Procedures & Reference Document / LER			
111 - Procedure / reference document technical content	D - Emergency Planning	D - Emergency Drill	050-00261/2008-001-00
Number of Items for this Docket: 1			
Percent of Total for this Docket: 6			
Work Planning & Practices / LER			
187 - Action implementation LTA	H - Health Physics	H - Health Physics	050-00261/2008-001-00
Number of Items for this Docket: 1			
Percent of Total for this Docket: 6			
Total Items for this Docket: 18			
