0/24/2014 17:53:06 Page 1 of 1 Document Types: IR, LER From 01/01/2009 to 12/31/2009	Human Factors Information System (HFIS) IR/LER Category Analysis by Docket Report		Total Number of Hits:7National Average:462x National Average:92National Median:23for Selected Dockets:7	
	Facility Name: Millstone 3 Docket (050- 00423)			
Details	Department	Work Type	Docket/Report	
Problem Identification & Resolution / IR				
146 - Evaluation LTA	D - Emergency Planning	Q - Fire Protection	050-00423/2009-004	
148 - Action not yet started or untimelyNumber of Items for this Docket:2Percent of Total for this Docket:29	E - Electrical	M - Maintenance / Repair	050-00423/2009-004	
Work Planning & Practices / IR				
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00423/2008-010	
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00423/2008-010	
186 - Failure to take action / meet requirements	D - Emergency Planning	D - Emergency Drill	050-00423/2009-004	
186 - Failure to take action / meet requirements	O - Operations	O - Control Room Ops	050-00423/2009-004	
<ul> <li>186 - Failure to take action / meet requirements</li> <li>Number of Items for this Docket: 5</li> <li>Percent of Total for this Docket: 71</li> </ul>	O - Operations	O - Control Room Ops	050-00423/2009-004	