

**U.S. Nuclear Regulatory Commission  
Human Factors Information System (HFIS)  
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 18

National Average: 30

2x National Average: 60

National Median: 18

Average for Selected Dockets: 18

---

**Facility Name: Hatch 2 Docket (050- 00366)**

<b>Details</b>	<b>Department</b>	<b>Work Type</b>	<b>Docket/Report</b>
<b>Human-System Interface &amp; Environmnt / IR</b>			
170 - HSI or information availability / quality LTA	E - Electrical	M - Maintenance / Repair	050-00366/2009-005
170 - HSI or information availability / quality LTA	S - Specialized task force	W - Assessment	050-00366/2010-006
<b>Number of Items for this Docket: 2</b>			
<b>Percent of Total for this Docket: 11</b>			
<b>Procedures &amp; Reference Document / IR</b>			
111 - Procedure / reference document technical content	P - Procedure Writers	P - Procedure Dev	050-00366/2009-005
113 - Procedure / reference document development and maintenance L	E - Electrical	M - Maintenance / Repair	050-00366/2009-005
113 - Procedure / reference document development and maintenance L	M - Mechanical	M - Maintenance / Repair	050-00366/2009-005
<b>Number of Items for this Docket: 3</b>			
<b>Percent of Total for this Docket: 17</b>			
<b>Problem Identification &amp; Resolution / IR</b>			
140 - Problem not completely or accurately identified	S - Specialized task force	W - Assessment	050-00366/2009-005
142 - Operating experience (OE) review LTA	E - Electrical	M - Maintenance / Repair	050-00366/2009-005
142 - Operating experience (OE) review LTA	M - Mechanical	M - Maintenance / Repair	050-00366/2009-005
145 - Causal development LTA	S - Specialized task force	W - Assessment	050-00366/2010-006
146 - Evaluation LTA	S - Specialized task force	W - Assessment	050-00366/2010-006
146 - Evaluation LTA	S - Specialized task force	W - Assessment	050-00366/2009-005
150 - Programmatic deficiency	M - Mechanical	M - Maintenance / Repair	050-00366/2009-005
<b>Number of Items for this Docket: 7</b>			
<b>Percent of Total for this Docket: 39</b>			
<b>Work Planning &amp; Practices / IR</b>			
186 - Failure to take action / meet requirements	E - Electrical	M - Maintenance / Repair	050-00366/2009-005
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00366/2009-005
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00366/2009-005
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00366/2009-005
187 - Action implementation LTA	S - Specialized task force	W - Assessment	050-00366/2010-006
<b>Number of Items for this Docket: 5</b>			
<b>Percent of Total for this Docket: 28</b>			

---

**U.S. Nuclear Regulatory Commission  
Human Factors Information System (HFIS)  
IR/LER Category Analysis by Docket Report**

**Total Number of Hits: 18**  
**National Average: 30**  
**2x National Average: 60**  
**National Median: 18**  
**Average for Selected Dockets: 18**

---

**Facility Name: Hatch 2 Docket (050- 00366)**

**Details**

**Work Planning & Practices / LER**

186 - Failure to take action / meet requirements

**Department**

O - Operations

**Work Type**

O - Control Room Ops

**Docket/Report**

050-00366/2010-001-00

**Number of Items for this Docket: 1**

**Percent of Total for this Docket: 6**

---

**Total Items for this Docket: 18**

---