

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 33

National Average: 30

2x National Average: 60

National Median: 18

Average for Selected Dockets: 33

Facility Name: Peach Bottom 2 Docket (050- 00277)

Details	Department	Work Type	Docket/Report
Communication / IR			
160 - No communication / information not communicated	F - Fuel Handling	R - Refueling	050-00277/2009-005
160 - No communication / information not communicated	A - Administrative Support	A - Administrative	050-00277/2009-005
Number of Items for this Docket: 2			
Percent of Total for this Docket: 6			
<hr/>			
Human-System Interface & Environmnt / IR			
170 - HSI or information availability / quality LTA	O - Operations	T - Testing	050-00277/2010-002
170 - HSI or information availability / quality LTA	M - Mechanical	M - Maintenance / Repair	050-00277/2010-002
Number of Items for this Docket: 2			
Percent of Total for this Docket: 6			
<hr/>			
Procedures & Reference Document / IR			
113 - Procedure / reference document development and maintenance L	G - Engineering	M - Maintenance / Repair	050-00277/2010-002
113 - Procedure / reference document development and maintenance L	P - Procedure Writers	P - Procedure Dev	050-00277/2010-002
Number of Items for this Docket: 2			
Percent of Total for this Docket: 6			
<hr/>			
Problem Identification & Resolution / IR			
142 - Operating experience (OE) review LTA	O - Operations	T - Testing	050-00277/2010-002
142 - Operating experience (OE) review LTA	E - Electrical	M - Maintenance / Repair	050-00277/2009-005
146 - Evaluation LTA	E - Electrical	M - Maintenance / Repair	050-00277/2009-005
146 - Evaluation LTA	G - Engineering	G - Design	050-00277/2010-002
148 - Action not yet started or untimely	E - Electrical	M - Maintenance / Repair	050-00277/2009-005
150 - Programmatic deficiency	O - Operations	T - Testing	050-00277/2010-002
Number of Items for this Docket: 6			
Percent of Total for this Docket: 18			
<hr/>			
Work Planning & Practices / IR			
182 - Work package quality LTA	E - Electrical	M - Maintenance / Repair	050-00277/2009-005
185 - Procedural adherence LTA	M - Mechanical	Q - Fire Protection	050-00277/2010-003
185 - Procedural adherence LTA	E - Electrical	M - Maintenance / Repair	050-00277/2009-005
185 - Procedural adherence LTA	E - Electrical	M - Maintenance / Repair	050-00277/2009-005
185 - Procedural adherence LTA	E - Electrical	M - Maintenance / Repair	050-00277/2009-005
185 - Procedural adherence LTA	F - Fuel Handling	R - Refueling	050-00277/2009-005
185 - Procedural adherence LTA	F - Fuel Handling	R - Refueling	050-00277/2009-005
185 - Procedural adherence LTA	F - Fuel Handling	R - Refueling	050-00277/2009-005

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 33

National Average: 30

2x National Average: 60

National Median: 18

Average for Selected Dockets: 33

Facility Name: Peach Bottom 2 Docket (050- 00277)

Details	Department	Work Type	Docket/Report
Work Planning & Practices / IR			
185 - Procedural adherence LTA	F - Fuel Handling	R - Refueling	050-00277/2009-005
185 - Procedural adherence LTA	F - Fuel Handling	R - Refueling	050-00277/2009-005
185 - Procedural adherence LTA	F - Fuel Handling	R - Refueling	050-00277/2009-005
185 - Procedural adherence LTA	F - Fuel Handling	R - Refueling	050-00277/2009-005
186 - Failure to take action / meet requirements	E - Electrical	G - Design	050-00277/2009-005
186 - Failure to take action / meet requirements	O - Operations	O - Control Room Ops	050-00277/2010-002
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00277/2010-002
187 - Action implementation LTA	E - Electrical	G - Design	050-00277/2009-005
187 - Action implementation LTA	G - Engineering	G - Design	050-00277/2010-002
187 - Action implementation LTA	E - Electrical	G - Design	050-00277/2009-005
189 - Recognition of adverse condition / questioning attitude LTA	O - Operations	O - Control Room Ops	050-00277/2010-002
190 - Failure to stop work / non-conservative decision making	O - Operations	O - Control Room Ops	050-00277/2010-002
197 - Self-check LTA	F - Fuel Handling	R - Refueling	050-00277/2009-005

Number of Items for this Docket: 21

Percent of Total for this Docket: 64

Total Items for this Docket: 33
