

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 29
National Average: 30
2x National Average: 60
National Median: 18
Average for Selected Dockets: 29

Facility Name: Robinson 2 Docket (050- 00261)

Details	Department	Work Type	Docket/Report
Procedures & Reference Document / IR			
113 - Procedure / reference document development and maintenance L	P - Procedure Writers	P - Procedure Dev	050-00261/2010-002
Number of Items for this Docket: 1			
Percent of Total for this Docket: 3			
Problem Identification & Resolution / IR			
140 - Problem not completely or accurately identified	M - Mechanical	M - Maintenance / Repair	050-00261/2009-005
146 - Evaluation LTA	M - Mechanical	M - Maintenance / Repair	050-00261/2010-002
Number of Items for this Docket: 2			
Percent of Total for this Docket: 7			
Work Planning & Practices / IR			
182 - Work package quality LTA	E - Electrical	M - Maintenance / Repair	050-00261/2010-005
182 - Work package quality LTA	M - Mechanical	M - Maintenance / Repair	050-00261/2009-005
183 - Pre-job activities LTA	M - Mechanical	M - Maintenance / Repair	050-00261/2009-005
184 - Tag outs LTA	M - Mechanical	M - Maintenance / Repair	050-00261/2009-005
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00261/2010-002
187 - Action implementation LTA	G - Engineering	G - Design	050-00261/2009-005
187 - Action implementation LTA	G - Engineering	G - Design	050-00261/2010-002
187 - Action implementation LTA	G - Engineering	G - Design	050-00261/2010-002
189 - Recognition of adverse condition / questioning attitude LTA	M - Mechanical	M - Maintenance / Repair	050-00261/2009-005
189 - Recognition of adverse condition / questioning attitude LTA	G - Engineering	G - Design	050-00261/2010-002
190 - Failure to stop work / non-conservative decision making	G - Engineering	G - Design	050-00261/2010-002
Number of Items for this Docket: 11			
Percent of Total for this Docket: 38			
Oversight / LER			
130 - Inadequate supervision / command and control	W - Work Control / Scheduling Outage Pla	A - Administrative	050-00261/2010-004-00
Number of Items for this Docket: 1			
Percent of Total for this Docket: 3			
Procedures & Reference Document / LER			
111 - Procedure / reference document technical content	W - Work Control / Scheduling Outage Pla	A - Administrative	050-00261/2010-004-00
111 - Procedure / reference document technical content	I - Instrumentation & Control	T - Testing	050-00261/2010-002-00
Number of Items for this Docket: 2			
Percent of Total for this Docket: 7			

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 29

National Average: 30

2x National Average: 60

National Median: 18

Average for Selected Dockets: 29

Facility Name: Robinson 2 Docket (050- 00261)

Details	Department	Work Type	Docket/Report
Problem Identification & Resolution / LER			
140 - Problem not completely or accurately identified	S - Specialized task force	W - Assessment	050-00261/2010-002-00
141 - Problem not properly classified or prioritized	S - Specialized task force	W - Assessment	050-00261/2010-002-00
147 - Individual corrective action LTA	E - Electrical	M - Maintenance / Repair	050-00261/2010-002-00
148 - Action not yet started or untimely	E - Electrical	M - Maintenance / Repair	050-00261/2010-005-01
Number of Items for this Docket: 4			
Percent of Total for this Docket: 14			
<hr/>			
Training / LER			
100 - Training LTA	O - Operations	O - Control Room Ops	050-00261/2010-004-00
Number of Items for this Docket: 1			
Percent of Total for this Docket: 3			
<hr/>			
Work Planning & Practices / LER			
180 - Scheduling and planning LTA	E - Electrical	M - Maintenance / Repair	050-00261/2010-002-00
182 - Work package quality LTA	E - Electrical	M - Maintenance / Repair	050-00261/2010-005-01
182 - Work package quality LTA	I - Instrumentation & Control	F - Modification	050-00261/2010-002-00
186 - Failure to take action / meet requirements	O - Operations	O - Control Room Ops	050-00261/2010-002-00
189 - Recognition of adverse condition / questioning attitude LTA	O - Operations	O - Control Room Ops	050-00261/2010-002-00
190 - Failure to stop work / non-conservative decision making	O - Operations	O - Control Room Ops	050-00261/2010-002-00
198 - Worker distracted / interrupted	O - Operations	O - Control Room Ops	050-00261/2010-002-00
Number of Items for this Docket: 7			
Percent of Total for this Docket: 24			
<hr/>			
Total Items for this Docket: 29			
