A) Subtle anticline (shown by yellow dashed line) exposed in banks of Saline River. Deweyville terrace surface approximately 20 feet above the river is in the background. Photograph provided by Randy Cox



B) Close up view of Holocene sediments involved in folding. Photograph provided by Randy Cox.

Note: Site described in Cox et al. (2002).

SERI
GRAND GULF NUCLEAR STATION SITE
EARLY SITE PERMIT APPLICATION
SITE SAFETY ANALYSIS REPORT

SALINE RIVER CUT BANK EXPOSURE
ALONG THE SALINE RIVER LINEAMENT

FIGURE 2.5-25 REV. 0