Figure 2.5-115—{Plasticity Chart}



© 2007 UniStar Nuclear Development, LLC. All rights reserved.
COPYRIGHT PROTECTED

Figure 2.5-116—{Friction Angle Interpretation from CPT Results}



© 2007 UniStar Nuclear Development, LLC. All rights reserved.
COPYRIGHT PROTECTED

Figure 2.5-117—{Preconsolidation Pressure from Laboratory Testing}



© 2007 UniStar Nuclear Development, LLC. All rights reserved.
COPYRIGHT PROTECTED

Figure 2.5-118—{OCR Interpretation from CPT Results}



© 2007 UniStar Nuclear Development, LLC. All rights reserved.
COPYRIGHT PROTECTED

Figure 2.5-119—{Undrained Shear Strength from Laboratory Tests}



© 2007 UniStar Nuclear Development, LLC. All rights reserved.
COPYRIGHT PROTECTED

Figure 2.5-120—{Undrained Shear Strength Interpreted from CPT Data}



© 2007 UniStar Nuclear Development, LLC. All rights reserved.
COPYRIGHT PROTECTED

Figure 2.5-121—{Uphole Seismic Survey Results from UFSAR}



© 2007 UniStar Nuclear Development, LLC. All rights reserved.
COPYRIGHT PROTECTED

Figure 2.5-122—{Geophysical Model of the Site for Units 1 and 2 from UFSAR}



* TAKEN FROM EWING M. AND WORZEL L. (1948) EXPLOSION SOUNDS IN SHALLOW WATER, GEOLOGICAL SOCIETY OF AMERICA MEMOIR 27

© 2007 UniStar Nuclear Development, LLC. All rights reserved.
COPYRIGHT PROTECTED