

(References 305 and 310)

FIGURE 2.5-223
Schematic Figure Showing Seismotectonic Elements in the Epicentral Region of the 1886 Earthquake