

Source: Wooten et al. (2001)



Source: Wooten et al. (2001)



Schematic diagram showing a possible kinematic model for the south borrow pit fault and associate structures.

Source: Wooten et al. (1996)

Progress Energy Carolinas

Shearon Harris Nuclear Power Plant
Units 2 and 3
Part 2, Final Safety Analysis Report

New Hill, North Carolina

Schematic Block Diagram and Map Showing Structural Relations for Faults in the Site Area

FIGURE 2.5.1-236 Rev. 1