CPT Data

Job Number	04.1908-0029	CPT Number	C-701	Location	Turkey Point COL-FL
Operator	ALBERT FONSECA	Date and Tin	18-May-2008 08:19:36	Cone Number	F7.5CKE3SW2/0750
Client	MACTEC	Elevation	ND	Water Table	ND
Coord. North	ND	Coord. East	ND	Check:	06/24/08
				Verify:	6/29/08



Robertson et al. 1986 * Overconsolidated or Cemented

CPT Data

Job Number	04.1908-0029	CPT Number	C-701	Location	Turkey Point COL-FL
Operator	ALBERT FONSECA	Date and Tin	18-May-2008 08:19:36	Cone Number	F7.5CKE3SW2/0750
Client	MACTEC	Elevation	ND	Water Table	ND
Coord. North	ND	Coord. East	ND	Check: SG 06/24/08 Verify: DB 6/25/08	

CPT DATA



1 - sensitive fine grained
2 - organic material
3 - clay
4 - silty clay to clay
5 - clayey silt to silty clay
6 - sandy silt to clayey silt
7 - silty sand to sandy silt
8 - sand to silty sand
9 - sand
10 - gravelly sand to sand
11 - very stiff fine grained (*)
12 - sand to clayey sand (*)

Robertson, 1986 * Overconsolidated or Cemented

CPT Data

Job Number	04.1908-0029	CPT Number	C-702	Location	Turkey Point COL-FL
Operator	ALBERT FONSECA	Date and Tin	14-May-2008 08:59:01	Cone Number	F7.5CKE3SW2/0750
Client	MACTEC	Elevation	0.3	Water Table	-2.0 ft
Coord. North	397149.4	Coord. East	876042.2	Check: SG 05/19/08 Verify: TS 5/19/08	



CPT Data

Job Number	04.1908-0029	CPT Number	C-702	Location	Turkey Point COL-FL
Operator	ALBERT FONSECA	Date and Tin	14-May-2008 08:59:01	Cone Number	F7.5CKE3SW2/0750
Client	MACTEC	Elevation	0.3	Water Table	-2.0 ft
Coord. North	397149.4	Coord. East	876042.2	Check: SG 05/19/08	Verify: TB 5/19/08



Robertson et al. 1986 * Overconsolidated or Cemented

CPT Data

Job Number	04.1908-0029	CPT Number	C-702	Location	Turkey Point COL-FL
Operator	ALBERT FONSECA	Date and Tin	14-May-2008 08:59:01	Cone Number	F7.5CKE3SW2/0750
Client	MACTEC	Elevation	0.3	Water Table	-2.0 ft
Coord. North	397149.4	Coord. East	876042.2	Check: SG 05/19/08 Verify: [illegible] 5/19/08	



Robertson et al. 1986 * Overconsolidated or Cemented